



Aviation Investigation Notification

Location:	Marietta, TX	Accident Number:	CEN21LA077
Date & Time:	December 5, 2020, 13:30 Local	Registration:	N371MP
Aircraft:	ROBINSON HELICOPTER COMPANY R44 II	Injuries:	5 None
Flight Conducted Under:	Part 91: General aviation - Personal		

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	ROBINSON HELICOPTER COMPANY	Registration:	N371MP
Model/Series:	R44 II II	Aircraft Category:	Helicopter
Amateur Built:			
Operator:	Private Individual	Operating Certificate(s) Held:	None
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	KOSA, 363 ft msl	Observation Time:	13:30 Local
Distance from Accident Site:		Temperature/Dew Point:	18°C / 0°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	4 knots / , 240°
Lowest Ceiling:		Visibility:	
Altimeter Setting:	30.17 inches Hg	Type of Flight Plan Filed:	None
Departure Point:	Marietta, TX	Destination:	Texarkana, TX

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	4 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	5 None	Latitude, Longitude:	33.194025,-94.526083 (est)

Administrative Information

Investigator In Charge (IIC):	Aguilera, Jason
Additional Participating Persons:	Daniel Montie; FAA FSDO; Irving, TX
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.