













# **Aviation Investigation Preliminary Report**

**Location:** Spanish Fork, UT **Accident Number:** WPR21LA086

Date & Time:January 13, 2021, 13:50 LocalRegistration:N7480FAircraft:Hughes 269CInjuries:2 None

Flight Conducted Under: Part 91: General aviation - Instructional

### **Aircraft and Owner/Operator Information**

Aircraft Make: Hughes Registration: N7480F

Model/Series: 269C Aircraft Category: Helicopter

**Amateur Built:** 

Operator: TRIKE INDUSTRIES LLC Operating Certificate(s) None

Held:

**Operator Designator Code:** 

### **Meteorological Information and Flight Plan**

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	KPVU,4497 ft msl	Observation Time:	13:56 Local
Distance from Accident Site:	6 Nautical Miles	Temperature/Dew Point:	4°C /-6°C
<b>Lowest Cloud Condition:</b>		Wind Speed/Gusts, Direction:	5 knots / None, 300°
Lowest Ceiling:		Visibility:	10 miles
Altimeter Setting:	30.28 inches Hg	Type of Flight Plan Filed:	NONE
Departure Point:	Spanish Fork, UT (SPK)	Destination:	Spanish Fork, UT (SPK)

### **Wreckage and Impact Information**

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	40.130849,-111.6879

## **Administrative Information**

Investigator In Charge (IIC):	Stein, Stephen
Additional Participating Persons:	David Horton; Schweizer Aircraft; Fort Worth, TX Troy Helgeson; Lycoming Engines; Williamsport, PA
Investigation Class:	Class 3
Note:	The NTSB did not travel to the scene of this accident.

Page 2 of 2 WPR21LA086