













Helicopter

Aviation Investigation Preliminary Report

Location: Johnson, KS Accident Number: CEN21LA184

Date & Time:April 5, 2021, 17:00 LocalRegistration:N8348XAircraft:ROBINSON HELICOPTER R44Injuries:2 None

Flight Conducted Under: Part 91: General aviation - Personal

Aircraft and Owner/Operator Information

Aircraft Make: ROBINSON HELICOPTER Registration: N8348X

Model/Series: R44

Amateur Built:

Operator: SEGER ROBERT E Operating Certificate(s) None

Held:

Aircraft Category:

Operator Designator Code:

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	KSPD,4383 ft msl	Observation Time:	16:56 Local
Distance from Accident Site:	38 Nautical Miles	Temperature/Dew Point:	29°C /-7°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	9 knots / , 170°
Lowest Ceiling:		Visibility:	
Altimeter Setting:	29.64 inches Hg	Type of Flight Plan Filed:	None
Departure Point:	Johnson, KS	Destination:	Johnson, KS

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	37.667167,-101.988 (est)

Administrative Information

Investigator In Charge (IIC):	Lindberg, Joshua
Additional Participating Persons:	Michael LeBlanc; Federal Aviation Administration; Wichita, KS
Investigation Class:	Class 3
Note:	The NTSB did not travel to the scene of this accident.

Page 2 of 2 CEN21LA184