



Aviation Investigation Notification

Location:	New Roads, LA	Accident Number:	CEN21LA385
Date & Time:	August 20, 2021, 03:40 Local	Registration:	N744RB
Aircraft:	ROBINSON HELICOPTER COMPANY R44 II	Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	ROBINSON HELICOPTER COMPANY	Registration:	N744RB
Model/Series:	R44 II	Aircraft Category:	Helicopter
Amateur Built:			
Operator:	On file	Operating Certificate(s) Held:	None
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Night
Observation Facility, Elevation:	KHZR,40 ft msl	Observation Time:	04:15 Local
Distance from Accident Site:	6 Nautical Miles	Temperature/Dew Point:	24°C /24°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	
Lowest Ceiling:	None	Visibility:	10 miles
Altimeter Setting:	29.97 inches Hg	Type of Flight Plan Filed:	NONE
Departure Point:	Lafayette, LA (KLFT)	Destination:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Destroyed
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	30.72554,-91.353989 (est)

Administrative Information

Investigator In Charge (IIC):	Williams, David
Additional Participating Persons:	Michael Wilson; Federal Aviation Administration; Baton rouge, LA
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.