



Aviation Investigation Preliminary Report

Location:	Miami, FL	Accident Number:	ERA21LA387
Date & Time:	September 28, 2021, 19:00 Local	Registration:	N212HT
Aircraft:	ROBINSON HELICOPTER COMPANY R44 II	Injuries:	1 Minor, 3 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Aircraft and Owner/Operator Information

Aircraft Make:	ROBINSON HELICOPTER COMPANY	Registration:	N212HT
Model/Series:	R44 II	Aircraft Category:	Helicopter
Amateur Built:			
Operator:	Iftach Shimonovich	Operating Certificate(s) Held:	On-demand air taxi (135)

Operator Designator Code:

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	TMB,6 ft msl	Observation Time:	19:53 Local
Distance from Accident Site:	0 Nautical Miles	Temperature/Dew Point:	0°C /0°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	7 knots / None, 90°
Lowest Ceiling:	None	Visibility:	10 miles
Altimeter Setting:	29.95 inches Hg	Type of Flight Plan Filed:	NONE
Departure Point:	Miami, FL	Destination:	Miami, FL

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	3 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Minor, 3 None	Latitude, Longitude:	25.647564,-80.433225 (est)

Administrative Information

Investigator In Charge (IIC):	Rayner, Brian
Additional Participating Persons:	Jimmy L. Mygatt; FAA FSDO; Miramar, FL
Investigation Class:	Class 3
Note:	The NTSB did not travel to the scene of this accident.