



Aviation Investigation Notification

Location:	Delta, MO	Accident Number:	CEN22LA006
Date & Time:	October 5, 2021, 14:20 Local	Registration:	N266RK
Aircraft:	ROBINSON HELICOPTER CO R66	Injuries:	1 Minor
Flight Conducted Under:	Part 137: Agricultural		

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	ROBINSON HELICOPTER CO	Registration:	N266RK
Model/Series:	R66	Aircraft Category:	Helicopter
Amateur Built:			
Operator:	THOMPSON FLYING SERVICE LLC	Operating Certificate(s) Held:	Agricultural aircraft (137)
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	KCGI, 352 ft msl	Observation Time:	13:53 Local
Distance from Accident Site:	8 Nautical Miles	Temperature/Dew Point:	26°C / 18°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	7 knots / , 50°
Lowest Ceiling:	None	Visibility:	10 miles
Altimeter Setting:	30.06 inches Hg	Type of Flight Plan Filed:	None
Departure Point:	Delta, MO (Priv)	Destination:	Delta, MO (Priv)

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	37.206,-89.74571 (est)

Administrative Information

Investigator In Charge (IIC): Folkerts, Michael

Additional Participating Persons: William Grubb; Flight Standards District Office; St Louis, MO

Investigation Class: [Class 4](#)

Note: The NTSB did not travel to the scene of this accident.