













Aviation Investigation Notification

Location: Delta, MO Accident Number: CEN22LA006

Date & Time:October 5, 2021, 14:20 LocalRegistration:N266RK

Aircraft: ROBINSON HELICOPTER CO R66 Injuries: 1 Minor

Flight Conducted Under: Part 137: Agricultural

The NTSB is conducting a <u>Class 4 investigation</u> into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	ROBINSON HELICOPTER CO	Registration:	N266RK
Model/Series: Amateur Built:	R66	Aircraft Category:	Helicopter
7 2			
Operator:	THOMPSON FLYING SERVICE LLC	Operating Certificate(s) Held:	Agricultural aircraft (137)

Operator Designator Code:

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	KCGI,352 ft msl	Observation Time:	13:53 Local
Distance from Accident Site:	8 Nautical Miles	Temperature/Dew Point:	26°C /18°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	7 knots / None, 50°
Lowest Ceiling:	None	Visibility:	10 miles
Altimeter Setting:	30.06 inches Hg	Type of Flight Plan Filed:	NONE
Departure Point:	Delta, MO (Priv)	Destination:	Delta, MO (Priv)

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	37.206,-89.74571 (est)

Page 1 of 2 CEN22LA006

Administrative Information

Investigator In Charge (IIC):	Folkerts, Michael
Additional Participating Persons:	William Grubb; Flight Standards District Office; St Louis, MO
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.

Page 2 of 2 CEN22LA006