

## **Aviation Investigation Notification**

Location: Batavia, NY Accident Number: ERA22LA007

Date & Time: October 6, 2021, 21:16 Local Registration: N505TJ

Aircraft: BELL HELICOPTER TEXTRON CANADA 429 Injuries: 4 None

Flight Conducted Under: Part 91: General aviation - Positioning

The NTSB is conducting a <u>Class 4 investigation</u> into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

**Aircraft and Owner/Operator Information** 

Aircraft Make: BELL HELICOPTER Registration: N505TJ

**TEXTRON CANADA** 

Model/Series: 429 Aircraft Category: Helicopter

Amateur Built:

Operator: MERCY FLIGHT INC Operating Certificate(s) On-demand air taxi (135)

Held:

**Operator Designator Code:** 

## Meteorological Information and Flight Plan

| Conditions at Accident Site:     | VMC                 | Condition of Light:          | Night       |
|----------------------------------|---------------------|------------------------------|-------------|
| Observation Facility, Elevation: | GVQ,913 ft msl      | Observation Time:            | 20:54 Local |
| Distance from Accident Site:     | 0 Nautical Miles    | Temperature/Dew Point:       | 10°C /9°C   |
| <b>Lowest Cloud Condition:</b>   | Few / 1400 ft AGL   | Wind Speed/Gusts, Direction: |             |
| Lowest Ceiling:                  | None                | Visibility:                  |             |
| Altimeter Setting:               |                     | Type of Flight Plan Filed:   | CVFR        |
| Departure Point:                 | Rochester, NY (ROC) | Destination:                 | Batavia, NY |
|                                  |                     |                              |             |

## **Wreckage and Impact Information**

| Crew Injuries:      | 1 None | Aircraft Damage:     | Substantial                |
|---------------------|--------|----------------------|----------------------------|
| Passenger Injuries: | 3 None | Aircraft Fire:       | None                       |
| Ground Injuries:    |        | Aircraft Explosion:  | None                       |
| Total Injuries:     | 4 None | Latitude, Longitude: | 43.034158,-78.167864 (est) |

## **Administrative Information**

Investigator In Charge (IIC): Kemner, Heidi

Additional Participating Persons: Robert Cunningham; FAA/FSDO; Rochester, NY

Investigation Class: Class 4

Note: The NTSB did not travel to the scene of this accident.

Page 2 of 2 ERA22LA007