



Aviation Investigation Notification

Location:	Freer, TX	Accident Number:	CEN22LA033
Date & Time:	November 10, 2021, 13:30 Local	Registration:	N7198A
Aircraft:	ROBINSON HELICOPTER R22 BETA	Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Other work use		

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	ROBINSON HELICOPTER	Registration:	N7198A
Model/Series:	R22 BETA	Aircraft Category:	Helicopter
Amateur Built:			
Operator:	FLYING J SERVICES LLC	Operating Certificate(s) Held:	None
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	KNOG,257 ft msl	Observation Time:	14:00 Local
Distance from Accident Site:	30 Nautical Miles	Temperature/Dew Point:	29°C /16°C
Lowest Cloud Condition:	Scattered / 5500 ft AGL	Wind Speed/Gusts, Direction:	14 knots / 20 knots, 150°
Lowest Ceiling:	None	Visibility:	10 miles
Altimeter Setting:	29.83 inches Hg	Type of Flight Plan Filed:	NONE
Departure Point:	Freer, TX	Destination:	Freer, TX

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	27.8828,-98.6178 (est)

Administrative Information

Investigator In Charge (IIC): Link, Samantha

Additional Participating Persons: Mike Gabster; Federal Aviation Administration; Baton Rouge, LA

Investigation Class: [Class 4](#)

Note: The NTSB did not travel to the scene of this accident.