



Aviation Investigation Notification

Location:	Fort Davis, TX	Accident Number:	CEN22LA034
Date & Time:	November 10, 2021, 11:00 Local	Registration:	N3027W
Aircraft:	ROBINSON HELICOPTER COMPANY R44 II	Injuries:	1 Minor, 2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	ROBINSON HELICOPTER COMPANY	Registration:	N3027W
Model/Series:	R44 II	Aircraft Category:	Helicopter
Amateur Built:			
Operator:	Aaron Kellum	Operating Certificate(s) Held:	None
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	KMRF	Observation Time:	09:30 Local
Distance from Accident Site:	24 Nautical Miles	Temperature/Dew Point:	-6.7°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	10 knots / 15 knots, 180°
Lowest Ceiling:		Visibility:	10 miles
Altimeter Setting:		Type of Flight Plan Filed:	None
Departure Point:		Destination:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor, 1 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Minor, 2 None	Latitude, Longitude:	30.735729,-104.00638

Administrative Information

Investigator In Charge (IIC):	Williams, David
Additional Participating Persons:	Robert Thomason; FAA; San Antonio, TX
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.