

## Fire Protection Service, Inc.

www.FPS-USA.com

FPS<sub>sm</sub>-New Orleans
(504) 466-8003
FAX (504) 469-9922

**ISSUE 2 REVISION 2** 

DATE: 10/20/06

## **FPS**<sub>sm</sub>**-HOUSTON**

(713) 924-9600 FAX (713) 923-6272

## FPS sm-Corpus Christi

(361) 289-9102 FAX (361) 289-1421

APPROVED BY: RRB

## REPAIR REPORT

VESSEL/INSTALLATION: Chipa/brook M	loon	JOB#: <u>SO125278</u>
DURING THE INSPECTION OF THE ABOVE FOLLOWING ITEMS WERE FOUND NON-COM	NAME	D VESSEL/INSTALLATION THE
FPS returned 60 CO2 cylinders for seriostalled by FPS, System	11ce fre	Fill on 24 May 2018.
All cylinders reinstalled by FPS, System	13 10	specational order.
Aessel needs to remove pins from cylindu	11s befor	e sailing.
		· · · · · · · · · · · · · · · · · · ·
ALL REQUIRED SERVICES WERE DISCUSSED WIREPRESENTATIVE (PRINT)APPROVAL FOR SERVICE GIVEN YES N		CAPTAIN OR SHIP
Required signature of Ship Representative		
ALL REQUIRED SERVICES COMPLETED YES	S NO	
INSPECTOR:		
Service completed by: Fire Protection Service, Inc.	Hou	ston, Texas
New Orleans, Louisiana	Cor	pus Christi, Texas
DOC-M20 PAGE C	F	REVIEWED BY: PC