United States Coast Guard

Formal Investigation

Caribbean Fantasy Marine Casualty

Caribe Hilton

San Juan, Puerto Rico 00901

March 20, 2017 -- March 28, 2017

REPORTER'S OFFICIAL TRANSCRIPT OF PROCEEDINGS

DAY V of VIII

DATE TAKEN: Friday, March 24, 2017

TIME: 0803-0217

REPORTED BY: Sally Sybert Gessner Official Court Reporter Administrative Law Judge Office Baltimore, Maryland 21202-4022

# UNITED STATES COAST GUARD MARINE BOARD OF INVESTIGATION PANEL MEMBERS

COMMANDER MICHAEL CAPELLI, CHAIRMAN Coast Guard Seventh District (DPI)

Miami, FL 33131-3030

LCDR STEPHEN MIROS, Esquire
Coast Guard Office of Maritime & International Law

Washington DC 20593

JASON YETS, Esquire Cruise Ship National Center of Expertise

Ft. Lauderdale, Florida 33316-4210

LT JENNIFER PROCTOR
Coast Guard Seventh District (DPI)

Miami, FL 33131-3030

LTJG CARLOS DIAZ-COLON
Coast Guard Sector San Juan

San Juan, PR 00901

BOARD MEMBERS NOT PRESENT:

Mr. Jim Gillette, Coast Guard Investigations, NCOE Mr. Tom Woodford, Coast Guard Marine Safety Center

Appearance:

LT Shannon Price Coast Guard Prevention Law Division

Washington, DC 20593-7213

# NATIONAL TRANSPORTATION SAFETY BOARD MARINE BOARD INVESTIGATION PANEL MEMBERS

ADAM TUCKER
INVESTIGATOR-IN -CHARGE
Office of Marine Safety
490 L'Enfant Plaza East, SW
Washington, DC 20594-2000

LARRY D. BOWLING Office of Marine Safety 490 L'Enfant Plaza East, SW Washington, DC 20594-2000

CARRIE BELL
Office of Marine Safety
490 L'Enfant Plaza East, SW
Washington, DC 20594-2000

LUKE WISNIEWSKI Office of Marine Safety 490 L'Enfant Plaza East, SW Washington, DC 20594-2000

## NANCY McATEE

Fire & Explosive Specialist Office of Research & Engineering 490 L'Enfant Plaza East, SW Washington, DC 20594

### APPEARANCES ON BEHALF OF PARTIES IN INTEREST

PANAMA

Mr. Gaspar Arenas

AMERICAN CRUISE FERRIES:

Carlos E. Bayron, Esquire

Mayaguez, PR 00681

<u>Luz D. Vargas Rivera</u>

Mayaguez, PR 00681

RINA

Paul E. Calvesbert, Esquire

BAJA FERRIES:

New Orleans, LA 70130

Manolo T. Rodriquez-Bird

San Juan, PR 00918-2405

J. Ramon Rivera-Morales

San Juan, PR 00918

Jorge F. Blasini-Gonzalez

San Juan, PR 00918-3405

## TABLE OF CONTENTS

WITNESS COMMANDER		JENKINS ise Ship NCOE)	PAGE 10
_		Jennifer Proctor	12
Examined by	y Ms.	Nancy McAtee	26
Examined by	y Mr.	Larry Bowling	29
Examined by	y Mr.	Adam Tucker	49
JERRY McMI			55
COMMANDER	JANET	ESPINO-YOUNG	
Examined by	y Mr.	Larry Bowling	55,120,146
Examined by	y Mr.	Adam Tucker	114,143
Examined by	y Comr	mander Capelli	118
CWO ALLAN I	P○TH		149
Examined by	-	Bowling	150,174
Examined by	y Mr.	Tucker	171
Examined by	y Ms.	McAtee	173
Examined by	y CDR	Capelli	178

#### PROCEEDINGS

Start Time 0803

CDR CAPELLI: Good morning, the hearing will come to order. Today is March 24<sup>st</sup>, 2017, the time is 0803 we are continuing at the Caribe Hilton, in San Juan, Puerto Rico. I am Commander Mike Capelli of the United States Coast Guard, from the Seventh Coast Guard District, Inspection and Investigation Branch, in Miami, Florida.

I have been directed to serve as the Lead

Investigating Officer for this Formal Investigation

which has been convened by the Commander of the Seventh

Coast Guard District, Rear Admiral Scott Bushman under

the authority of Title 46, United States Code, Section

6301, and Title 46 Code of Federal Regulations, Part 4.

To investigate the circumstances surrounding the fire, subsequent grounding, and full evacuation of 511 passengers and crew off the Caribbean Fantasy on August 17<sup>th</sup>, 2016 while approaching the pilot boarding station to the Port of San Juan, Puerto Rico. I am conducting this investigation under the rules in 46 C.F.R. Part 4. The investigation will determine as closely as possible the factors that contributed to the incident so that proper recommendations for the prevention of similar casualties may be made.

Determine whether there is evidence that any act of misconduct, inattention to duty, negligence, or willful violation of law on the part of any licensed or certificated person contributed to the casualty and determine whether there is evidence that any Coast Guard personnel, or any representative or employee of any government agency, or any other person caused or contributed to the casualty.

Panama has been invited to attend this
hearing as a Substantially Interested State, and is
represented by Mr. Arenas. I have previously
determined that RINA, American Cruise Ferries, and Baja
Ferries are Parties in Interest to this investigation.
These parties have a direct interest in the
investigation and have demonstrated the potential for
contributing significantly to the completeness of the
investigation or otherwise enhancing the safety of life
and property at sea. All parties in interest have a
statutory right to employ counsel to represent them, to
cross-examine witnesses, have witnesses called on their
behalf.

I will examine all witnesses at this formal hearing under oath and witnesses will be subject to federal laws and penalties governing false official statements.

Witnesses who are not parties in interest may be advised by their counsel concerning their rights.

However, such counsel may not examine or cross-examine witnesses, or otherwise participate.

These proceedings are open to the public, and to the media. I ask the cooperation of all persons present to minimize any destructive influence on the proceedings in general and on the witnesses in particular. I ask that you silence all electronic devices at this time.

The members of the press are welcome, and an area has been set aside for your use during these proceedings. The news media may question witnesses concerning their testimony after I have released them from these proceedings.

Since the date of the casualty, the NTSB and the Coast Guard have conducted substantial evidence collection activities, and some of that previously collected evidence will be considered during these hearings. Should any person have, or believe he or she has information not brought forward, but which might be of direct significance to the ongoing investigation that person is urged to bring the information to my attention by emailing CaribbeanFantasy@USCG.mil.

The Coast Guard relies on strong partnerships

to execute its missions, and this investigation is no
exception. The National Transportation Safety Board is
participating in this hearing. Mr. Adam Tucker, seated
to my left is the Investigator-In-Charge for the NTSB
investigation. Mr. Tucker would you like to make a
brief statement?

MR. TUCKER: Yes, good morning, my name is

Adam Tucker; I'm the Investigator-In-Charge for the

National Transportation Safety Board for this

investigation. The National Transportation Safety

Board is an independent federal agency which under the

Independent Safety Board Act of 1974 codified as 49

U.S. Code Chapter Eleven is required to determine the

probable cause of this accident, to issue a report on

the facts, conditions, and circumstances related to it,

and make recommendations for measures to prevent

similar accidents.

duplicating the development of the facts.

Nevertheless, I do wish to point out that this does not preclude the NTSB from developing additional information separately from this proceeding if that becomes necessary.

The NTSB has joined this hearing to avoid

At the conclusion of this hearing, the Safety Board will analyze the facts of the accident, and

1	determine the probable cause independent of the Coast
2	Guard. At a future date, a separate report of the
3	Safety Board's findings will be issued to include our
4	official determination of the probable cause of this
5	accident. If appropriate, the Safety Board will issue
6	recommendations to correct safety problems discovered
7	during this investigation.
8	Thank you.
9	CDR CAPELLI: We will now call our first
10	witness of the day, Commander Jenkins the supervisor at
11	the Cruise Ship National Center of Expertise.
12	WITNESS
13	COMMANDER RANDY JENKINS
13	COMMINDER RANDI DERRING
13	LTJG DIAZ-COLON: Good morning
14	LTJG DIAZ-COLON: Good morning
14 15	LTJG DIAZ-COLON: Good morning  Commander, can you please stand and raise your right
14 15 16	LTJG DIAZ-COLON: Good morning  Commander, can you please stand and raise your right  hand? Whereupon a witness produced on call of the
14 15 16 17	LTJG DIAZ-COLON: Good morning  Commander, can you please stand and raise your right  hand? Whereupon a witness produced on call of the  Coast Guard was duly sworn according to the law, was
14 15 16 17 18	LTJG DIAZ-COLON: Good morning  Commander, can you please stand and raise your right  hand? Whereupon a witness produced on call of the  Coast Guard was duly sworn according to the law, was  examined and testified as follows:
14 15 16 17 18	LTJG DIAZ-COLON: Good morning  Commander, can you please stand and raise your right  hand? Whereupon a witness produced on call of the  Coast Guard was duly sworn according to the law, was  examined and testified as follows:  THE WITNESS: I will.
14 15 16 17 18 19 20	LTJG DIAZ-COLON: Good morning  Commander, can you please stand and raise your right hand? Whereupon a witness produced on call of the  Coast Guard was duly sworn according to the law, was examined and testified as follows:  THE WITNESS: I will.  LTJG DIAZ-COLON: Please be seated. For the
14 15 16 17 18 19 20 21	LTJG DIAZ-COLON: Good morning  Commander, can you please stand and raise your right hand? Whereupon a witness produced on call of the  Coast Guard was duly sworn according to the law, was examined and testified as follows:  THE WITNESS: I will.  LTJG DIAZ-COLON: Please be seated. For the record can you please state your full name and spell
14 15 16 17 18 19 20 21 22	LTJG DIAZ-COLON: Good morning  Commander, can you please stand and raise your right hand? Whereupon a witness produced on call of the  Coast Guard was duly sworn according to the law, was examined and testified as follows:  THE WITNESS: I will.  LTJG DIAZ-COLON: Please be seated. For the record can you please state your full name and spell your last?

LTJG DIAZ-COLON: For the record will the

25

1 | Counsel please state your full name?

and I am the Detachment Chief.

2 COUNSEL: LT Shannon Price, P-R-I-C-E.

THE WITNESS: Thank you. Commander, where are you currently employed, and what is your position?

THE WITNESS: I am currently employed at the Cruise Ship National Center of Expertise, the CSNCOE,

LTJG DIAZ-COLON: And can you give us a brief overview of your prevention experience?

THE WITNESS: Sure, I graduated from the United States Merchant Marine Academy at King's Point, and earned a commission under the Coast Guard's direct commission, MARGRAD, or Maritime Graduate Program.

And my first duty station was at Hampton Roads, where I was an inspector-in-training earned several quals, qualifications, and after there was assigned to MSO San Diego, I was the resident inspector at NASCO Shipyard overseeing new construction of deep draft vessels.

Shortly thereafter I was fleeted up into the chief of inspections position at MSO San Diego. I competed and earned a Coast Guard sponsored postgraduate program position, and earned a Master's Degree in Fire Protection Engineering at WPI in Worcester, Massachusetts. I then did a payback tour at the Coast

1	Guard's Marine Safety Center at headquarters where I
2	was the major vessel branch chief. And part of my
3	assignment there, was, and duties there were to oversee
4	cruise ship plan review.
5	From there I was the chief of prevention
6	at MSU Port Arthur. And now I am currently assigned as
7	the attachment chief at CSNCOE.
8	LTJG DIAZ-COLON: Thank you, Commander.
9	I am going to pass the floor over to Lieutenant Proctor
10	which will continue questions.
11	WITNESS
12	COMMANDER RANDY JENKINS
13	EXAMINATION
14	BY LT PROCTOR:
14 15	BY LT PROCTOR: Q. Good morning Commander.
15	Q. Good morning Commander.
15 16	Q. Good morning Commander.  A. Morning.
15 16 17	Q. Good morning Commander.  A. Morning.  Q. This is Lieutenant Jennifer Proctor with the
15 16 17 18	Q. Good morning Commander.  A. Morning.  Q. This is Lieutenant Jennifer Proctor with the  U.S. Coast Guard. Commander you had stated that you
15 16 17 18 19	Q. Good morning Commander.  A. Morning.  Q. This is Lieutenant Jennifer Proctor with the  U.S. Coast Guard. Commander you had stated that you  were the detachment chief of the Cruise Ship National
15 16 17 18 19 20	Q. Good morning Commander.  A. Morning.  Q. This is Lieutenant Jennifer Proctor with the  U.S. Coast Guard. Commander you had stated that you  were the detachment chief of the Cruise Ship National  Center of Expertise, can you please explain to me what
15 16 17 18 19 20 21	Q. Good morning Commander.  A. Morning.  Q. This is Lieutenant Jennifer Proctor with the  U.S. Coast Guard. Commander you had stated that you  were the detachment chief of the Cruise Ship National  Center of Expertise, can you please explain to me what  the NCOE is, and does it do, how is it staffed, and
15 16 17 18 19 20 21 22	Q. Good morning Commander.  A. Morning.  Q. This is Lieutenant Jennifer Proctor with the U.S. Coast Guard. Commander you had stated that you were the detachment chief of the Cruise Ship National Center of Expertise, can you please explain to me what the NCOE is, and does it do, how is it staffed, and what are its missions?

mission areas. We help and assist in the development
of policy and regulations. We don't own or write any
policy, but we are heavily involved in their
development as subject matter experts, and that
includes engaging in position papers, or providing
feedback to position papers that actually go in front
of the IMO, that help shape international regulations.

That also involves the development of policy and guidance as it relates to training of our members in the field doing cruise ship exams. So we have helped create the Tactics, Techniques, and Procedures, the TTP's that guide how an exam should be conducted, it also includes development of process guides.

We serve as force multipliers to the field, so we still actively engage in examinations whenever the field needs the support or they are short-staffed, we travel worldwide to conduct that, and to help them engage in those exams.

We also do, about a third of our work is involved in training. So we host a course three times a year that's a week long, as a prerequisite for every member who is trying to get a qualification to do foreign passenger vessel examinations.

In addition to that, we help facilitate our Ship Rider Program, which is also a prerequisite to

- 1 getting the qualification. And it is sort of like a
- 2 | little mini internship, where our student will go on
- 3 | board a cruise ship for a week or so, and they
- 4 | interview the department heads, and try and basically
- 5 | get a sense of what it is that the cruise ship
- 6 | employees have to deal with on a day to day basis. And
- 7 | it gives them a better awareness of what the impact is
- 8 | of their decisions when they are on board conducting
- 9 their examinations.
- And then finally, we try to serve as a conduit

  for the industry. If they have any questions or

  concerns or they are not sure of the interpretation of

  a regulation we'd like to be that point of contact for

  them. Or if they are having any issues with a, you
- 15 know, an examination or something like that. We like
- 16 to try and act as arbitrator for that as well. And
- 17 | that includes engaging in stakeholder meetings, to
- 18 | include cruise lines, classification societies, and
- 19 trade associations.
- Q. Thank you. You briefly touched on the
- 21 | training and the Ship Rider Program, can you please
- 22 describe what the qualification process is for someone
- 23 to become a foreign passenger vessel examiner?
- A. Sure. So we have a PQS that outlines several
- 25 | competencies that we want the trainee to have

competency and proficiency in. It is a fairly rigorous process, that is each individual unit will have verifying officers that are also qualified that will oversee the training and mentorship of their trainees.

So it requires them to research what the requirements are and the international standards, there is a performance element to it, they have to actually go out and then demonstrate that they have earned the proficiency in overseeing those exam processes, and the ability to inspect various arrangements, or system, ship's equipment.

Once they have satisfied that they have the proficiency of that competency then they will get it signed off.

At the completion of their PQS, when they have satisfied all the competencies in there, they will sit for a formal board of qualified members, who then will assess whether they are deemed, qualified to do that examination.

In addition, as I mentioned, the cruise ship course is a prerequisite as well, as is the Ship Rider Program.

Q. Thank you. Could you please describe how the NCOE trains on a holistic approach for determining substantial compliance, and what that means?

A. Sure. So we teach that the best approach to doing a cruise ship exam is to do a holistic assessment. We have gotten away from where we use the checklist mentality, where we go on board and we say we look at, you know, two or three things in a space, check, check, check. In the meantime missing five or six other things that we should also be aware of, or be assessing as part of our Port State Control activities.

So we are guided, in part, by the principles in Regulation, Chapter 22 Regulation 2 of SOLAS which provides for the fire safety objectives. And that is to first try and prevent the fire from occurring in the first place. And then, since we can't reduce the risk down to zero, we want to be able to minimize the impact of the fire to the passengers and the crew, as well as to the ship. And we do that through containment, early detection, containment, and then suppression.

And then, when all else fails, if we are not able to contain the fire, then the idea to provide safe egress from the ship for the passengers and crew to the lifesaving appliances.

Q. Thank you. I'd like to talk to you about structural fire protection with regards to the precommissioning and post-delivery, during the initial certificates of compliance. Can you please describe

what it is in that process?

A. Sure, so if a vessel, a foreign cruise ship wants to operate in the U.S., they want to embark or disembark passengers in U.S. ports, or they carry U.S. passengers, that's the criteria that would require them to participate in our program.

There are basically two types of ships that we would see in that regard. And one would be a new construction vessel, and another one would be one that's existing that wants to operate in the U.S. for the first time. The process, for the most part is the same.

For new construction vessels it would start, typically with concept review, where the designer or potential owner, or someone from the shipyard even, would come and they would basically propose the idea of the cruise ship that they want to build.

And it is an early opportunity for the Coast Guard to identify any areas that they may think that there is, you know, some differences of interpretation, or some areas of concern that we may have for them operating in the U.S. Once that has been resolved, then it usually goes into the plan review stage.

For existing vessels, typically, that's where they enter in is the plan review stage. The Marine

Safety Center will review several plans, namely the
structural fire protection plans. They would also
identify how spaces are categorized on the vessel,
means of escape, and those plans need to be approved by
the vessel's flag state beforehand.

- So once we receive them, they are supposed to be approved already, and it just gives us an opportunity to spot check and review that yes, we agree that the ship is designed in accordance with the regulations.
- From there, we engage in four types of fire exam processes. There is the structural fire protection exam, then there is the initial certificate of compliance exam, which is our document that indicates that we feel the ship is in substantial compliance with the international regulations.
- To the -- from -- once the ship's operating in the U.S. routinely, then we will conduct an annual exam which is an annual renewal of that certificate of compliance, and then usually at the six month interval of that one year cycle we will conduct a periodic exam which focuses on crew proficiency, and competency.
- Q. Thank you. Can you please just go into detail about the structural fire protection portion of certificating vessels, and elaborate on the difference

between A, B, and C, structural fire protection?

A. Sure, so structural fire protection basically, is a process of segregating spaces that may represent a higher degree of fire risk from spaces that we want to protect. Like those that are accessible to passengers.

There are three types of barriers that are constructed to achieve that, and that's A, B and C class, "A" providing the highest degree of protection.

An A class barrier is required to prevent the passage of smoke and flames for up to one hour.

And then if there is a need for additional protection, A class construction is further broken down into A15, 30, and 60. And the performance criteria for that is to prevent the passage of heat through that barrier, through conduction, trying to prevent things from the other side of the bulkhead from catching on fire for example, commensurate with those times, so 15 minutes, 30 minutes, and 60 minutes.

And the performance criteria for that is it is supposed to provide, prevent the heat rise on the unexposed side of the barrier up to 140 degrees Celsius on average. And then any hot spot on the barriers is supposed to prevent the passage of heat of up to 180 degrees Celsius, for that one hour time period. I'm sorry, for the 15, 30, 60, yeah.

Q. Okay. Thank you, and how would you verify structural fire protection during an initial certificate of compliance inspection, and in future examinations by inspectors once the ship is in operation?

A. So for new construction vessels, typically, members from the Marine Safety Center, as well as the unit that is overseeing the new construction, typically it is our Activities Europe Office. But also as far as the Activities is engaged in overseeing construction as well. Typically, around the halfway mark of construction, they will go on board the vessel, and they will verify that the barriers are being constructed and protected in accordance with the plans that they provided.

So we are looking for workmanship, we are seeing that the insulation that is being installed is rated for the barrier that it is required to be rated for. We are also looking for openings in the barrier, so penetrations for cable runs, pipe penetrations, things like that; we are looking to make sure that those are also adequately protected with the fire stops.

We look at -- usually at that point, we are trying to establish space categorization, as well. So

that we can identify that the -- what they said they are using the space for, whether it is shop, or dining hall is, in fact, how that is going, is being built, so that the barriers that are being installed are adequate for the degree of protection that is required..

- Q. How would inspectors verify the structural fire protection in future exams after the ship is in operation?
- A. Again, it is to make sure that those barriers

  -- this -- for once the ship is built the only time

  that you would expect anything to happen with those

  barriers is if they are changing how space is

  categorized or used, which may require a higher degree

  of protection. We may be involved in that to make sure

  that they have actually upgraded the insulation.

A lot of the time they will install new technology that requires penetrating the bulkheads for cable runs, CCTV for example, and we want to make sure that any time that they penetrate the bulkhead that they are doing it in an approved and appropriate manner.

Q. Can you please tell us about some of the fire suppression systems one would find in an engine room such as high pressure, water mist, CO2, total flooding, and also how we would inspect them?

A. Sure that, that is it, and essentially you could have a foam system, CO2 system, or a water based system, either standard sprinkler or high fog, water mist type system. Our examination of that is essentially just to check the material condition of the equipment, sprinkler heads for example.

Occasionally we may actually have them activate one of the systems, if there is room for cause. We have reason to believe through an expanded exam that the system is, for some reason, not performing the way we think that it should perform, or will perform because of damage to it, or something like that. We may actually have them activate the system and make sure that there is actual flow, and -- to the sprinkler, and that you are getting the protection that you need. But for the most part it is a material condition assessment.

Throughout the rest of the ship we may actually test the sprinkler section valves. But for the, for the machinery space that's essentially what we are looking for.

Q. And you briefly mentioned earlier about the annual and periodic exams, can you please describe the difference in those two processes, and what inspectors look for in each type of exam?

A. In an annual exam, we will test systems. We are basically, again, verifying substantial compliance with the international requirements, and that includes, SOLAS, MARPOLE, LOAD LINE for example. And so it will start with an assessment on the pier of the condition of the hull. We make sure that the load line mark is not submerged, for example.

Once we go on board we may assess the, you know, their security posture, make sure that they are actually checking identification to see if they are substantially in compliance with the ISPS code. We will then look for means of escape issues, sometimes they have blocked the corridors with equipment, we are verifying that the pathways are clear.

Again, it's the material condition of structural fire protection barriers. We do crew proficiency checks as well, we will witness fire and abandon ship drills, we will witness muster drills with the passengers, to make sure that the crew is proficient in their duties in that regard.

We are testing nav equipment, we will test the detection system, spot check. We will test the sprinkler section valves to make sure that the alarms and adequate flow is provided. The difference primarily between the systems test and equipment test

of the annual exam and the periodic exam is that the periodic exam is really, primarily focused on the crew and their proficiency, and their training.

We teach our students that at that exam, you typically are not testing equipment except for cause, if you have reason to believe that there is a piece of equipment, for example, that needs to be tested. And we focus more on the crew proficiency and training.

- Q. Can you please elaborate on the crew proficiency, how would -- how are inspectors trained to assess and to verify the crew competency on board?
- A. So usually during a fire and abandon ship drill our teams will be divided up and we will be asking scenario based questions of like the stairway guide, or lifesaving appliance crewmembers, muster station leaders, things like that, and we will be asking them basic scenario questions like, I'm a passengers I have left my medication in my stateroom am I allowed to go and retrieve them.

And what we are doing is, we are testing to see that the process and procedures that are on board the vessel that are in place to assist passengers in emergency situations are being followed. And that the training, that the crew is aware of what those procedures are and that they are actually performing to

those standards.

And so we will ask that question several times of several different crewmembers to make sure that we are getting the same answer, and that way we can get a good assessment of whether or not they are all being trained to the same, and they are all performing to the same standard.

- Q. Do you witness, so do you witness drills, and can you describe what kind of drills you do?
- A. Sure -- the -- we will witness fire drills. So usually we will have the team member on board the bridge to assess the command and communications part of that drill. We will also have team members on station where the fire is hypothetically occurring to see that the fire teams arrive on scene, they are adequately dressed out, verifying the communication back to the bridge so that we can see whether, again, that that communication is taking place. And then we are assessing the ability of the fire team to engage the fire as they are trained to do.

We also assess the abandon ship drill, and that will typically include questioning life boat crew, life raft crew, making sure that they are aware of the equipment on board the lifeboat, how do you launch the lifeboat, how do you start the lifeboat, how do you

1	communicate to the bridge from the lifeboat, where are
2	the rations, things like that. And then we will
3	actually see them usually lower a boat, and most times
4	launch a boat, and operate the boat, and retrieve the
5	boat.
6	Q. Thank you. Is there any instance when a ship
7	would be subject to more than two exams in a year?
8	A. Yes, if we if there is a ship that has been
9	identified as needing additional inspection activity,
10	or exam activity because of a previous detention, or
11	because of a trend of multiple deficiencies on
12	subsequent exams, then they may be identified as
13	needing a quarterly exams, and that is typically done
14	by our headquarters staff.
15	Q. Thank you. I'd like to pass the microphone
16	over to Nancy.
17	WITNESS
18	COMMANDER RANDY JENKINS
19	EXAMINATION
20	BY MS. McATEE:
21	Q. Good morning Commander Jenkins.
22	A. Morning.
23	Q. This is Nancy McAtee from the National
24	Transportation Safety Board. I just have a couple
25	follow-up questions on structural fire protection and

fixed firefighting systems. Would you please discuss
how life safety systems such as Marine Evacuation

Systems and lifeboats are protected from smoke and

fire?

A. So, per Chapter 3 of SOLAS, which provides for the prescriptive requirements for lifesaving appliances, it indicates that the survival craft should be stowed and away as to protect it from damage, and also protest it from the effects of fire and smoke.

Additionally, life raft launching and MES embarkation stations are also required to have a certain degree of protection. The tables call for A60 but they are -- for the side shell of the vessel and way of the lowering arrangements, are allowed to be reduced down to A30.

But there are requirements for structural fire protection in the event that the MES is deployed, and launched in way of accommodation spaces, machinery spaces, category, basically, 11, 12, 13, and 14 spaces, flam lockers, things like that.

So if there is a space like that, that is adjacent to the side shell of the vessel, then we would expect to see some type of structural fire protection, so that if there were a fire in that space, that it doesn't impact the life raft and MES deployment.

Q. Thank you. With respect to A boundaries, what type of fire conditions would lead to a possible reduction in that time period that the protection, say 4 an A60, what reduction, what conditions would lead to a 5 reduction in that time?

1

2

3

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

So the, the premise is that the structural fire protection is designed to provide for passive protection, in the event that you can contain the fire in the space of origin.

However, if for some reason, the -- for example the ventilation is not secured, or openings in the barrier, like fire doors are left open or are not secured adequately, then there is a potential of actually having the fire spread from the space of origin, and then maybe the structural fire protection that's installed won't perform as expected.

- What is the -- now we are going to move over to fixed firefighting systems. What's the specific role of a local application system?
- So a local application system is essentially a water based suppression system designed to protect a specific piece of equipment. Namely internal combustion engines, for example for the use of propulsion or power generation, or boiler fronts, incinerators, oil fueled purifier rooms, for example.

And it is in addition to the suppression system that is otherwise required for the main machinery space.

But it is designed to give the engineers a quick opportunity to suppress a fire in those pieces of equipment that typically represent a higher degree of fire risk.

Q. Thank you, that's all I have at the moment.

8 WITNESS

#### COMMANDER RANDY JENKINS

### EXAMINATION

BY MR. BOWLING:

3

4

5

6

7

9

10

11

23

25

- 12 Q. Commander good morning.
- 13 A. Morning.
- Larry Bowling with the National Transportation 14 Safety Board. Before we get into my line of 15 questioning, what I want you -- I have a couple follow-16 17 ups, but I'm going to ask you to step back and wear one of your earlier hats, and that is when you were at the 18 19 Marine Safety Center. And I understand from records 20 that I have in my possession that you actually 21 performed or supervised some of the initial plan review for the Caribbean Fantasy when it came, first came to 22
- A. Correct.
  - Q. Earlier, I think under, when you were

the U.S. or into service in the U.S. correct?

responding to the Lieutenant, you used the term PQS, can you tell me what that acronym is?

A. Performance Qualification Standard.

- Q. Okay, thank you. And the -- under that same line of questions, you had responded, related to the frequency of the Port State Control examinations on foreign flag passenger vessels, and you mentioned about a reduced interval, or a more frequent schedule. Can you expand on that a little bit?
  - A. As far as the scope of the exam?
- Q. Well the, the frequency and why they are condensed to quarterlies, versus annuals, or semi-annuals.
- A. Sure. So if a vessel had previously been examined and been deemed to have been a substandard condition that warranted a detention, that would be -- that could be cause for our headquarters staff to require them a more frequent inspection interval.

Likewise if a -- over the course of a few years a unit, or several units have gone on board and done examinations, and found multiple deficiencies or deficiencies that keep recurring over time, that may not rise to the level of a substandard condition, but may indicate that there is need for additional scrutiny then that could also warrant additional inspection

activities.

- Q. Okay, thank you. Now does the Cruise Vessel

  National Center of Expertise have input into that, or

  is it between the units in the field and the program

  office at Commandant, or how does -- exactly how does

  that work where a vessel would be put in a very

  frequent or a quarterly schedule?
  - A. Sure, there is nothing that requires our input. But certainly if our program office wants us to weigh in then we will, you know, look at the condition that the vessel is in. We will look at the history of the vessel, the narratives that the local units are inputting and trying from there -- make a recommendation as well. But certainly that is not required and that decision is left up to headquarters to ultimately put them on a quarterly schedule.
  - Q. Okay, thank you. If I could ask Lieutenant Diaz to bring up Exhibit E203. And Commander, while he brings that up, this, I believe is the first letter outbound to the then classification society for the ship at that time Bureau Veritas, which initiated -- it was actually the first piece of correspondence for the initial plan review.

Can you take a quick look at that and verify that is indeed what that is. And what we are looking

- 1 | at is a Marine Safety Center letter -- if you don't
- 2 | mind, Carlos, roll that back up -- or Lieutenant roll
- 3 | that back up to -- there we are -- serial number
- 4  $\mid$  H2100236, and it is dated February 2<sup>nd</sup>, 2011. If you
- 5 | don't mind, let the witness take a look at that.
  - A. Okay.

6

- 7 Q. Scroll up some please, Lieutenant. And if you
- 8 | don't mind, roll to the bottom. I believe Commander
- 9 Jenkins signed that, actually, as a Lieutenant
- 10 | Commander. Okay, and giving that -- I will try to be
- 11 | time efficient, do you recall any elements of the --
- 12 | your involvement with the initial plan review?
- 13 A. I do.
- 14 O. Tell you what, rather than me go through a
- 15 | line of questions; just tell me what you recall. And
- 16 | it is okay if you don't remember it all. Just tell me
- 17 | what you remember from that plan review process.
- 18 A. Sure, from what I remember, this was a vessel
- 19 operating in Mexico and they were looking to bring her
- 20 to the U.S. to operate between Puerto Rico and the
- 21 | Dominican Republic. She was an existing ROPAX/Roll on
- 22 | car carrier, basically/passenger vessel.
- 23 She was built I think, as I recall in the
- 24 | 80's, the late 80's. As such, she was subject to the
- 25 | Retroactive Fire Safety Amendments, the RFSA's, which

requires that older vessels, to some certain degree upgrade their fire protection systems, including structural fire protection.

This is a typical plan review letter that we would see on an existing vessel, where there is innumerous amount of questions that we would post to the submitter on how spaces are categorized, whether we think that they are adequately categorized, whether the plans that were presented to us actually show the right type of -- or structural fire protection. And then escape arrangements.

A lot of times we find that maybe there is a dead end corridor that is identified, or direct access to a stair that we think shouldn't be allowed. A lot of times it is administrative, and the actual arrangements in the ship is, is adequate and it is just a plan. Sometimes it is, it does accurately reflect what's going on the ship, and there are issues that we need to resolve.

Q. Okay, and with regard to the initial submission. So would I be correct if -- it looks to me as if the official start date for the plan review would occur when Bureau Veritas submitted the plans. And in this letter it says, January 4<sup>th</sup>, 2011. Would that be about the time the initial plan review process started?

A. That's accurate. Unless there was some correspondence through email back and forth, basically saying that we are getting ready to submit plans to -- or/and there may be some earlier discussions about some issues.

But, officially, that's right, once the plans come in; we advertise a customer service response time of thirty days, where we would basically provide a reply to them on the submission that they provided.

- Q. Okay, if you don't mind, look at these references, can you tell me a little bit about what an individual would see on the -- only the -- I'm not so much worried about the letters, but more so the important plans that MSC would review and ensure compliance with the applicable international treaties. And I guess we'd start with the means of escape.
  - A. Sure.

- Q. Or actually the structural fire protection.
- A. The structural fire protection plan would typically indicate the types of barriers that are provided on the vessel, whether they are A, B, or C class. And then whether they are further broken down in A 30, 60, 15, things like that. What we would do then is we would compare that with the tables and Chapter 22, Regulation 9 that prescribe what the

barriers should be, depending on what spaces are adjacent to each other.

In other words, if you have a galley next to a main dining hall, the table would prescribe a certain type of structural fire protection barrier. So we would look to see that the plan accurately identifies that that is actually what's going on on the ship. It would also, typically provide the types of space categorization that's on board the ship.

We would see that lockers, pantries, public spaces, things like that are being categorized how, you know, we think they should be categorized. Or if there is an opportunity for an interpretation issue, then we — that might be a dialogue that we have with them as well.

Whether, say for example if it is a low risk, that they are identifying a Category 6, but it is a main dining hall, and typically you have a higher degree of combustible load, or combustible volume, then we may have a dialogue that says, well should this be a Category 8. That's the type of dialogue that we would have with the submitter on the structural fire protection plan.

Q. Okay, and then the next plan down, the means of escape, what's the value there on that particular

plan, or what does that show?

A. So, for means of escape we want to see, on the plan, that there is protected space or pathway to the stair towers, and to the lifesaving appliances. We are looking for two means of escape from each main vertical zone. We are looking to see that certain spaces that are prohibited from having direct access to stairs aren't in fact giving direct access.

And it may also include sizing calculations based on the number of passenger or crew that are in those areas will determine the width of certain corridors, or the width of the doorways. And so the Marine Safety Center will also look at some of the calculations that go into that as well to make sure that the corridors were wide enough for the number of passengers or crew that are served.

- Q. Okay, and the next one down, I see are the fire control plan.
- A. So the fire control plan is a plan that will lay out the equipment that is used in fire protection, and like portable extinguishers, controls for ventilation, controls for fire pumps, things like that. And it is basically, we are looking to see that, they are using the right symbology as required by IMO and SOLAS.

Q. Okay, and the next plan down, Reference E lifesaving appliances.

- A. So typically the Marine Safety Center does not review lifesaving appliance plans. But occasionally they will submit the plan as, you know, support for the other plans, for example, to show that the means of escape are provided to those appliances. Unless for some reason they, they are using an alternative design for like an oversize lifeboat then that is a -- that is something that we get involved with.
  - But, in general, for typical lifesaving appliances, that is not something that we would review. And I would expect somewhere on the letter to say that. We use that for reference, but that's not something that we are going to weigh in on.
  - Q. All right, thank you. And then the final plan, I just need a quick explanation on would be the firefighting and safety plan, and it is listed here as Reference F.
  - A. Yeah, to my recollection, I'm not sure what that plan actually depicted.
  - Q. Okay, and Lieutenant Diaz, if you don't mind, run up to Comment Five on page three of this particular letter; I'm going to have the witness see if he recalls a comment here. Comment Five; I am going to read it

for the record.

(Reading) "We are concerned that the vessel's special category space boundary ratings are not in compliance with Regulation 2-2/37.1.2 as required by Regulation 41-2.6.4. Please address compliance with this regulation including details of separation between the main horizontal fire zone, decks two and three, and the main horizontal fire zone two, deck four". Do you recall --

- A. As I recall, Regulation 41-2.6.4 is part of the RFSA's, or the Retroactive Fire Safety Amendments. And I believe, initially, there was a disagreement on the applicability of the RFSA's to this vessel. And whether or not the car decks, which is what the main horizontal zone is basically depicting there, was required to upgrade their structural fire protection to A60.
- Q. Okay, thank you. Lieutenant Diaz, if you don't mind, bring up Exhibit E202; just leave me on the first page. And this is a, what I believe is the second outbound letter from the Marine Safety Center, serial number H2100493, dated February 24, 2011, and this exhibit was also signed by Commander Jenkins, then Lieutenant Commander Jenkins. And again, I haven't seen anything else in the record; I haven't seen any of

the Bureau Veritas submissions, so I'm kind of flying blind on this.

But, I would like to get, like you to take a look at Comment Five on this particular letter, page three. And it is kind of back to the topic we were just talking about. Comment Five, and rather than reading it into the record, I'll let you read it yourself.

A. So Regulation 2-2 37.1.2, compliance with which is required by Regulation 41-2.6.4 requires that: "The boundary bulkheads and decks of special category spaces to be insulated to an A60 standard, except in way of adjacent 5-9, or 10 spaces. The vessel's special category spaces do not appear to meet this requirement in numerous locations."

"In addressing compliance with this requirement, please also include details of the separation between main horizontal fire zone one, decks two and three, and main horizontal fire zone two, deck four, particularly in way of the vehicle ramps."

Q. And again, if you recall, can you tell me a little about the details? My concern there is I don't understand they are -- what the Marine Safety Center, or your team was telling Bureau Veritas regarding those main horizontal fire zones.

A. This again, was part of the dialogue with the submitter on the applicability of the RFSA's, and the need to upgrade those spaces, or those arrangements to an A60 standard. And so, I think at this point, we are just reiterating our position. It may have been because they submitted updated plans and had cleared some of the items.

I note, in some of the previous comments it says, "We consider this issue resolved", so either through dialogue, or through updated plans, they had corrected other items. But it looks like here, we noted that in this particular case they had not, and so we were just reiterated the point that we think that they need to upgrade their SFPA60 for those spaces.

Q. Okay, thank you very much. Lieutenant Diaz, would you bring up Exhibit, I believe it is E201? And same as before, I believe this is the third correspondence outbound to Bureau Veritas, it is MSC letter H21100702, dated March 11<sup>th</sup>, 2001 -- or excuse me, 2011.

And if we could go to -- on page one, I think it's Item Five on that particular letter. Right there, and roll on up a little bit. Take a look -- and you don't have to read it on the record -- but Comment Five -- excuse me, Lieutenant roll on up until I see A and B

1 under five, right there.

Take a look at Comment Five and the subparagraphs A and B, and just if you recall, tell me
what that's about. And the reason I'm questioning, I
want to hear about that is, it specifically starts
talking about the vehicles decks.

- A. So, at this point, it appears that after our second letter, where we called out the arrangements again, their third submission. Then went on record with their disagreement with our interpretation, and they likely provided an argument of why they felt that it didn't apply, and this was, this looks like our reply to that, and disagreement. And then provides our reasoning on why we think it does apply.
- Q. Okay, and just a couple of quick questions.

  And you know I have -- I accept their plan review from the other side, I have never really performed it, except on small boats. So my question is how frequently did you, when you were wearing your hat at the -- as the -- your responsibility at the Marine Safety Center, see submissions where classification society would challenge -- and I want to use that word if I am using it correctly --
- A. Yeah.
- 25 Q. -- but challenge the applicability of a treaty

such as the Retroactive Fire Safety Amendments, or the validity, of it I guess. I'm not quite sure what -- I haven't seen their correspondence on how they put it to the Marine Safety Center.

- A. Sure. The classification societies that we deal with are highly trained and professional members.

  And it is not uncommon for them to disagree with a position that we've taken. And certainly, it is not something that we shy away from, because you know, we are not infallible either.
  - So occasionally we will get into some dialogue like that, and we will try and understand what the intent of the requirements are. We will go back and research the language that was in the preamble, or was at the onset of the regulation, some of the background, and the resolutions, to see what it is, exactly that the -- that the regulators, or the ones that came up with the regulation were aiming for.
  - So certainly that, that does happen on occasion, and it is, it is usually a professional dialogue that we have with them, and then usually at the end we do end up resolving the differences.
  - Q. Okay, thank you. And Lieutenant if you would bring up, I think it is the final Exhibit I need to get to, E200. This is the Marine Safety Center letter H2-

1100721, and it is dated March 15<sup>th</sup>, 2011. And if you don't mind, roll down to the signature page; I believe the witness signed this one as well.

Yes, I want to go to Paragraph Two, there was a section in there I needed some clarification on.

Right there, the -- that paragraph talks about the coloring scheme on the structural fire protection boundaries, and it lays out several concerns that you and the team at the Marine Safety Center had at the time. Do you recall what was your concern, what -- that this color scheme issue on the plans that were submitted?

A. If I recall correctly, usually when we have multiple plans in front of us, we like to verify version control. So especially in the case when they are providing updates or they are correcting plans to address some of our comments.

And there is typically two or three different types of plans that we'll look at, and we want to make sure that what's being reflected on one plan is being reflected on the other one as well. So they are both, they are both being updated/upgraded at the same time.

With respect to the coloring scheme, that's typically something we see on the fire control plan.

The fire control plan only requires that you identify

- bulkheads, either red for A; or yellow for B, if I am
  not mistaken. But it doesn't go into further detail,
- and there is no requirement for it to go into further
- 4 detail on the additional rating of like an A class
- bulkhead of either 15, 30, or 60, it just says A or B.
- And this may have been an area where we -- we
- 7 | didn't -- maybe they were using different colors, or
- 8 | the colors were not reflecting what was required by
- 9 this -- the list of symbols that are used in a fire
- 10 | control plan.
- 11 Q. Okay, thank you. And once a fire control plan
- 12 | is deemed to be final and approved, is it usually
- posted on a vessel somewhere for use by the crew?
- 14 A. It is.
- 15 Q. Is that a requirement?
- 16 A. It is.
- 17 Q. And do you know off the top of your head the -
- 18 where that requirement comes from?
- A. Yes, that is also in Chapter 22 of SOLAS, I
- 20 | think Regulation 15, I'm not sure exactly.
- 21 Q. Okay, thank you. Lieutenant Diaz, if you
- 22 | don't mind, bring up E196, and I just want to ask the
- 23 | witness, again Commander, I haven't seen the Bureau
- 24 | Veritas submissions, but per my records this is the
- 25 | last letter that I have from the Marine Safety Center,

- and it is serial number H2-1102295 dated July 22, 2011.
- 2 | And if you don't mind Lieutenant, run on down just to
- 3 | show the whole body of the text and let the witness
- 4 read that real quick.
- 5 (Brief pause.)
- 6 Okay, and Commander based on what you see
- 7 | before you on this particular letter, would I be
- 8 | correct saying that at this point the Marine Safety
- 9 | Center reached out to Bureau Veritas and said, we
- 10 | consider the initial plan review process complete?
- 11 A. Yes.
- 12 Q. And why is it basically that letter would be
- 13 the last correspondence then, with the classification
- 14 | society?
- 15 A. Yes.
- Q. Okay, and so at this point in the process I
- 17 | think that Lieutenant Proctor worked you through, or
- 18 has asked you these questions. So at this point the
- 19 | field office would pick up --
- 20 A. That is correct.
- 21 Q. -- the verification?
- 22 A. That's correct.
- 23 Q. So can you expand a little bit what happens
- 24 | right at this point with the local Port State Control
- 25 | inspectors, how they validate the Marine Safety Center.

Sure, in this letter, it looks like all of our plan review comments were adequately addressed. And so there were no further comments. Occasionally you will 4 see additional requirements that the -- that we are -aren't able to verify from a 2D plan, that needs to 5 actually to be verified on board the ship. In that 6 case, we will provide some documentation that says that it needs to be verified by the officer in charge of 8 marine inspection.

Let's see -- room and room construction that requires detection that alarms whenever a fire is occurring outside the space, for example, is one. It is depicted on the plan but we would say, okay, the local unit needs to go out and verify that the alarms actually work.

But in this case it looks like all the plans, all the comments were satisfied. And then you will see at the bottom there, we copied the letter to the unit where the ship is planning to operate.

- Okay, I see that copy, Commander, Coast Guard Sector San Juan, Prevention Department.
  - Α. Correct.

1

2

3

7

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

Before we leave this particular Exhibit, the general question, but related specifically to the Caribbean Fantasy, but my question is with the Marine

- Safety Center, once the plan review process is complete, does that terminate the responsibility for the Marine Safety Center? Or does the Marine Safety Center staff stay active with the -- in this case, Sector San Juan preventions department through the validation process as the team visits the ship?
  - A. Typically at this point the Marine Safety

    Center, because the Marine Safety Center is a tool for

    the local unit, because they have the expertise, and

    doing the plan re (sounds like re) piece of it. So

    once they are satisfied that the plan review portion is

    complete, then usually they move on to other projects.

If the vessel down the road ends up making modifications or refurbishments, then that may reinitiate some plan review activity.

But at this stage then, their involvement would be over with unless the local unit had requested their assistance in doing the initial examination.

- Q. Okay, thank you. And I mentioned Bureau

  Veritas in here, and the vessel has since changed

  classification societies, it's changed over to RINA are

  you aware of that?
- A. I am.

Q. Tell me from your experience, what a classification society's role is with regard to

ensuring a vessel is maintained per its plans that are approved?

A. So depending on the flag state many of the flags will delegate the, the authority and the ability of the class societies to perform on their behalf. And that entails issuing the Passenger Ship Safety

Certificate which is issued at the conclusion of their exam process.

And they are going on board and they are -- as the flag state representative, going in greater detail than what we would do as a Port State Control and verifying that systems are operating properly, that the arrangements are staying the same, that there haven't been any modifications.

It is just a greater inspection, usually it is a three, four day examination that they are doing, and they are, again, verifying compliance with the international standards. And then once they are satisfied, they'll issue the PSSC, or the Passenger Ship Safety Certificate.

Q. Okay, thank you. Earlier we were talking about the frequency of the Coast Guard Port State Control exams, examinations on foreign flag ships. And the question I have is were you aware that the Caribbean Fantasy was on a quarterly inspection

1	schedule at Sector San Juan?
2	A. I was not aware until after the incident.
3	MR. BOWLING: Okay, thank you. Thank you
4	Commander, I have no further questions at this time,
5	thanks.
6	CDR CAPELLI: Good morning, the time is 0905
7	and we are going to take a quick recess.
8	(Whereupon a recess was taken from 0905-0920.)
9	CDR CAPELLI: Good morning, the time is 0920
10	we will now reconvene; we are going to continue
11	questioning from Mr. Adam Tucker from the NTSB.
12	WITNESS
13	COMMANDER RANDY JENKINS
14	EXAMINATION
14 15	EXAMINATION BY MR. TUCKER:
15	BY MR. TUCKER:
15 16	BY MR. TUCKER: Q. Good morning Commander.
15 16 17	BY MR. TUCKER:  Q. Good morning Commander.  A. Morning.
15 16 17 18	BY MR. TUCKER:  Q. Good morning Commander.  A. Morning.  Q. My name is Adam Tucker; I'm with the National
15 16 17 18	BY MR. TUCKER:  Q. Good morning Commander.  A. Morning.  Q. My name is Adam Tucker; I'm with the National Transportation Safety Board. And just a few follow-up
15 16 17 18 19 20	BY MR. TUCKER:  Q. Good morning Commander.  A. Morning.  Q. My name is Adam Tucker; I'm with the National  Transportation Safety Board. And just a few follow-up  questions to what, and clarifications. My first
15 16 17 18 19 20 21	BY MR. TUCKER:  Q. Good morning Commander.  A. Morning.  Q. My name is Adam Tucker; I'm with the National  Transportation Safety Board. And just a few follow-up  questions to what, and clarifications. My first  question is related to crew drills, and in specific you
15 16 17 18 19 20 21 22	BY MR. TUCKER:  Q. Good morning Commander.  A. Morning.  Q. My name is Adam Tucker; I'm with the National Transportation Safety Board. And just a few follow-up questions to what, and clarifications. My first question is related to crew drills, and in specific you mentioned crew proficiency. During the Coast Guard
15 16 17 18 19 20 21 22 23	BY MR. TUCKER:  Q. Good morning Commander.  A. Morning.  Q. My name is Adam Tucker; I'm with the National Transportation Safety Board. And just a few follow-up questions to what, and clarifications. My first question is related to crew drills, and in specific you mentioned crew proficiency. During the Coast Guard either the annual or the quarterly, does anybody

A. Yes that all ties back to effective communication. So if we are noticing that they are -- the command and control structure on the bridge is not able to decipher what it is that the team on scene is passing -- whether it is because, due to a language barrier or some other reason, then certainly that might be something that we raise as an issue.

- Q. Thank you. And still staying with the drills, the crew drills, so does the ship or does the vessel typically determine, you mentioned fire drills for example. Does the ship decide where the fire is going to be, or is that something that the Coast Guard port safety control officers go on board and say, no I want to see a fire here. How does that work?
- A. The drill is their drill, it's their evolution. We are just assessing their process and their ability to actually conduct the drills effectively.

So we will make that a point when we go and have our pre-meeting with the staff, we will let them know, we are, you know, we'd like to witness a drill. And then they establish where the drill scenario's going to be, and then we make sure that the processes that they have in place on board the ship are being followed.

So there is a requirement to at least once a year do a drill, in a CO2 protected space. But beyond that, it is -- it's their drill and we let them run it as they would normally run it whenever we are not there. And so one of the things that we key in on though, is that if you are going to do the drill, you know, the regulations require that you do them as realistic as possible, as if it were a real emergency. 

That may be the only kind of guidance that we give them, so we -- we don't want to see them simulating things unless it is for a reason of safety. For example, we want to make sure that they know how to actually secure the ventilation, and they are just not simulating it. That they actually are lowering the boats, or if they are going into a fire protected space that all the equipment that they would normally carry in with them, they are actually wearing, and using. So

- Q. Thank you. And we also talked about the -for this particular vessel the quarterly inspections.

  And it was mentioned substantial compliance is more the annual, and then the remainder were the crew proficiency. I am wondering is the quarterly drill, is that also a, more of a crew proficiency evaluation?
  - A. It's a blend. The quarterly exam is similar

in scope to an annual exam. However, it may be more of
a spot check, so there may be systems and equipment
that we are not necessarily testing to -- as much -- to
the degree that we would on an annual exam. But the
scope and the things that we look at are similar. And
on each of those exams we are questioning the crew
about their position and their duties as well.

Q. Okay, thank you. And now in -- specific to the Caribbean Fantasy, and the actual engine room, I believe it is a category A type oil fire in a machinery space. And I was -- I've looked at the structural fire protection plan, and I've noticed that the deck above is categorized as an A60. And as I understand, an A60 is a -- 60 minutes is that threshold.

And on the sides of ship, I believe what I read was that it is an A30. What's the -- I guess, above that deck there were a lot of cars, a lot of vehicles, cargo essentially on the deck above, and are there any circumstances where that A60 might not hold up?

A. Certainly, the idea of the A60 standard is that it is supposed to provide a degree of protection from the effects of fire for up to one hour for A60.

That's your highest degree that you could provide on the ship. And that is the prevention of the passage of

flame and smoke, as well as a heat rise from actually conducting through that barrier for up to 60 minutes, is for 140/180, 140 on average, 180 on any hotspot or any joints. So that's what you would expect that protection to provide.

But as I mentioned earlier, if for some reason the -- there -- you provide the fire an opportunity to spread from the space of origin, then you may be defeating the ability of the SFP to perform as designed.

And that could be through ventilation systems, through doors that are left open, through penetrations that were not adequately provided with fire stops, like cable runs or pipe runs. In those scenarios then you could possibly, like I said, allow the fire to spread from the space origin, and quicker than the 60 minutes.

Q. Understood. Thank you for that. And what we have noted, just for the record is that from the time that the fire began on this particular accident vessel until the time it was reported by the ship safety officer.

And through testimony of the staff captain, it was around 29 minutes from the time when the fire started, until we had confirmation that there was a fire, the secondary fire in the -- on garage B, and

1 also on the adjacent port side bunker station. Commander that's all the questions I have, thank you 2 3 very much. Α. Sure. 5 CDR CAPELLI: Good afternoon Commander, I have no questions. So at this time Panama do you have 6 any questions for the witness? 7 8 MR. ARENAS: No. 9 CDR CAPELLI: Baja Ferries do you have any questions for the witness? 10 MR. BLASINI: No sir, we do not have any 11 questions. 12 13 (Brief pause.) CDR CAPELLI: Commander Jenkins you are now 14 released as a witness at this hearing, thank you for 15 your testimony and cooperation. If I later determine 16 that we need additional information from you I will 17 contact you through your counsel. If you have any 18 19 questions about this investigation you may contact the 20 recorder, LTJG Diaz-Colon, thank you. We will now recess before the next witness. 21 We will reconvene at 0940. 22 (Whereupon a brief recess was taken 0928-0943.) 23 24 CDR CAPELLI: Good morning the time is 0945,

we will now hear testimony from Commander Espino-Young

1	Chief of Prevention, and Mr. Jerry McMillan the Marine
2	Inspection Training Officer.
3	LTJG DIAZ-COLON: Will the witnesses please
4	stand and raise your right hand.
5	WITNESSES
6	CDR JANET ESPINO-YOUNG
7	MR. JERRY McMILLAN
8	Two witnesses called on behalf of the Coast Guard
9	were duly sworn according to the law, were examined, and
10	testified as follows:
11	WITNESSES: I do.
12	LTJG DIAZ-COLON: Please be seated.
13	CDR CAPELLI: We are going to lead off
14	questioning from Larry Bowling from the NTSB.
15	MR. BOWLING: Thank you, Commander.
16	WITNESSES
17	CDR JANET ESPINO-YOUNG
18	MR. JERRY McMILLAN
19	EXAMINATION
20	BY MR. BOWLING:
21	Q. Just for the record, can I get the witnesses
22	to spell their last names, please?
23	A. THE WITNESS/CDR ESPINO-YOUNG: Espino-Young,
24	E-S-P-I-N-O-Y-O-U-N-G.
25	O Thank wou Mr MoMillan?

- A. THE WITNESS/MR. MCMILLAN: M-C-M-I-L-L-A-N.
- Q. Okay, and you are represented by counsel, correct?
  - A. CDR ESPINO-YOUNG: Yes.

- 5 COUNSEL: Yes, Lieutenant Shannon Price, P-R-I-C-E.
  - Q. Thank you. And again, I will try and direct my questions for one of the witnesses individually, but if I direct it to the wrong individual, please feel free to speak up.

Some high level questions, I would like to hear from Commander Espino-Young, I understand you are the chief of prevention. Can you tell me what that role at Sector San Juan entails, and let's just narrow it to foreign flag vessels operating within your area of responsibility.

- A. CDR ESPINO-YOUNG: The chief of prevention has been delegated with the duties to oversee the Port State Control program in this Captain of the Port Zone in San Juan. So our inspections division on the Port State Control side conducts foreign flag inspections on cargo vessels, tank vessels, passenger vessels that are operating within their zone.
- Q. Okay, thank you. If you don't mind, pull that microphone a little closer to you and Mr. McMillan, there, thank you.

The -- again, at the higher levels, but specific to foreign flag passenger vessels, such as the Caribbean Fantasy, tell me about the safety net, or the safety regime. And what I'm looking for is I want to hear about responsibilities for compliance and safety, where it falls with owner, where it falls with the classification society or responsible organization that the ship is being serviced by, the master, and where the Coast Guard fit into that, the Port State Control regime.

A. CDR ESPINO-YOUNG: So for the hierarchy within the operating safety net, when it comes to complying for an international conventions, it is the ultimate responsibility of the flag state, which is the certificating authority to ensure that the vessel is operating under their flag in international service are compliant with the international standards.

And part of that is, obviously, ensuring that the owner and operator are also taking heed in executing their mission. And then the recognized organizations are delegated, depending on how their relationships are between the flag state and RO's, for short, in the class to survey the vessels and issue certification on their behalf with compliance to the international standards.

Port State Control regime falls as the last ditch effort in that safety net, which is the catch all we, you know, with our Port State Control Program vessels, foreign vessels arriving into U.S. shores to operate commercially, submit their notice of arrivals, and part of that is for us to go through a series of 6 vetting processes and procedures to identify vessels to conduct examinations on.

1

2

3

4

5

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

And therefore we are, you know we are somewhat auditing to ensure that the vessels are in compliance and we schedule examinations to do that based on a series of prioritization, priority ones, twos, and nonpriority vessels, both on the safety and side.

- Okay, thank you. And as far as the program Q. itself, where is that managed out of?
- CDR ESPINO-YOUNG: That is Headquarters CVC. So the Compliance, Vessel Compliance folks up at Headquarters are the managing of the Port State Control Program. And then policy disseminates down the chain to the actual operating Captain of the Port zones.
- Q. Okay, and you used the acronym CVC is that Commercial Vessel Compliance?
  - CDR ESPINO-YOUNG: Α. Correct.
- Okay, thank you. From the standpoint of the International Safety Management Code, tell me how that

particular instrument ties in to a Port State Control
Program. And if you don't mind, explain the value or
the intent of the ISM code with regard to compliance
with the applicable statutory requirements, and the
international treaties.

- A. CDR ESPINO-YOUNG: So, the intent of the ISM program, or the ISM code as an offshoot of SOLAS was really intended to ensure that the owner/operators and the companies were held responsible or ensured that there was a series of check and balances between company ashore, and then the vessel itself was also going through a series of auditing, internal audit processes.
- So, the intent was to hold vessels accountable, and owners accountable to ensure that requisitions, you know, for parts were submitted on time, when corrective action or deficiencies were identified by the vessel crew they were immediately reported to the shore based company for corrective action. So, it was to really engage the owners in the complete process of managing a vessel to ensure the substantial compliance, and that substandard ships were eliminated.
- Q. Thank you. Lieutenant Diaz, would you bring up Exhibit E071, and Commander, this is the IMO

Resolution A 1022(26), Guidelines on the Implementation of the International Safety Management Code by Administrations. Have you seen this document before?

> Α. CDR ESPINO-YOUNG: Yes.

1

2

3

5

7

9

11

13

14

15

16

17

18

19

20

21

22

23

24

25

Q. Okay, if you don't mind, Lieutenant roll, or scroll down to Section 2.1.2 and it is a, it talks 6 about verification and compliance with the ISM Code. And right -- keep going, and Commander from your 8 position as a chief of preventions and with regard to your Port State Control teams when they are doing these 10 exams, tell me what Section 2.1.2 means for a Port State Control team. 12

Particularly with regard to the objectives for trying to validate whether a system is effectively implemented on a ship versus one that may not be effectively implemented.

CDR ESPINO-YOUNG: So, the administration, Α. through a designated company, you know, usually a recognized organization also does audits, or really surveys.

And there is a - series of, you know on both the company side of things from the, you know, the management itself and they are issued a Declaration of Compliance, which attests to the compliance efforts and that they are meeting the intent of the code on the

| shore based side.

And on the vessel side they are issued a

Safety Management Certificate, attesting to their

compliance to the international standards, and the ISM

Code. So having both of those certifications would

assume that the vessel is compliant with the code

itself.

And then there is a series of surveys that occur periodically, both on the ship, an internal survey, an audit. And on the ship side, on the shore based side by the recognized organization, or the flag state to assure that those — the vessel and the company are actually performing and the system is actually intact and well maintained.

- Q. Okay, thank you. And, with regard to the Caribbean Fantasy on August 17, 2016. And again, tying this into 2.1.2, the administration of that vessel on that day, would that have been the Panamanian Maritime Authority Flag Panel?
  - A. CDR ESPINO-YOUNG: Yes, yes.
- Q. And as far as any authorities that Panama would have delegated, would that have -- would they have delegated responsibility down to RINA, in this case, on the Caribbean Fantasy for verification?
  - A. CDR ESPINO-YOUNG: I believe so, yes.

Q. And while we are still here with the Safety

Management Systems and the ISM Code, if a vessel, in

general, if a vessel is deemed not to have an

effectively implemented Safety Management System

aboard, what actions would Coast Guard; your Port State

Control teams would take?

- A. CDR ESPINO-YOUNG: We would formally provide paperwork for the vessel to be detained under the IMO standards for non-compliance with the ISM Code, and request an external audit be conducted on the Safety Management System of that vessel.
- Q. Okay, thank you. And I think the -- with regard to evidence that a Port State Control

  Examination had been completed on a vessel -- let's stick to the Caribbean Fantasy -- how is that documented? How is that recorded that your teams have gone out and completed a quarterly, or a mid-period, or an annual exam on a foreign flag passenger vessel? How is that captured?
- A. CDR ESPINO-YOUNG: So, there is two ways. For foreign passenger vessels, we issue a Certificate of Compliance, which is issued for a year. And in the second page is a record of, you know, the transaction of that examination. And it clearly identified what type of examination, whether it was an annual,

- periodic, or quarterly. And then a summary of the
  events of that particular exam would be recorded in
  that record.
- 4 And then additionally, there would be a Form A under Port State Control, which would document the 5 actual examination. And if there is deficiencies, a 6 Form B would be issued, describing the deficiencies, 7 under what convention. And then corrective action, 8 whether it was formal detention, would be a Code 30. 9 Prior to departure would be a Code 17. And then you 10 would give timeframes for corrective action. 11

It also would direct either the flag state or the recognized organization to act for corrective action.

- Q. Thank you. And Commander the -- with regard to the flag of Panama, if -- the term open register, are you familiar with that at all?
  - A. CDR ESPINO-YOUNG: Yes, sir.

12

13

14

15

16

17

18

19

- Q. What, tell me what an open registry is, and if the flag of Panama is an open registry.
- A. CDR ESPINO-YOUNG: From my understanding, the
  open registry is a, you know, a flag that, you know,
  has a large constituent, you know, flags of various
  different types of ships, and they also do a lot of,
  you know, all sorts of recreational boats. And for the

- large part, one of the larger registries for
  registering vessels for commercial and recreational
  - Q. Okay, thank you. And from the standpoint of the United States, do you know the status of the United States flag? It is an open registry or closed?
  - A. CDR ESPINO-YOUNG: It is a closed.
  - Q. Okay, final question at the high level, before we get into specifics on the Caribbean Fantasy and the inspections at Sector San Juan, the examinations, I should say. I understand that Commandant, the CVC maintains a list of vessels that are banned from service or basically entering into U.S. waters, are you familiar with that?
- 15 A. CDR ESPINO-YOUNG: Yes.

use.

- Q. Lieutenant Diaz bring up Exhibit -- bear with me one second -- E049, there you go. I pulled this from the Commandant website. How does a vessel, from your knowledge, how would a vessel get put on this list?
- A. CDR ESPINO-YOUNG: You would have to have documented three detentions within a twelve month period, and all of them would be also attributable, the detentions, to ISM as a safety management failure of those deficiencies.

The unit would then put together a memo requesting to
Commandant to ban the vessel meeting the criteria of
the policy.

- Q. Okay, and this -- on the current list of vessels that are banned from operating in the United States, or water subject to the jurisdiction of the United States, there are currently two vessels, both under the flag of Panama, one under the flag of St. Vincent. Did Sector San Juan have any interaction with either of those vessels? The Commander or the Grey Shark, the Panamanian flag vessels?
  - A. CDR ESPINO-YOUNG: The Commander, yes.
  - Q. Tell me about that, from what you recall.
  - A. CDR ESPINO-YOUNG: From my understanding, you know, and I'll defer to Jerry, because he -- it was prior to my arrival that that vessel was an operating vessel in the Captain of the Port Zone, San Juan and was, you know, was detained three times, as a matter of fact I believe they, they -- detained the last time because of an incident and then requested banning for that particular. But I'm sure Jerry has more he can tell us.
  - Q. Okay, Mr. McMillan, just high level summary, tell me about the Panamanian flag vessel Commander.
    - A. MR. MCMILLAN: The Commander is actually owned

by a citizen in St. Thomas. And their primary, they

operated small passenger vessels before, so they bought

this vessel, and it was previously a Greek flag vessel.

Brought it over, and they really did not follow their

Safety Management System at all. They had one on board

they just didn't follow it.

So every time that we go on board, and we detained it is because they were not following their Safety Management System. I can't tell you the details. I do know that the last one is they lost a rudder, and they didn't know they lost a rudder, and I should say they lost two rudders. They lost the first, one, and they didn't know. And the second one, they — I think they ran aground and actually lost the rudder.

So that's how they got, they got banned.

Q. Okay, thank you. And I want to get down into the initial control verification examination and specifics related directly to the Caribbean Fantasy. And as a matter of record, your preliminary interview we have, it is Exhibit #012, and Commander Young, Espino-Young is Exhibit #018, so I don't want to get a lot of details we have already been into.

But I do want to, for the record here, I want you to, if you don't mind, telling in a couple of sentences what exactly a marine inspection training

officer is.

A. MR. MCMILLAN: Okay, my position is to oversee the training of marine inspection inspectors and Port State Control officers. The best way to say this -- it is just, I just oversee the program.

And also, conduct inspections, and also technical expert for a lot of different things that pertain to inspections. And also nationally, marine inspectors are part of work groups to help improve our training program throughout the Coast Guard so we are all working together.

Q. Okay, thank you. And Mr. McMillan what I want to try and do while I have the floor is get you through some of the Port State Control, the more significant Port State Control examinations and findings on the Caribbean Fantasy, starting with the initial Control Verification in early 2011.

So, if you don't mind, walk me through the initial up through say the situation -- or the last Port State Control Exam in August of 2016. And we will probably step back and look at some of them in more detail.

A. MR. MCMILLAN: Okay, I actually prepared a white paper for the command, in August, the  $24^{\rm th}$ , after the incident, to brief him of everything that happened

- 1 | with the vessel.
- Q. Okay, and far as a white paper, can you
- 3 | explain that, and I would ask Commander Capelli, is
- 4 that a matter of record at present?
- 5 CDR CAPELLI: No, it is currently not on
- 6 record.
- 7 BY MR. BOWLING:
- 8 A. MR. MCMILLAN: This white paper was just to
- 9 brief the command of everything that happened with the
- 10 | vessel since we first got notified with it, and then
- 11 after the fire, the last inspection before the fire.
- 12 Q. Okay, Commander, I would ask that we allow the
- witness to use that document, and sometime later we
- 14 | will offer it as an exhibit.
- 15 CDR CAPELLI: He can refer to it to refer
- 16 (sic) his recollection of the activities that were
- 17 happening.
- MR. BOWLING: Okay, thank you.
- 19 BY MR. BOWLING:
- Q. Okay, Mr. McMillan, please continue.
- 21 A. MR. MCMILLAN: Okay, when we first heard about
- 22 | the Caribbean Fantasy, which was the Twilla Star
- 23 (phonetic) at that time, which was Mexican flag, that
- 24 | was in March of 2010. And we got that notification
- 25 | processed through Headquarters, actually, from CVC.

They sent us an email talking about this vessel is coming down.

certificates, those are issued by Mexico.

Then August of 2010 we were notified by Bureau

Veritas, which is the, they were the class society for

the vessel. But they did not issue statutory

And then we talked to them about all the -the process of going through the ICV, and about
submitting plans to the Marine Safety Center, so that
could be done. And that did not actually happen until
January of 2011 --

- Q. Excuse me, Mr. McMillan, would you pull that microphone a little bit closer?
- A. MR. MCMILLAN: This better?
- 15 Q. Yes, thank you.

A. MR. MCMILLAN: Okay. So January of 2011 that's when the operators of the vessel or the owners submitted plans to MSC for review. And they were expecting to start operating in March of 2011.

And in February, we got contacted by a BV rep to schedule ICVE, and we found that the plan review was not based on plans as built. So they had to resubmit those back to flag for approval, so they could be resubmitted to the Marine Safety Center.

Then March 2011, the vessel was denied entry

into our waters because they didn't have a non-tank

vessel response plan in place. Then also March after

they did that, we actually did a Port State Control

Exam on the vessel.

Then a little bit later in March we actually witnessed a deployment of the Marine Evacuation System. And at that time we found that there was a mismatch between the life rafts and the slide. Typically, those systems are approved together. So somewhere along the line they switched the systems, they used a DB chute with Viking life rafts.

And the, the way that system was approved, there is a slide system, the ones that were currently on the vessel when they evacuated the ship.

In April of 2011 the MES was returned back to its original configuration. And that was Viking of Miami, is actually the one that -- overseeing that process.

Then in May, that's when we commenced the ICV over three days, and we issued a 174 item worklist. We cleared 80, and there was about 94, I think, remaining at the end of it. And the vessel wasn't authorized to carry cargo because the cargo deck sprinkler systems was not working at that time.

After the drencher system was fixed on decks A

and B, which is lower decks, the vessel was allowed to continue operation as a cargo vessel, and they still have to continue with the ICV.

Let's see, later in May, I think May 30<sup>th</sup>, that's when we actually issued the COC, and placed on a quarterly exam schedule at that time. We decided that because of all the problems we had seen, that it needed to be put on a quarterly.

And we -- the Marine Safety Manual says that we should coordinate that with CVC, and Headquarters, but I don't think that actually happened. Just a local determination to do that.

Let's see, okay, in August of 2011 the vessel changed flag to Panama, and at that time they also switched their technical operating company to V Ships Leisure, and that was a recommendation of the person who was actually doing the ICV for the company. He recommended that their management system not do it, and that they hire V Ship Leisure to take that part over.

Okay, so November of 2011 we conducted the second quarterly exam and then we found the drencher system clogged on several nozzles. And at that time, they fixed them on the spot, then the company changed their Safety Management System at that time to start flushing the drenchers on a weekly basis while they

were over in Santo Domingo.

And then we also found the charter installed an unauthorized jewelry shop -- I can't remember what deck that was, but they installed it, which was -- during plan review it was identified as a room in room. But the owner went and decided to go ahead and install it. Or, I shouldn't say the op -- the owner, the charter of the vessel decided to go ahead and install it at that time.

Let's see what else. Okay, then December of 2011 we found that the chief mate didn't have the required hazard training that is required. And they fixed that.

Let's see, then April of 2011 the vessel suffered some failure of the ship's surface generators in April and June that was in 2012. And they were fixed, and they actually put on a temporary generator to take care of that. And this was all done under RINA's preview, they knew about it and they approved it. And they talked to us about it to make sure that we were okay with it.

Then in August of 2011 they had an accidental deployment of their port Marine Evacuation System. And they were restricted in passenger count until they got that redone. And what they figured happened, was that

actually activated it. They don't know whether it was intentional, or he just activated it by accident. But to actually activate you actually have to remove some panels to get in there, so they figured it might have been on purpose.

Q. Okay.

A. MR. MCMILLAN: But they never did find out who did it. July of 2013 the vessel suffers a blackout while maneuvering away from the dock while using its bow thruster and had to drop both anchors. And their - - that got investigated to find out why that happened. I don't -- I don't have that in the timeline, but that was a problem that they had.

Then September, 2013 we were informed by

Viking Miami the vessel installed unauthorized hydrostatic release units on their, on both MES's, they have
a special type of hydrostatic release. And those have
to -- you actually can't buy in the Caribbean or the

U.S. they are more for RORO type vessels with MES's,
and they actually had to buy them from Europe.

And the reason, we found out why they did it in our investigation was it was cheaper for them to do that than to buy the other ones. So we had them install the correct ones at that time.

Q. Okay.

A. MR. MCMILLAN: Let's see. I take that back, that was BV up to that point.

In December of 2013 that's when -- yeah,

December of 2013, that's when they switched from BV to

RINA. So, I have to correct that. So everything up to

that point is, was BV.

Then the next significant event was March of 2014 the vessel had a fire in the transitional batteries, and the vessel was allowed to sail with cargo, they were on the dry-dock -- in 21 days, so they were allowed to sail as a cargo ship for 21 days with transitional power, with operational restrictions that were put on them by RINA, and additional crewmembers manning the emergency generator and some things like that.

July of 2014 the vessel returns from dry dock and we conducted a transitional power test, since they had installed a brand new board and brand new battery bank. They failed the first test, then they -- we did a second test and they also failed that. And they were allowed to sail as a cargo vessel without passengers at that time too.

Then in August of 2014 we went on board for a deficiency check for the transitional power. And while

we were conducting -- going to conduct that test we
found that the batteries were completely drained at
that time, and we also found some other deficiencies.

to Safety Management System that were part of that detention. So that was the first time I ever detained a vessel on a deficiency check.

I think there was actually two items that were related

Let's see, then after the vessel came back we conducted a P-1 boarding. Since they, they did have a detention, that's a requirement under our procedures.

Let's see, nothing really up until the second detention which was 21, October 2015. We did -- detained it under SOLAS, STCW, and ISM related deficiencies at that time.

And then in March of 2016 the vessel goes to dry-dock, and is over there until it started heading back in July. And the vessel got detained in Gibraltar by Port State Control over there, and they -- that was due to cleanliness of the engine room, and also problems with the ship's surface generators.

I found out about the detention through -just going to the Equasis website and looking it up
because up to that point we had been corresponding back
and forth by email, and we were supposed to do a -their annual exam about the first week of July, and we

didn't hear anything after July. About the first of July, I think, so July 8<sup>th</sup> is the last email I got from them. And we didn't hear anything from them. And that's -- after that is when I went to the Equasis website, and found out they were detained.

Okay, and from what I -- talking to the

Company later, what happened was, when they were in

Tunisia they got a bad load of ultra-low sulfur fuel,

and when they went to switch over, to go into the

European Union Eco-Zone, they -- that's when they found

out they had bad fuel. They actually seized piston on

two of the three generators because of that.

And the engines were rebuilt; those engines were rebuilt in Gibraltar. And then the ship wanted to, when they were coming over here to do their COC, they wanted to come directly to San Juan and do the COC without having the hotel staff on board. And at that time, we told them no, they had to have the hotel staff on board and trained. They will pass, do their drills and everything.

And so 9 of August is when they finally, I think it was the  $8^{th}$  of August they finally get to San Juan, and on the  $9^{th}$  of August we did their annual COC, and we issued some, a few deficiencies at that time, but nothing major. Some things that you find,

typically when you find a ship coming out of dry-dock, small things.

I shouldn't say small things, one of them was we tested the drencher systems, which we did on every exam because of the problems that they had when they initially came. And I found 21 nozzles on C deck that were not installed on the drencher system. They had them on board and they installed them.

And I ask them why that happened. They said while they were in Tunisia they had -- in the shipyard, they had 250 nozzles stolen. So they had to get new ones procured and delivered to the vessel while they were in Tunisia, they just didn't get that one section completed.

Let's see what else. Also we had a problem with the two fire dampers, because we checked all the fire dampers on C deck. And we found two of the automatic ones didn't close because of problems with the hinges.

They did fix that before we left the vessel.

But we had -- we didn't clear it until we -- Class

actually gave us a report that they were satisfied with

the repairs. And Class was on board for that annual

exam.

I think that is pretty much it for the

timeline of the vessel.

- Q. Okay, thank you and the last exam you were

  just referring to, that would have been the -- the COC

  renewal exam just prior to the fire, and it started the

  first of August, correct?
  - A. MR. MCMILLAN: That is correct.
  - Q. And at least from the records, I understand that Chief Warrant Officer Roth, one of your teammates, was lead on that particular exam?
  - A. MR. MCMILLAN: Yes, I had him be the lead that time.
  - Q. We have him set up as a witness this afternoon, so we will explore that in depth with him. But on that particular exam in August, what role did you play?
  - A. MR. MCMILLAN: I was filling the role of teams two and three, in our process guide. So I had all the passenger decks, all the way down to the cargo decks.
  - Q. Okay, we may come back to that. Let's, if you don't mind, I want to step back to the initial and take a look at some of the documents that we have, and I am going to ask Lieutenant Diaz to bring up Exhibit #013. And at least my understanding, this is the first Captain of the Port Order that I found issued to the

ship from the then Captain of the Port in 2011.

And before I get into questions on this, I'd

like to ask the Commander, tell me what a Captain of

the Port order is, and specifically, it is a control

action, or is it not a control action per the Marine

Safety Manual which is a document that I assume was

used.

- A. CDR ESPINOSA-YOUNG: Yes, Captain of the Port orders are a control action. It is a -- under the Port and Waterways Safety Act, it is a means of controlling a ship, either denying or controlling the vessel movement within U.S. waters.
- Q. Okay and in general, there is a cite at the bottom of that, that actually refers to the Port and Waterways Safety Act, if that order, if that order is complied with, or not complied with, can the company be subject to penalty or other action?
- A. CDR ESPINOSA-YOUNG: Yes, so the acknowledgement at the bottom is for that very purpose. When we issue a Captain of the Port order, is for them to acknowledge. And under the Ports and Waterways Safety Act, at the time, because the penalty action has increased significantly within, I'd say the last four months.

But, you know, they can be subject to penalties up to four thousand dollars per day of

violation of that Captain of the Port order. Also, you know, any, you know, violations of law as well.

- Q. Okay, thank you. Commander, if you don't mind, grab that mic real quick because I am going to -(Witnesses conferring.)
- Q. With a captain of the port order, explain the process at Sector San Juan how that is issued. In other words, I'm looking for do your petty officers have the ability to issue such a document, or are that reserved for the higher level senior officers like yourself?
- A. CDR ESPINOSA-YOUNG: The -- at Sector San Juan the discretion is still kept at the Captain of the Port level. So Captain Warren, or Captain Reijo is the alternate Captain of the Port, has signature authority for issuings of Captain of the Port orders.

So the field personnel will identify an issue, or locally, depending on how -- through the vetting process as it occurred in this case, through our vetting of that particular vessel as it was coming in, identifying the vessel did not have a non-tank vessel response plan.

And therefore, a Captain of the Port order is drafted and routed through the chain of command to, for Captain's signature, to deny the vessel entry based on

- the fact that it did not have a non-tank vessel response plan in accordance with the regulations.
- Okay, so with that said -- and this would be 3 4 an open question for you or Mr. McMillan, whoever 5 feels, they have more detail here -- but, when this Captain of the Port Order was issued, the first 6 paragraph indicates that right around March the 11<sup>th</sup>, 7 2011 the vessel was inbound to the area of 8 9 responsibility for Sector San Juan. And that I -- it looks to me as if they were planning on beginning 10
  - A. MR. MCMILLAN: That's correct.

operations, is that correct?

11

12

13

14

15

16

17

18

19

20

21

22

23

- Q. All right, at this point, had any plan review or approval been completed at the Marine Safety Center, or had any other action been taken at the Sector level where the vessel would be allowed to operate in U.S. waters?
- A. MR. MCMILLAN: They were still under plan review at that time. But they were going to just operate as a RORO cargo ship, that's what their plans were until they -- plan review was completed.
- Q. Okay, and so no passengers were allowed at the time?
- A. MR. MCMILLAN: That's correct.
  - Q. All right, and the significance of a non-tank

vessel response plan, tell me what that is? What is a non-tank vessel response plan at a high level?

A. CDR ESPINOSA-YOUNG: That is a requirement that vessels at greater that 400 gross tons that operate in -- or are intending to operate in U.S. waters have to provide a plan for response and that captures everything from oil spill response to salvage, marine firefighting efforts, emergency towing. That plan gets submitted to our Vessel Response Plan offices up in Headquarters for vetting.

And they have to have contractual agreements with these companies in order to -- in the event of an emergency of any of those things, whether it is salvage, marine firefighting, oil spills. The organizations in charge responsible would be clearly outlined and contractual agreements would be provided.

- Q. Okay, thank you. Lieutenant would you bring up Exhibit E014? Okay, and this is Captain of the Port Order 3961832 dated March the 11<sup>th</sup>, 2011. Tell me what you recall regarding this particular Captain of the Port Order, Mr. McMillan.
- A. MR. MCMILLAN: This is just a, just a followup just to let them know that they couldn't do passenger operations until they completed the control verification exam, and successfully completed the

control verification exam.

- Q. Okay, and as far as the earlier, Captain of the Port Order, and this particular Captain of the Port Order, are you aware if the vessel complied with either or both of the Captain of the Port orders?
  - A. MR. MCMILLAN: They complied with both.
- Q. All right, thank you. Lieutenant bring up E015 please. This is Captain of the Port Order March 16<sup>th</sup>, 2011. That was an Amendment of the first Exhibit we brought up, E013, which was the first Captain of the Port Order, can you tell me there, what's going on with the particular vessel?
- A. MR. MCMILLAN: Okay, when the vessel first arrived we did a, just a Port State Control Exam, because they wanted to do cargo operations. And okay, then they have a -- there is another Document of Compliance, has it carrying -- has (inaudible word) under SOLAS. So, this is different from the safety management one.

So they, that's why they were restricted from carrying HAZMAT on, which on this vessel deck C is their hazmat deck, which is -- there are special structural fire protection requirements for that deck. But they didn't have the certificate, so we wouldn't allow them to carry hazmat, even though if they wanted

to.

- Q. Okay, and at least according to the record that I have this was the third Captain of the Port Order issued to the vessel. Do you know if that Captain of the Port Order was complied with?
  - A. MR. MCMILLAN: Yes, it was.
- Q. All right, thank you. Lieutenant bring up E016. This is the Captain of the Port Order March 18, 2011, which was the fourth Captain of the Port Order in the vessel file that I discovered. Tell me a little about that Captain of the Port Order, and explain, if you don't mind, what a marine sanitation device is.
- A. MR. MCMILLAN: The marine sanitation device is basically a sewage processing plant. The reason we issued this, is because we could not, with what we had seen on board and what, the documents they had on board, we couldn't tell if it met 33 C.F.R. 159 requirements, or the IMO requirements for a marine sanitation device.

So that's, we just tell them at that time they couldn't use it until -- in our waters until they -- excuse me.

- Q. No problem, if you need a break, we can recess for five minutes.
- A. MR. MCMILLAN: No, it is just -- been having a

- longstanding cold, so.
  - Q. Okay.

- A. MR. MCMILLAN: And I think we also found holes in that system too at that time. So they needed to fix it. So we did get the documentation that the marine sanitation device was correct, and they did fix the holes in the tanks.
  - Q. Okay, and on the second paragraph, the vessel was a controller, effectively, was issued to have the vessel remain in port. Is that what I'm reading there, where is says, "I hereby direct your vessel to remain in port until the above deficiency has been addressed"?
  - A. MR. MCMILLAN: Yes, I believe that's because of the holes in the sewage tank.
  - Q. Okay, if you we could bring up Exhibit E17, I believe it is an Amendment to this particular Order.

    And that's Captain of the Port Order, 396731 -- or excuse me, 7319, dated March 18<sup>th</sup>, 2011. And, trying to tie that in to the last Captain of the Port Order we talked about, because at this point it looks like there was a direct order from the Captain of the Port to expel the vessel from the Port of San Juan.
  - A. MR. MCMILLAN: That's correct; they didn't want it to remain in port.
    - Q. Do you recall how that shifted from remaining

in port to depart port?

1

6

7

8

9

10

19

20

- A. MR. MCMILLAN: That was the date of the Captain of the Port Order?
  - Q. Scroll back up, Lieutenant Diaz, please.
- 5 A. CDR ESPINOSA-YOUNG: 18 March.
  - A. MR. MCMILLAN: 18 March. I think it was just the -- I think at that time, I think the company wanted to go to Santo Domingo to actually effect repairs to the plant. So they didn't want to do it here in San Juan.
- Okay, thank you. And we are still on this 11 timeframe, during your run down of the white paper that 12 13 you were describing; you mentioned the issues with the MES slide. And then in April of 2011, so we are kind 14 of getting close there, in the timeline. You said 15 that, I think it was Viking had returned to the vessel 16 17 and returned the MES system into its original configuration. 18
  - A. MR. MCMILLAN: Yeah, that's correct.
  - Q. Tell me what, exactly, was done there, do you recall? Or were you present for that?
- A. MR. MCMILLAN: Yes, I was. The vessel
  installed a DBA chute, and Viking -- the company still
  had the original slide back in Mexico. So they brought
  slides back over. And the local Viking office here,

Viking Miami came down and they actually went through
the chute and made sure everything was serviceable,
then they put it back on the vessel.

- Q. Okay, as far as you know, was that overseen by the then Flag of Mexico, and the Class which would have been Bureau Veritas?
- A. MR. MCMILLAN: Don't know if Mexico actually came on board for that or not. But BV was -- didn't have statutory authority at that time to issue a certificate. So I don't know who actually bought off on the installation, of the vessel. They were just returning it back to the original configuration.
- Q. Okay, thank you. Now I would like to bring up Exhibit E054, and we will be going over to E055. And Mr. McMillan this is the, what I believe is the initial Control Verification Examination Forms A and B. Actually, that looks like the work list, so -- E055, if I am not mistaken. There we go. Can you run down and
- let -- well actually, hold right there, and I see the team lead, you were team lead on that particular exam?
- A. MR. MCMILLAN: That is correct.
- Q. If you don't mind, Lieutenant Diaz, roll the -to the summary, and let Mr. McMillan take a quick look
  at that. Tell me about the initial, how -- the
  duration of it, how it went. And you have indicated

1 there was a 174 item worklist. I want to know, is that the norm, is it something you don't see normally, or is 2 it something you see all the time? 3

4

7

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

Α. MR. MCMILLAN: On -- when you get a ship that's been in service, it's not uncommon to get that 5 many. Usually a new construction, they are getting, 6 they are getting, the shipyard is getting very good on this, we usually don't see very big work lists. 8

I'd say when I first started doing control verification, I've been doing this for a while, we used to write a lot of worklists.

- Okay, so I see an entry for, it looks like a three day visit to the ship, 10-13, May 2011. So the notes would represent what took place that particular time period?
- MR. MCMILLAN: Yeah, just -- it is easier for me to read it down here. Yeah, we did initially three days.
- If you look down to that section of notes, there is an area I want to, two areas I wanted to talk about. The note that you entered on the cargo hold drencher system, and also on the structural fire protection notes.

And with the structural fire protection, specifically what you had there at the time and the deck two cargo area with the A60 structural fire protection, or the A60 insulation.

- A. MR. MCMILLAN: Okay, during plan review it was determined that the vessel was going to have to install structural fire protection in the cargo holds. And they were in the process of installing the structural fire protection while we were doing the ICV. And this is actually took them a while to install all this, this structural fire protection. So we knew, going into the control verification that they were installing this.
  - Q. All right, and the cargo hold drencher system?
  - A. MR. MCMILLAN: Let's see -- cargo hold --
- Q. Specifically the hold piping, and clearing clogged nozzle devices.
- A. MR. MCMILLAN: Yeah, during the ICV we actually had them energize all the drencher systems, and we found split pipes, holes in the pipes, and also a lot of the heads were clogged because of the rust in the system.

So it took them a while to fix all that piping. And even after that, they still had a lot of rust in the system because at that time they were running salt water through the system. And it is just like pouring acid on rust when you put salt water on it.

Q. Okay, thank you. And Lieutenant would you scroll to the bottom of that summary, I want to make sure I got all my questions. Let's see -- all right thank you.

Bring up Exhibit E050. And what I'm looking at is a Sector San Juan letter P212-11, dated May 19<sup>th</sup>, 2011. If you don't mind Lieutenant, roll up so I can see who signed that.

Signed by Commander Berliner the Chief, previous Chief of the Preventions Department. Mr. McMillan would you take a look at that and tell me what you recall from that particular, why that letter was generated?

A. MR. MCMILLAN: At that time they were -- they were doing repairs, but every time they did repairs and we tested we found more rust getting into the nozzles. So what we were trying to do is, motivate them to do some permanent fixes to it. And they were looking at several different things. They were talking about coming in and chemically cleaning the pipes.

And finally what they started doing is running fresh water through the system. After they got all the leaks and splits in the pipe fixed. Then they -- which made it a lot better. So ...

Q. And I didn't add the emphasis on that second

- sentence, it was provided to me in that form. But
- 2 | there is a sentence in there. (Reads) "The system did
- 3 | not operate properly when tested for the third time
- 4 | since identifying problems with the system during the
- 5 | initial control verification examination process".
- 6 And then it goes further, and states a couple lines
- 7 down that, "It looks to me as if the first I saw were
- 8 | the Sector San Juan had warned of a potential IMO
- 9 detention should there be a fourth failure of that
- 10 | system". Am I interpreting that letter correct?
- 11 A. MR. MCMILLAN: That's correct.
- 12 Q. Were you around when the Commander, previous
- 13 | Commander, Commander Berliner issued that letter?
- 14 A. MR. MCMILLAN: Yes, I was.
- 15 Q. Do you know why he went out with the warning
- 16 to the Company about potential detention?
- 17 A. MR. MCMILLAN: That was actually, this
- 18 actually was drafted by Lieutenant Commander Louis
- 19 | Porales, which was our Chief of Inspections at that
- 20 time.
- 21 Q. Okay.
- 22 A. MR. MCMILLAN: And ah, because every time they
- 23 | fixed it, that said they fixed it and we tested it,
- 24 | then we had additional problems. That's the reason
- 25 | that he went that way. Should we have detained at the

- 1 -- during the initial? We probably should have at that 2 time.
- The philosophy changed a little bit over time

  with passenger ships and detentions. So now we are -
  if that ship had come in to port today we would have

  detained it. Because they were issued a Passenger Ship

  Safety Certificate saying that everything was good.
  - Q. Okay and you used the term they, who were you referring to when you when you said they? You said they said they fixed it.

- A. MR. MCMILLAN: The Company, actually Alan Bull (phonetic), which was their representative at the time. He is the one that was on board overseeing all these repairs and getting the ship through the initial control verification process.
- Q. Okay, and company, you are referring to Baja Ferries?
  - A. MR. MCMILLAN: Baja Ferries, yes.
  - Q. Thank you. I want to close out the initial, and I'd like to bring up Exhibit E062. That's not the correct one, sorry. I'm looking for MISLE ID # 4028641, there we go, it looks like E059. Okay Mr. McMillan, if you don't mind, take a quick look at the title and date on that.

25 And I believe, at this point, if I have

interpreted the data right, it looks as if this is when

Sector San Juan actually issued the first certificate

of compliance to the vessel for operation. And if you

don't mind, LT Diaz, roll down and let Mr. McMillan

take a look at that summary.

(Brief pause.)

- Q. My question is, would this be the time when the vessel actually was given permission, or given the certificate of compliance to begin operating as a passenger carrying RORO versus just a cargo only RORO?
- A. MR. MCMILLAN: Yes, that's correct. So it was on the 30<sup>th</sup> of May that we actually issued the certificate of compliance.
- Q. Okay, and on that, in that summary, the last sentence, "Vessel will be boarded on a quarterly basis to conduct periodic certificate of compliance, certificate of" -- excuse me, "Vessel examinations, control vessel examinations", CVE's. That, how was that communicated to the company reps at that time? Do you recall? Do you know if it was?
- A. MR. MCMILLAN: Yes, it was, we actually told them that we were going to do this during the boarding.
- Q. All right, so what I'm looking at here, this looks like it's out of the Coast Guard database, is there a form on the ship that is also completed for the

1 ship?

9

18

19

20

21

22

- MR. MCMILLAN: We issue the Certificate of Α. 2 3 Compliance?
  - Ο. Um-hmm.
- 5 Α. MR. MCMILLAN: And I don't know if we actually wrote that on there, or if we just verbally told them. 6 I think it was just verbal about -- I'd have to look 7 actually look at that COC, and see if it actually was 8
- written there. It should be scanned in the system. Okay, were you on board when the COC was 10
- issued to the ship? 11
- Α. MR. MCMILLAN: Yes, I was. 12
- 13 Do you recall any comments or feedback from either the crew at that time, or any of the company 14 reps, or the flag -- excuse me the classification 15 society reps. If they were on board regarding the ship 16 17 being placed on a quarterly inspection schedule?
  - Α. MR. MCMILLAN: No, they, they just accepted it.
  - Q. Okay, thank you. Commander Capelli, I would like to get up into the 2014 examination, so I'm going to need another, probably forty minutes. I don't know where you are break wise, are we okay to keep going?
- 24 MS. PRICE: You okay?
- 25 MR. MCMILLAN: I'd like to take a few minutes,

- 1 please.
- CDR CAPELLI: Okay, the time is 1045, we will
- 3 | now recess.
- 4 (Whereupon a brief recess was taken.)
- 5 CDR CAPELLI: Good morning the time is 1103
- 6 | the hearing will now reconvene. We'd like to remind
- 7 | the witnesses that you are still under oath. And we
- 8 | are going to continue with questions from Mr. Larry
- 9 Bowling.
- 10 MR. BOWLING:
- 11 Q. Thank you. And Mr. McMillan before we go into
- 12 | the 2014 series of Port State Control Examinations, I'd
- 13 | like to look at; I want to go back to 2011 on one
- 14 | topic. You mentioned around September of 2011 the team
- 15 | at Sector San Juan became aware of; I think you used
- 16 | the term unauthorized jewelry shop. Can you build on
- 17 | that a little bit and when you used the term
- 18 unauthorized; just explain what you meant by that,
- 19 please?
- 20 A. MR. MCMILLAN: What I mean by unauthorized,
- 21 during the plan review they had a, it was identified,
- 22 | that jewelry shop was identified as a room in room.
- 23 Which, there was escape requirements that, in SOLAS
- 24 | that you have to be able to depart a space to a safe
- 25 | space. So if a room in room, if you have a fire in the

- space and they leave, they leave that spot they are not in a fire safe place.
- Q. Okay, thank you. What I'd like to do is step

  up, from that timeframe up into the 2014 timeframe with

  Caribbean Fantasy. And I'd like to bring up Exhibit

  E052, and let the witness take a look at -- I believe

  that's the right one, Form A. And scroll down to the

  Port State Control Inspection Form B.

And what I'd like to do is look at some of these deficiencies that were written here, and, at least according to my records, I believe this particular Form captures the, some of the events you described earlier, with a fire in their transitional power, battery bank.

And, if we can go look at that first deficiency, and if you don't mind, tell me a little bit about that.

- A. MR. MCMILLAN: Okay, the transitional power —
  let me read this. Okay, when they had the fire in the
  transitional battery bank, it also burnt the
  switchboard for the transitional light. So that, the
  transitional load, loads, I should say. So that's,
  that's why we wrote this one, because we identified the
  places that were not working at that time.
  - Q. Okay, and if we could scroll on down, maybe

reduce that down to back to maybe 125% or something,
and go to Deficiency Number Two. And at that point, I
guess the Port State Control team, it looks like they
documented, "The emergency transitional source of power
failed to supply certain circuits", can you tell me a
little bit about that?

- A. MR. MCMILLAN: All these circuits are required to be on transitional power with a switchover. So the way transitional power works is, usually you have, I want to say thirty minutes of power to switch over, so, in case something happened to the machinery on board. That the electrical generating machine we have time between the starting up the generators, if there is a problem to the time, how do I say this, gives you thirty minutes.
- So, and that thirty minutes is based on how long it takes to abandon ship. And when you look back to the regulations, because the regulations require thirty minutes to abandon, completely abandon ship.
- Q. Okay, thank you. And the note there on the bottom before you get into the signature blocks, it says, "To be completed prior to carrying passengers", why would that note be entered on that particular Form B?
  - A. MR. MCMILLAN: I am trying to remember --

because you have to have transitional power is a requirement on passenger ships, so you need that.

Then on cargo ships, there are certain circuits that need to be on transitional. But for passengers to get out of the -- for them to safely get out of the ship, there is emergency lighting and stuff that has to be on transitional power.

- Q. Okay, and then on that deficiency, over in the right hand column, there is a code, 17, and then AC, and I think it is better explained down on the bottom of that particular form, but tell me about this coding to the right with regards to how that -- and the chart you can see here at the bottom of page two how that is, how that works.
- A. MR. MCMILLAN: Okay, 17 prior rectified deficiencies, prior to the vessel departing port. And the A is for the satisfaction of the RO, which is the Recognized Organization, and C is to the Coast Guard. So to both.
- Q. Okay, so in that particular deficiency, then the Port State Control officer would be saying, that has to be rectified prior to departure, and then there has to be some involvement from the Class, or the recognized organization, and Coast Guard be signed off on before it is clear, correct?

- A. MR. MCMILLAN: That is correct.
- Q. Okay, thank you. Lieutenant, if you don't
- 3 | mind, run on down through the other pages, I want to
- 4 | see if the printed summary is there. Go to the Exhibit
- 5 | List and see if you can bring up MISLE ID 4922 -- or
- 6 | 3403, I believe that was the one we were in. Tell you
- 7 | what, Mr. McMillan, do you know how that particular
- 8 | issue was resolved with the -- how the damage from that
- 9 | fire in the battery bank was corrected?
- 10 A. MR. MCMILLAN: They didn't correct it. The
- 11 | vessel was -- at that time they didn't correct it.
- 12 What happened is, they went through, verified that the
- 13 emergent generator circuits were all working. And RINA
- 14 actually came on board; they sent one of their
- 15 | electrical specialists to come down to evaluate the
- 16 system.

25

- 17 Q. And we have it as an Exhibit, I just lost the
- 18 | number. But, there was another Port State Control Form
- 19 where, the Port State Control Team at Sector San Juan
- 20 | had indicated right after that particular exam in 2014
- 21 | that the vessel -- I want to say June, around June  $5^{th}$ ,
- 22 | 2014, the vessel proceeded to dry-dock for repair, and
- 23 | it was under a spec dispensation from Panama. Are you
- 24 | familiar with that?
  - A. MR. MCMILLAN: I think that was due to the

- 1 | transitional power. The -- they were given -- since
- 2 | they were going to dry-dock in short order, they
- 3 | allowed them to operate as a cargo ship, without the
- 4 transitional power; they didn't have passengers on
- 5 board.
- And when they went to dry-dock, that's where
- 7 | they changed the structural fire protection, they
- 8 | separated the emergent generator room from the
- 9 transitional batteries, they actually put an A60
- 10 | bulkhead in. Which is an A60 -- A60 insulation, and an
- 11 A60 door to that space. And they also installed a
- 12 | brand new transitional switchboard.
- 13 Q. Okay, thank you. And I believe we are now
- 14 | at Exhibit E056, and this is Port State Control Forms A
- 15 and B, and that is from the August 20<sup>th</sup> -- Lieutenant,
- 16 | if you don't mind roll up to these, so the witness can
- 17 | see the -- that's MISLE activity number 4958273, and
- 18 the date of the inspection is 20<sup>th</sup> of August, 2014. And
- 19 at this point, if I am not mistaken, this was the first
- 20 formal detention that Sector San Juan put toward the
- 21 | vessel, am I correct?
- 22 A. MR. MCMILLAN: That's correct.
- Q. And can we go down and look at the Form B, and
- 24 | I want to see these two deficiencies. Now, Deficiency
- 25 | Number 1, and Deficiency Number 2, this code we just

- 1 talked about, it is showing now, 30.C, can you tell me
- what that, what that's telling the panel here?
- A. MR. MCMILLAN: Ship's detained. And the A
- 4 | would be the satisfaction of the RO.
- Okay, and back up to the two deficiencies that
- 6 | warranted the formal detention, tell me about that
- 7 | first one.
- 8 A. MR. MCMILLAN: I don't see a number.
- 9 Q. I'll read it. It talks about, "The
- 10 | transitional source for emergency power" --
- 11 A. MR. MCMILLAN: Um-hmm.
- 12 Q. -- "Shall be arranged to supply automatically,
- in the event of power failure. The batteries were
- 14 | found to be fully discharged, with the charger in the
- off position, and enabled to assume the transitional
- 16 loads and lights".
- A. MR. MCMILLAN: Yeah, that's correct. Okay, so
- 18 | 30C -- back up. That's to the satisfaction of the
- 19 | Coast Guard.
- Q. Okay, but the deficiency itself.
- 21 A. MR. MCMILLAN: Um-hmm.
- 22 Q. Tell me a little bit about that, what was the
- 23 | situation on the boat?
- A. MR. MCMILLAN: We, actually we, when we dug
- 25 down into it a little bit, we found out that the

- electrician had actually secured the battery charger,
  and the batteries had discharged at that point. So
  they, they actually had to, to get this going again, I
  believe that they actually had to replace the
  batteries. Because once you get a battery that's been
  dead for too long, you may not be able to get it to
  take a charge again. I think that was the -- in this
  - Q. Okay and then the second deficiency, on this particular detention?

case that is what was going on.

A. MR. MCMILLAN: The second deficiency was for the automatic sprinkler system. There is a head tank that they have to have, and it is — in this one, was where we had run into problems over time with the vessel, either the tank was empty, or was completely full, and the requirement is that you have to have enough capacity for one minute.

So when, the way this system is designed is, with the tank half full, and certain pressure on the tank that allows you to have that one minute of output of the pump.

Q. Okay, thank you. And at this particular time which would have been 2014, August, 2014 the vessel, what was the vessel Flag, and who was it being Classed by at that time?

- A. MR. MCMILLAN: Panama flag and it was RINA.
- Q. Okay, and do you recall any actions taken as a result of this Port State Control action, detention of the ship, taken by either the flag of Panama or the

RINA as either the RO or the classification society?

- A. MR. MCMILLAN: I'm not sure what they did internally.
- 8 Q. All right do you --

1

5

12

13

14

15

16

17

18

- 9 A. MR. MCMILLAN: But we actually recommended, I
  10 think an ISM audit with these -- with these two
  11 deficiencies, if I am not mistaken.
  - Q. Okay, are you aware of any time around this period where Flag or RINA would have rescinded any of the statutory documents that allow the vessel to operate? And I say, pulled the Class documents, to basically remove the vessel from service until these items were corrected?
  - A. MR. MCMILLAN: On this, because of the -- well not because of this.
- 20 Q. Okay.
- A. MR. MCMILLAN: But when they had the fire in
  the transitional power, they actually issued them a
  provisional, or Short-Term Passenger Ship Safety

  Certificate restricting them.
- 25 Q. Okay. But for this particular detention that

1 Passenger Ship Safety Certificate remained in full force that was issued by RINA? 2

5

13

14

15

16

17

18

19

20

21

22

23

24

25

- MR. MCMILLAN: I believe it did, because they, 3 4 they fixed it in port, then they were cleared to go again.
- Okay, thank you. I want to bring up Exhibit 6 Q. E060, and this was a January 21<sup>st</sup>, 2015 exam. And 7 apparently I have my numbers wrong. I'm looking for 8 MISLE activity 505-6168. This is another examination, 9 if I'm not mistaken, it looks like it is January, 2015, 10 by Sector San Juan, it's a quarterly it looks like, 11 MISLE activity number 505-6168. 12

And I want to run down and look at one of the deficiencies the Port State Control Team found regarding the Voyage Data Recorder. There it is, Item Number 3, tell me what you recall about that.

MR. MCMILLAN: Okay, during that exam, that Α. was a quarterly exam, we ah -- the team that was doing -- team one, they noticed when they were up on the bridge, they were looking at the VDR, they noticed that there was an alarm going on, and they asked about it. And they found out that it wasn't working correctly.

I don't remember exactly what they found during that -- I think it was documented in the narrative.

(Brief pause.)

1

16

17

18

19

20

21

22

23

24

- A. MR. MCMILLAN: Okay, there are just, I'm not sure exactly all the problems with it, but I know that one of the things, it was not syncing with GPS, and there were some other error codes, but I don't, I don't remember what they were at that time, because I wasn't the person who was doing team one at that time.
- Q. Okay, thank you. And is -- from the

  standpoint of a voyage data recorder, are you aware of

  any requirements from -- in SOLAS, where those systems

  have to be verified or validated by service

  technicians?
- A. MR. MCMILLAN: They are supposed to have an annual servicing done, to make sure they are operating correctly.
  - Q. Okay, and when those are completed, tell me how those are documented.
  - A. MR. MCMILLAN: The Company doing the servicing, they actually issue a servicing report. And that's -- that's one of the things that we look at when we are doing our exams.
    - Q. Okay, and so that it is a document that would be examined by the Coast Guard Port State Control?
  - A. MR. MCMILLAN: Yes, we don't, we don't actually record it, but we actually look for it. We --

- there is several pieces of navigation equipment that we
- 2 look at like the AIS, the EPERB, and all those, we look
- 3 for servicing reports.
- Q. Okay, thank you. Go to, hopefully, Exhibit
- 5 | E058. This is the, again, Port State Control, report
- 6 of inspection form A, it is related to MISLE activity
- 7 | 5746255, and the date of that particular inspection was
- 8 a 21, October, 2015.
- 9 And I look at the exam type; it looks as if it
- 10 is another quarterly there. And if we could roll,
- 11 | scroll on down to Form B. I want to talk about the
- 12 | first three deficiencies, tell me what you recall about
- 13 those. Start with deficiency number one, please.
- 14 A. MR. MCMILLAN: So the first one was due to
- 15 | engine room cleanliness, we found a lot of oil,
- 16 | slippery deck plates. And we also found oil in the --
- 17 | excessive oil in the bilges.
- 18 Q. And what's the concern there?
- 19 A. MR. MCMILLAN: Fire.
- 20 Q. Okay.
- 21 A. MR. MCMILLAN: And there is actually a MSC
- 22 Resolution that talks about, it is someone's
- 23 responsibility to keep the engine room as clean as
- 24 possible.
- 25 Q. Okay, and item number two, or deficiency

1 | number two, I should say.

- A. MR. MCMILLAN: Okay, yeah the third engineer didn't have the correct endorsements for his credentials.
  - Q. Okay, and where is that requirement? If you don't mind, tell me a little bit about the basis for that.
- A. MR. MCMILLAN: That's -- there is two parts to that. There is STCW, that's the actual, what training that mariner is supposed to get. And the other one is SOLAS, so the vessel is, has a safe manning certificate and that they are properly manned in accordance with that.
  - Q. Okay, and then Item Number 3, very similar, it looks like to the Item Number 2, but for the second engineer?
  - A. MR. MCMILLAN: That's correct. He was missing some special training for being on RORO's. So there is special training requirements under STCW. And we tied those back to their -- both of those back to their safety management.
  - Q. Okay, and that's where I wanted to -- my next question was, when you were talking about, you were giving us the rundown of the Port State Control effort by Sector San Juan Team. You mentioned on the -- this

- second detention, that it was tied into three
- 2 | international documents, you indicated STCW, if I am
- 3 not mistaken.
- 4 You also indicated the International Safety
- 5 | Management Code, and you also mentioned the Safety of
- 6 | Life at Sea Treaty. Were those three statutory
- 7 | requirements what you were referring to when you
- 8 | mentioned or you talked about this particular
- 9 detention?
- 10 A. MR. MCMILLAN: Ah, yes.
- 11 Q. Okay. And if you don't mind, let's roll on
- 12 down, I want -- I think there is a deficiency written
- 13 here, where the Port State Control Team reached out to
- 14 the classification society, specifically regarding a
- 15 | request for an IMS, or a Safety Management System
- 16 audit.
- 17 A. MR. MCMILLAN: Yes, we did request an audit.
- 18 Q. Right here, Item Number 21, and I am going to
- 19 read that on the record, and I want to ask you to
- 20 explain why the team put this deficiency. It looks
- 21 | like your signature is at the bottom of that as the
- 22 | Port State Control Officer.
- Item 20, or deficiency number 21, (Reading)
- 24 | "Based upon observations on board as well as with
- 25 | general lack of upkeep and maintenance of the vessel,

- enough objective evidence of non-conformities have been discovered to show the vessel is not fully implementing it's SMS", or safety management system.
- "An external International Safety Management"

  Code, I injected code, but, "An ISM audit is

  recommended". Now, can you give me some more details

  on that? Particularly for those that are not real

  versed in the ISM Code?
- MR. MCMILLAN: Okay, under the ISM code, there 9 are certain things that the company has to have in 10 their ISM. It is -- I'd have to actually go back and 11 look at the -- we have a NAVIC on it, that tells us 12 13 what we are supposed to be looking at. And, part of that NAVIC is we can only recommend an audit as a Port 14 State. The flag state actually has to be the one to 15 approve doing the audit. 16

17

18

19

20

21

22

23

24

- So, if they didn't want to do an audit they don't have to. But in this case, they actually did an audit, I do believe, because partially I would have cleared this. But I don't think an audit was done immediately. It takes a while do those, and set them up, and everything. So I think it was done at a later date.
- Q. Okay, thank you. And you used the acronym NAVIC, would that be Navigation Vessel Inspection

## Circular?

- A. MR. MCMILLAN: That is correct.
- Q. And do you know the number, off the top of your head?
  - A. MR. MCMILLAN: 04-05.
- Q. I copied NAVIC 04-05?
  - A. MR. MCMILLAN: That is correct.
- Q. Thank you very much. On this particular
  examination, we talked with the Sector Commander
  earlier, in this event, and he had indicated, at some
  point in time, he actually made a visit to the ship.

  Do you know if it was after this particular Port State
  - A. MR. MCMILLAN: It was during this detention he came to the ship. We did the detention the day -- started the inspection the day before, and we had to finish the next day. And both Captain Warren and I think it was Captain Flaherty, at that time, came on board to see what was going on.

Control Examination, or as a result of this detention?

Q. Okay, thank you. As a result of this particular detention, which was the second for Sector San Juan, do you know -- were there any discussions with the flag of Panama, RINA, or any discussions with Baja Ferries, or American Cruise Ferries regarding the vessel's compliance at that point? Do you recall any

communications?

- A. MR. MCMILLAN: If it was it was, it was done by the chief of inspections, I don't think I was involved with any of those discussions --
- Q. Okay.
- A. MR. MCMILLAN: -- if they happened.
- Q. All right, thank you. I want to get to a, item number E060. And this is the most recent detention of the vessel in the Port of Gibraltar. And I realize that this is not Sector San Juan. But, with the (inaudible word), have you seen anything from Port of Gibraltar, the Port State Control Authorities that were there, regarding their detention?
  - A. MR. MCMILLAN: No. I just went to Equasis, which is their database, and that's how I found out about the detention.
  - Q. Okay, thank you. Has the -- you or the previous chief of preventions, and -- or the current chief of preventions, did any -- are you aware of any discussions prior to the fire on the -- April, or August the 17th, between the Coast Guard Port State Control officials and RINA, and/or Baja Ferries about the vessel's compliance, and the compliance record?
  - A. CDR ESPINOSA-YOUNG: I personally, did not have any engagement directly with the Panamanians, or

with RINA. My engagement, specifically with the Caribbean Fantasy was the transition schedule with regards to bringing her back from dry-dock, and the correspondence with Baja Ferries for when they were going to arrive.

And the decision, based on their delay of their detention, wanting them to come directly to San Juan to conduct the examination without the additional crewmembers on board to do -- the housekeeping, which is their primary watch, according to the station bill, with a lot of the passenger issues. For which, I outright denied, and said, you -- we are not going to conduct your COC Examination without the majority of your crewmember.

So that was -- that was my first engagement with the company other than, you know, you know, past email discussions while the vessel was coming back.

And then attesting to any repair, or additions that were going to be taking place, or upgrades that were going to be taking place in Tunisia. So we were making sure that by the time the vessel came back from their dry-dock we weren't going to have to go through - plan review of items that they were going to be installing prior to our arrival.

So we wanted to make sure that, you know, if

there was any installation, additions, any upgrades,

any restructuring of, you know, passenger areas, or

some of the locations on board the ship, we wanted to

make sure that plan review would have been done prior

to the vessel, our marine inspectors going on board to

-- with that COC exam.

Q. Okay thank you, Mr. McMillan?

A. MR. MCMILLAN: After the first detention, I'm not sure exactly when it was. RINA did come visit our chief of inspections, and they discussed the vessel. I mean, they had concerns because they were getting possible points for Port State Control targeting.

So that's when we agreed, that if we were going to do an exam, we would call and let them know that we were doing it, so that they could actually send someone down.

And I do believe as part of that discussion, they said that they were going to do some enhanced oversight on the Caribbean Fantasy. And I'm not sure exactly what that meant, but I think they were doing some additional type survey work.

Q. Okay, thank you. We will try and explore that -- I think we have a RINA representative later in our schedule.

Commander Capelli, I have nothing further from

1	a Port State Control standpoint. The August 9 <sup>th</sup> , 2016
2	examination, we will explore this afternoon with CWO
3	Roth who was lead on that.
4	But later, I would like to talk about the
5	August the 17th response with chief of preventions,
6	because I understand she played a role in the Unified
7	Command, and the ICS at that point. But I relinquish
8	the floor at this point, thank you, thank you both.
9	WITNESSES
10	COMMANDER JANET ESPINO-YOUNG
11	MR. JERRY McMILLAN
12	EXAMINATION
13	BY MR. TUCKER:
14	Q. Good morning, my name is Adam Tucker; I'm with
15	the National Transportation Safety Board. A few
16	follow-up questions. The first question is, Commander,
17	you had mentioned earlier, just, I had not heard the
18	term before, you mentioned priority vessels. And I
19	believe it was referenced 1, 2, and 3. And then
20	further down I also heard P1. Is that the same think,
21	and can you tell me what that is?
22	A. CDR ESPINOSA-YOUNG: Yes, it is the same
23	thing Co Drienity was know for short they go
	thing. So, Priority, you know, for short they go
24	through Priority 1, and it would be P1, P2, P3, or Non-

V-115

1 | that we undergo through our Port State Control program,

- 2 | to identify vessels at the higher risk category for
- 3 examination.
- 4 So, based on the history of the vessel,
- 5 | owner/operator, recognized organization, classification
- 6 | society, history, operational controls, we run a matrix
- 7 of numbers that generates the prioritization for
- 8 examination.
- 9 So Priority 1's are for safety. And there is
- 10 | the ISPS caveat that also is for the security side. So
- 11 | the same Class -- you know standard applies to those.
- 12 And then the vessel gets, based on that, an exam
- 13 | conducted.
- So Priority 1's are conducted offshore, based
- on the nature of what triggered. Usually it is a
- 16 previous detention, ratio of a particular flag
- 17 | identified of high incidents of detentions,
- owner/operators, depending on, you know, the history of
- 19 them. So all that feeds into the selection of those
- 20 vessels.
- 21 Q. Thank you.
- 22 A. CDR ESPINOSA-YOUNG: Um-hmm.
- Q. And just so I understand, the -- it might be
- 24 | for Mr. McMillan, it was mentioned that Caribbean
- 25 | Fantasy was a P1, Priority 1 vessel, is that correct?

A. MR. MCMILLAN: It was for -- after the detention, because, you know, part of that criteria if that you haven't had any serious deficiencies, and points that they received, they were Priority 1.

- Q. Thank you. The other question that I have, perhaps for Mr. McMillan again, is during your time on board performing inspections, do you recall ever, any type of test of the ship's water mist system in the engine room?
- A. MR. MCMILLAN: That, the water mist was installed in the shipyard, and I'd have to defer to Mr. Roth on that.
- Q. Okay, thank you. The other question I have is with respect to Port State Control. I understand the Caribbean Fantasy is a starboard side ship, meaning that the ramps -- and it is configured for cargo operations on the starboard side. How does Port State Control address lowering and launching of survival craft on the, basically, the dock side of the ship, if the ship is never alongside port side?
- A. MR. MCMILLAN: Our TTP, which is Tactics and Procedures, all that it says is that we, on the inboard side we have to test the engines, and we just do a visual inspection of the davit system. And the only other thing we do is, we actually review their training

- records and see that they actually -- that they are
- 2 logging that they are lowering it to the water like
- 3 | they are supposed to. And that is about as far as we
- 4 go.
- In the past, I want to say years ago, we used
- 6 | to take videos, but that is kind of, with the TTP's and
- 7 | stuff we have -- we are just following what they say to
- 8 do. It would probably be a good idea to be testing
- 9 those, but we are not required to do it for Port State.
- 10 Q. Thank you. And Mr. McMillan, were you on
- 11 | board during the last inspection, the August 2016
- 12 inspection?
- 13 A. MR. MCMILLAN: Yes, I was.
- 14 Q. What was your role on board?
- 15 A. MR. MCMILLAN: I was filling the roles of
- 16 | teams two and three, which is the passenger decks. And
- 17 | since this ship is -- doesn't have too many passenger
- 18 decks, I also took the cargo decks also.
- 19 Q. So during the crew drill, because you are
- 20 | covering passenger decks, do you assess English
- 21 proficiency of the crewmembers at that time?
- 22 A. MR. MCMILLAN: Whatever the working language
- 23 of the crew is. In this case, it was English, the
- 24 | people I was interacting with spoke English well
- enough.

- Q. Thank you. Did you witness on that August 16<sup>th</sup> inspection the operation of the ship's drencher system?
  - A. MR. MCMILLAN: Yes, I did.
- Q. And what did you notice at that time? What do you recall?
- A. MR. MCMILLAN: When we were testing it, I

  tested two zones, and I forget the zone number. But

  the forward zone, there was 21 sprinkler -- drencher

  heads missing. So the water was going straight down,

  and I actually took a video of that and provided it to

  the Mr. Diaz.
  - Q. And by the time you had noticed that, was that issued rectified before you left the vessel?
- A. MR. MCMILLAN: Yes, it was, they had new heads on board and installed them.
- 17 Q. Okay.

4

13

14

18

19

20

21

22

23

24

25

A. MR. MCMILLAN: And that was, like I said, before, when they were in Tunisia, they had two hundred and fifty of them stolen. And they were -- they had them all -- all of them taken out so they could clean out the pipes. And then they had to order new ones to install those, and evidentially they missed that, that section. Because it was, that section was right over the forward ramp going up to C Deck from B Deck to C

1 Deck. Thank you, and that is all the questions I Q. 2 have, thank you very much. 3 4 WITNESSES 5 COMMANDER JANET ESPINO-YOUNG MR. JERRY McMILLAN 6 7 **EXAMINATION** BY CDR CAPELLI: 8 9 Before we switch topics, I want to ask one question. Where are all the Form B's sent that you 10 fill out? 11 MR. MCMILLAN: For -- if they are a detention 12 Α. 13 we actually put them into MISLE, as a requirement for detention because it, that has to go up to, all the way 14 to headquarters. If not, then the Form B's are 15 actually kept in a local file, filing cabinet. 16 CDR CAPELLI: That's all the questions I 17 have. Panama regarding the inspections topics, do you 18 19 have any questions? 20 MR. ARENAS: No, I don't have any questions. 21 But I want to add something to the record. In those two ships that was -- were show, before, the Commander 22 and the Grey Shark, the Commander is already cancelled 23

for our flag, and the Grey Shark was done, the ISM

safety inspection this past December 2015, and our --

24

1	now I don't have the preliminary report of the
2	deficiencies, but they showed deficiencies, that audit.
3	So that's all.
4	CDR CAPELLI: Okay, thank you. Baja Ferries
5	do you have any questions for the witness?
6	MR. BLASINI: No sir, no questions.
7	CDR CAPELLI: Okay, at this time, we are going
8	to switch topics to the response phase. Mr. Larry
9	Bowling?
10	WITNESSES
11	COMMANDER JANET ESPINO-YOUNG
12	MR. JERRY McMILLAN
12	TURNING TON
13	EXAMINATION
13	BY MR. BOWLING:
14	BY MR. BOWLING:
14 15	BY MR. BOWLING: Q. Thank you. Commander, on the day of the
14 15 16	BY MR. BOWLING:  Q. Thank you. Commander, on the day of the event, just walk me through what you did once you heard
14 15 16 17	BY MR. BOWLING:  Q. Thank you. Commander, on the day of the event, just walk me through what you did once you heard of the fire aboard the Caribbean Fantasy, and when I
14 15 16 17 18	BY MR. BOWLING:  Q. Thank you. Commander, on the day of the event, just walk me through what you did once you heard of the fire aboard the Caribbean Fantasy, and when I say the day of the event, August 17 <sup>th</sup> .
14 15 16 17 18	BY MR. BOWLING:  Q. Thank you. Commander, on the day of the event, just walk me through what you did once you heard of the fire aboard the Caribbean Fantasy, and when I say the day of the event, August 17 <sup>th</sup> .  A. CDR ESPINOSA-YOUNG: I was notified by our
14 15 16 17 18 19 20	BY MR. BOWLING:  Q. Thank you. Commander, on the day of the event, just walk me through what you did once you heard of the fire aboard the Caribbean Fantasy, and when I say the day of the event, August 17 <sup>th</sup> .  A. CDR ESPINOSA-YOUNG: I was notified by our command center over my landline, reporting that they
14 15 16 17 18 19 20 21	BY MR. BOWLING:  Q. Thank you. Commander, on the day of the event, just walk me through what you did once you heard of the fire aboard the Caribbean Fantasy, and when I say the day of the event, August 17 <sup>th</sup> .  A. CDR ESPINOSA-YOUNG: I was notified by our command center over my landline, reporting that they had received a report that the Caribbean Fantasy was on
14 15 16 17 18 19 20 21 22	BY MR. BOWLING:  Q. Thank you. Commander, on the day of the event, just walk me through what you did once you heard of the fire aboard the Caribbean Fantasy, and when I say the day of the event, August 17 <sup>th</sup> .  A. CDR ESPINOSA-YOUNG: I was notified by our command center over my landline, reporting that they had received a report that the Caribbean Fantasy was on fire. And the location of where the vessel was

our inspections bullpen, notified the chief of inspections and grabbed some additional resources, and bodies to take them up to the command center, based on the fact that this was an emergent situation, to alleviate and assist the command center with the number of phone calls that were going to be coming in through the command center, and make sure that we can handle the volume. 

So I'd say about a handful of us went to, up to the command center an tried to get the updated situational awareness, and you know, assisted primarily in the, you know, engagement directly with, you know, conversations with Baja Ferries in their initial reporting.

And then we did receive a call from the local rep, as Mr. Mark Payne, identifying himself as a representative, subcontractor for Ardent Global, which is the -- their identified salver (sic), marine firefighter, towing company. As I identified in their non-tank vessel response plan. And had said that their non-tank vessel response plan protocols were being activated at that time.

That was about 0800. So, the initial notification to me was about 0752, in the morning, and by the time I went up to the command center, Mr. Mark

- 1 Payne, that works for San Juan Towing and Marine
- 2 | Services, he is the marine manager, had identified
- 3 | himself as a subcontractor and local representative for
- 4 Ardent Global.
- 5 So most of our work was to reach out to
- 6 | Headquarters. I also spoke with our chief of
- 7 | inspections to obtain the non-tank vessel response
- 8 | plan, itself. So we had some detailed information, and
- 9 so that we could reaching out in communications, and
- 10 also handling assist vessels, you know, towing vessels
- 11 | that were, you know, calling in to the command center
- 12 | in order to render assistance, whether it is through
- 13 active firefighting, you know, efforts, or as Good Sam
- 14 | vessels assisting in the area.
- 15 So we manage most of the outflow at that point
- 16 | in time, and handling who was going to start taking the
- 17 responsibility, what assets were going to be starting
- 18 to be deployed by the company through their non-tank
- 19 | vessel response provider. At which time the direct
- 20 representative as outlined by the company, Ardent
- 21 | Global, Ms. Garcia, Rebecca Garcia out of Ft.
- 22 | Lauderdale contacted us.
- 23 And said in that time, National Response
- 24 | Corporation was their oil spill removal organization as
- 25 | identified by the plan. They had local representation

here, in San Juan. The qualified individual was identified as Witt O'Brien. And it was outlined as the emergency responder was going to be Mr. Jason Bergeron, who represented Baja Ferries throughout the Incident Command Post, and Unified Command.

So, during those executions, during the emergency lifesaving, out initial reaction as well was to identify the location of, you know, for the landing sites. So during discussions up in the command center and the, receiving information from CBP that initially wanted to change the landing site location over to Pan American Dock, so it was an active discussion via phone conversations that they wanted to direct passenger flow and off-load to that location.

We made a determination to send Mr. Morgado to the scene to ensure that the mass rescue operations plan, and the predesignated landing site was adhered to in order to ensure that passengers were going to be able to be safely offloaded either from a lifeboat or a life raft, or any of the Good Samaritan vessels that were going to be operating the persons ashore.

So, he was sent in the field in order to ensure organization, and adherence to those protocols for, you know, for the safety of the passengers taken to that location.

Once the emergent search and rescue, recovery, then we were, you know, obviously running parallel tracks, you know, addressing the issue of the vessel now being, you know, adrift, and you know, potentially, you know, heading toward shore. You know the order through the command center to, you know, directing the captain if you haven't done so to drop your anchor.

The vessel's anchor was dropped. About 1016, based on our documentation, the vessel's anchor did drag, and that was witnessed by, and confirmed by divers that did a survey of that area just for environmental purposes, and the vessel, you know, came to a rest partially grounded off of Punta Salinas, Puerto Rico.

At that time we had already engaged conversations with Mr. Mark Payne, through San Juan towing, and we had a meeting at about 10:30 that morning, 10:45 along with Mr. Paul Simpson, which was a marine surveyor, Mr. -- Captain Iglesias, which is their -- one of the captains of the towing vessels to discuss the initial assessment of the current condition of the vessel and meeting timelines.

We, at that time, you know, outlined, you know, plans to execute when the towing vessels arrived at the base, and we deployed two marine inspectors

- along with their team. The Captain, Captain Iglesias
- operating the towing vessel, Mr. Mark Payne, and Mr.
- 3 | Paul Simpson to take our marine inspectors and their
- 4 | crew to gain access to the vessel and conduct an
- 5 | initial survey assessment of the condition of the
- 6 vessel.
- 7 And that was about 1100/1130 that we arrived.
- 8 | So Chief Warrant Officer Roth and Mr. Alejandro Simms
- 9 | were the attending marine inspectors on that. They
- 10 | conducted an initial survey of, you know, of the, you
- 11 know, the number of degrees the vessel was listing.
- 12 | Just got an overall assessment, accesses, you know,
- preliminary information with regards to the current
- 14 | condition of the fire.
- 15 They were unable to access the majority of the
- 16 below decks because of heat, and they were not
- 17 | equipped. So they went, directly, really to the bridge
- 18 and took documented evidence of, you know, the
- 19 | inclinometer, the chart equipment. And then they
- 20 | produced an assessment at that time.
- 21 And we were already in consultation with
- 22 | Ardent Global's response team, their salvage masters,
- 23 | they were in transit and they arrived on island, I'd
- 24 | say that evening, you know, around eight o'clock
- 25 | timeframe, between six and eight.

So the initial team showed up from -- which was one of their naval ARC's, the salvage master. And then a contingency, I think of five marine firefighters. We were unable to place them on board due to transportation issues with the contracted helo that they had hired.

At that time we also (inaudible word) two marine inspectors on a Coast Guard helo because the vessel had no crew by this time, and the vessel continued to burn.

We were concerned with preservation of data on the voyage data recorder. So we deployed two marine inspectors, LTJG Jesse Collins, and Chief Warrant Officer Mark Philips to land on board the vessel and retrieve the data on the voyage data recorder for preservation.

And the assets on scene, I believe overnight the Richard Dixon, Coast Guard cutter Dixon remained vigilant over scene. Along with one of the contracted tugs that remained on board.

We also attempted to have one of the towing vessels in the area, and put a line on the vessel. But we were unsuccessful based on, you know, lack of crew. By that time the power -- they didn't have any power on board the vessel, so they couldn't operate the forward

- operating winch, you know, to execute that mission safely.
- 3 So the -- during this transition, we are
- 4 | moving into an incident command structure. And by the
- 5 | time the assets arrived on scene, formalized, obviously
- 6 Unified Command at the Sector in our conference room,
- 7 | which representatives of the organization were
- 8 | obviously the local commonwealth, DNR, and the
- 9 | Environmental Quality Board. Our representatives were
- 10 representing the commonwealth, the Coast Guard as the
- 11 Federal on Scene Coordinator's Representative during
- 12 | the incident, and then Witt O'Brien, you know, through
- 13 Mr. Bergeron representing Baja Ferries. And also in
- 14 | communications with Mr. Nestor Gonzales, which is the
- 15 American Ferries (sic) representative as well.
- Are we good thus far? I mean, I can continue.
- 17 Q. Yeah, I -- well no, and I appreciate it.
- A. CDR ESPINOSA-YOUNG: With more details as
- 19 | well, but ...
- Q. Let me, I'll have -- I'll want you to
- 21 | continue, because I want to get up to the point where
- 22 | at some point you and the Captain of the Port said, the
- 23 | fire is out.
- A. CDR ESPINOSA-YOUNG: Okay.
- 25 Q. But let's go back and just hit a couple

things. And with the non-tank vessel response plan, tell me that plan, and in real life, in this scenario, what is the value of that plan to not only the Coast Guard, but the ship owner/operator, and crew?

A. CDR ESPINOSA-YOUNG: It is a written plan which already has contractual agreements and assets that should be mobilized within the -- a timeframe. So, you know, in years past in a salvage, or firefighting, or an off shore event, you are dealing with a foreign owner trying to locally source assets to provide or render assistance to a vessel in distress.

Which could be in an off shore event, it could be an in shore event or at the pier, which delays the process of response, it actually hinders, if not creates a, you know, a degradation of that response effort, and potentially can have catastrophic events.

So the non-tank vessel response plan gives you a plan that is already identified, emergency procedures, notifications. It outlines resources, it outlines who is responsible for what roles, and what response times and what equipments need to be there and when.

So for an owner and an foreign entity, having a shore -- a U.S. based operator that can respond on their behalf, is you know, that is familiar with the

- language, it is also familiar with emergency responses,
  and there is no delays due to time zones or language
  barriers, it can certainly expedite, you know, the
- incident, or preventing a serious incident from happening.

forward movement of addressing a pretty serious

Q. Okay, and earlier we brought up Exhibit, one of the Exhibits, I want to say it was E013, there is no need to bring it up again, but it was a Captain of the Port Order written to the vessel and Baja Ferries for just that, the non-tank vessel response plan.

And we went through the follow-up Captain of the Port Order that, where that was rescinded or cleared. Now with that plan, is that something that is submitted locally and you and your team look at? Or is it submitted to Commandant? How does that non-tank vessel response plan get reviewed and approved or -- how does that work?

A. So it does get, it does not -- we don't receive at the local level. It is, goes directly to Headquarters on -- there is a special office that handles the vessel response plan folks. And they review, that's gets directly submitted to them, and they review the content of that plan to meet the criteria based on the Regulations.

So they go into detail, and double check and if not verifying the contractual agreements, the response time criteria. It is also to ensure that it is, you know, because it is also Captain of the Port specific, so each plan should have a geographic response. And who, if different, that person in charge should be.

So a plan can be submitted, and you normally operate in the northeast, and they are coming to San Juan, but they don't have the geographic specific, they can also be denied entry as a result of not having geographic specific, because it has to do with their assets, or contractual agreements, and their timeframe for response.

Because they could have a company that's U.S. based, but only operates in the northern region versus down in Puerto Rico, and the assets wouldn't be there to meet the criteria. So it is completely Headquarters approval on the meeting of the regulations.

- Q. Okay, thank you. And you say Headquarters, what division or program is that?
- A. CDR ESPINOSA-YOUNG: It is, I believe it is their Vessel Response Plan, and I think it is straddled in CVC, and there is a portion from it that also is CGFIC, which is facilities.

Q. Okay, thank you. You had mentioned Ardent Global, exactly what role were they playing again?

1

2

16

17

20

21

22

23

24

- A. CDR ESPINOSA-YOUNG: They were their -- the salvage and marine firefighting and emergency towing response company.
- Q. Okay, and then you mentioned NRC, or National Response Corporation, they were playing what role again?
- 9 A. CDR ESPINOSA-YOUNG: They were the oil spill removal organization.
- Q. Okay, and were they local, or were they somewhere else?
- A. CDR ESPINOSA-YOUNG: They were local, sir,
  yes.
- 15 Q. And when you say local?
  - A. CDR ESPINOSA-YOUNG: Meaning, they have assets in a centralized office here in San Juan.
- Q. Okay, and when you say assets, you know what type assets they have?
  - A. CDR ESPINOSA-YOUNG: They have everything from booming to, you know, absorbents (sounds like), to recovery vessels, they are the ones that actually mobilize in order to meet the predetermined area, contingency plan strategies for the geographic specific to protect certain environmental areas. So they have

all of the necessary requirements based on the designation as an oil spill removal company.

- Q. Okay, thank you. And then you mentioned
  another firm, Witt O'Brien, and I think you indicated
  they acted as the qualified individual, or individuals.
  What exactly is that agency or (does) that position
  call for?
  - A. CDR ESPINOSA-YOUNG: They are -- they also do a multitude of things, emergency response being one of them. But the qualified individual is really the shore based representation of Baja Ferries. And they are there to execute and be responsible for any contractual agreements they might be doing. So they are pretty much given the authority to act as Baja Ferries for any issues that require response or additional resources in managing the incident.
  - Q. Thank you, and as you were describing the events, I think you indicated around 10:15 that the anchor had been dropped from the vessel there abouts. But it had dragged -- can -- do you know from the dive surveys exactly the distance that anchor failed to hold, or how it was dragged, roughly?
  - A. CDR ESPINOSA-YOUNG: I don't recall. I remember seeing the video, I remember speaking to I think it was the -- a Danny R, that actually provided

along with NOAA, that actually dove on the vessel. But I can't recall the distance traveled.

- Q. Okay, and we explored this a little bit with the Sector Commander the other day, but with regard to the grounding, what, and how much of the hull, what portions of the hull actually grounded?
- A. CDR ESPINOSA-YOUNG: I would say a -- it was the port side, I would say the port side quarter, aft quarter of the ship, that was butt up against the shelf and it was partially grounded near, near the -- because it was actually ended up being some damage. Along the area of the -- just shy of the engine room. And so literally the port side, the port side aft quarter of the vessel was grounded, sitting on a ledge.
  - Q. Okay, and since the incident, has the company or any of the other salvage organizations provided to Sector San Juan a salvage assessment?
  - A. Prior to the vessel departing, several dive surveys were conducted, supervised by RINA. So because of the, you know, the initial report during the offshore dive indicated there was some damage along the keel.
- So the -- prior to the vessel taking,

  departing U.S. waters under dead ship tow, to its final
  resting place. We required the company, Panama, and

- RINA to provide us a structural analysis and a report attesting to the water tight integrity, and the
- 3 structural serviceability to the vessel to depart U.S.
- 4 | waters safely without any concerns.

- So dive operations were conducted, also a thorough inspection of the engine room and the locations of concern, where the hardest hit by the heat to determine A, for product removal, for the subsequent voyage as well. To eliminate any of the immediate pollution threat, and then also to make repairs as needed depending on what the -- those reports were indicating.
  - Q. Okay, thank you. And through the first couple hours of the event, with regard to the accountability for passengers. Tell me your involvement with that, and do you recall any -- as you are recalling this, or telling us the story if you -- the first time you recall having assistance, or being, interacting with, you know, and members of the crisis action team from Baja Ferries, or other individuals from the company, with regard to the passenger accountability, specifically.
  - A. CDR ESPINOSA-YOUNG: So the majority of my involvement with the passenger accountability issue was, you know, the initial report from the master

stating one number. And then our ANOA, or Advance

Notice of Arrival passenger manifest indicating

another.

So we were trying to rectify what was the missing pieces, and provided what the actual manifest that the captain was indicating it was a different number than out ANOA regulations.

So, for the most part the on scene at the reception were the ones that we were dealing with, the actual rectification of that. And ours was really, double checking what, you know, the manifest indicated versus the ANOA and why was there a discrepancy.

And then it was finally resolved as a result of the manifest or the Advanced Notice of Arrival information was never updated prior to the vessel's departure from Dominican Republic, which indicated a higher number of passengers on the manifest because a crewmember was taken off just prior to the vessel's departure from the Dominican Republic due to some kind of heart condition, so the individual never set sail.

Well that ANOA, and that passenger manifest list was never updated, therefore, his name was still appearing, hence the higher number and the discrepancy between the two.

Q. Okay, and we didn't explore it in depth, with

- the Sector Commander yesterday, but it falls more to

  your desk as the chief of preventions from my

  understanding. But the validity of the information on

  that Advance Notice of Arrival tell me, with the number

  of discrepancies that we've talked about, is that

  something that's significant, or is it inconsequential?

  I mean, is it -- what's -- how important is that
- A. CDR ESPINOSA-YOUNG: It is extremely
  important. Because that's how we use our, you know,
  all of that, crew and passengers are vetted through our
  headquarters Coast Watch. So everybody's background
  check is conducted based on the information that is
  there.

document?

Incorrect information is also -- because we double check our database with the information. And in there it requests, you know, timeframes of report, who is their classification society, what is the IMO number; it also provides who their flag state information is.

So there is courses of action with regards to failures of certain information that either the vessel could be denied entry coming into U.S. waters for the discrepancy. Or post-event could suffer a civil penalty action as a result of not completing, or having

an incorrect advance notice of arrival.

- Q. Okay, and the responsibility for the proper completion and execution of that advance notice of arrival, is it something that falls on the master, the company, the agent, or is it a shared responsibility, where does that lie?
  - A. CDR ESPINOSA-YOUNG: So the way the regulations read is really owner/operator, agent, person in charge. So, you know, it could be that it is a -- the master, and it, there is a varying degree of who submits these notice of arrivals. And some of them are agents, some of them are masters.

In the end we don't scrutinize, and it is going to be the owner that's going to be held responsible for it. And then whatever their contractual agreement, you know, that they have that they delegate that to the agent, if that's -- if that becomes an issue then that can take in accordance, settle that matter independently.

But ultimately, really it is the company is responsible for the submission of that notice of arrival, and the accuracy of the information.

Q. Okay, thank you. I -- during your statement, with regard, we are still on the first day, and you indicated that a salvage master, some naval arcs, and I

- think you said five marine firefighting specialists had showed up around -- I wrote down 2000 hours.
  - A. CDR ESPINOSA-YOUNG: Roughly, I mean I didn't,
    I didn't clock them into the hotel.
    - Q. Right.

- A. CDR ESPINOSA-YOUNG: But based on the initial report which was on the 18<sup>th</sup> of August at 1:00, Ardent Global provided the initial salvage plan intentions, and the potential towing, emergency towing operations plan. And in there it gave a description of who was on island, and who was ordered, and what equipment was coming, forthcoming from Ardent Global.
- Q. Okay, and just the high details, I know there is a lot of stuff going on, but can you walk me through that point in time until the point in time where you or the Captain of the Port decided that the fire was extinguished, or no longer a concern. Whether it was one day, two days, I mean, just give me the highlights, run me through that if you don't mind.
- A. CDR ESPINOSA-YOUNG: So the highlights was that the vessel continued to burn pretty much all of the August 18<sup>th</sup>, and it was aground. The fire was not extinguished, you can -- it was clear from the Richard Dixon that remained on scene, and we have images of the paint catching on fire as the, you know, heat was

continuing, and it prevailed pretty much throughout the August  $18^{\rm th}$ , into the evening hours.

Trying to assess the following evening to get our -- the marine salvage firefighters, and they went through, to have the right equipment, get them on board the vessel and do an assessment of, you know, the locations of where the hotspots were and identify really the, you know, the ventilation, condition of the ventilation system. The shut downs, and where the fire was located at that present time.

Pretty much everything below deck without the appropriate marine firefighting equipment was limited to only marine firefighters. And at that time they did a thorough oversight and identified the locations of where the fire dampers were not closed, and the location, you know the condition of the cargo deck and they were unable to gain access at that time to the engine room based on the heat, and the material condition of the vessel.

The evening of the 18<sup>th</sup>, through the 19<sup>th</sup>, we had an unusual, it was a full moon, which contributed greatly to our success, based on the fact that we had a high tide event that normally is one foot, we had a two foot high tide. And because the vessel was, you know, partially aground we started receiving reports from the

Richard Dixon at the time, and the on scene tug, that the vessel was looking lively.

And at which turn, the vessel orientation changed. And we immediately called the salvage master, the salvage team that was at the hotel, and to kind of capitalize on this opportunity, now that the vessel appeared to be free, and for us not to re-ground. We had a limited window of getting in executing this mission.

We directed the salvage master to mobilize their teams, and their tug. They had been, by this time, contracted, I believe it was Titan, or Triton I think it was called. To get salvers on the towing vessel, and then through the small boat station we deployed the rest of the firefighter and the salvers on board the vessel using the accommodation ladder that was put over side.

The salvage team was able to get on board and operate, you know, reconfigure and operate. Because they had already prepared the emergency, and got power to the winch and established a tow. Once they secured the tow, they got on board the vessel, and slowly, once they had a good handle on the situation, they heaved the anchor and the vessel was floated free at about two, three o'clock in the morning on the 19<sup>th</sup>.

The vessel was kept under tow and underway until the following morning. We had already had receiving of the emergency tow plan, and the dead ship tow inbound to the identified location, which was Pier 15, as where the vessel would be safely moored.

There was -- the vessel fire was still isolated in the engine room, primarily located in, I believe it was a lube oil tank that was still active flames coming out of the vent system of that tank.

And they were able to maneuver the vessel with four tugs, one lead tug as the lead, two side assist tugs with lines on, and one at the stern. And maneuver the vessel all the way to the pier, at Pier 15. At which time a complete overhaul of the fire was taking place, and then became the cooling and then reflashing.

So they had already brought additional resources to monitor for quality, you know, their -- what they call their gas doctor, which is really a marine chemist.

Q. Okay.

- A. CDR ESPINOSA-YOUNG: To determine, you know, when it was safe for entry for personnel, not in a SCBA, you know, protection equipment.
  - Q. And just for the record, when you used the

term Richard Dixon, would that be the --

- A. CDR ESPINOSA-YOUNG: Coast Guard --
- Q. -- fast response cutter Richard Dixon?
  - A. CDR ESPINOSA-YOUNG: Correct.
- 5 Q. That relieved the Joseph Tezanos cutter?
  - A. CDR ESPINOSA-YOUNG: Yes, correct.
  - Q. Okay, thank you. I'm getting close to turning the floor over, but -- to Commander Capelli. But I just want to quickly address one final area. And within the Unified Command did you raise any concerns, yourself, or did you hear any concerns raised by any of the members of the Unified Command over the timeliness of any of the response, the firefighting response, the salvage, any of the arrivals, any -- was anything raised in the Unified Command on the 17<sup>th</sup> through the say the end of the 18<sup>th</sup> of August?
    - A. CDR ESPINOSA-YOUNG: No, not in discussions, active discussion through the Unified Command. You know, we had some delays based on equipment needs, you know gaining the assets, but the personnel were on island to get the assets on scene.

So it was really a safety issue, some of the impediments. This is Puerto Rico, resources are somewhat limited. The local contractor was a challenge to deal with, so the local representative that was here

1	from San Juan Towing made it quite difficult sometimes
2	in getting the additional equipment and meeting our
3	needs, both from a safety perspective, or resources
4	that were necessary in order to execute our mission.
5	So it was not, I would say it was not a smooth
6	response in some cases. But most of these response
7	operations are in that fashion, but timeliness in the
8	initial phases, they met the response time criteria. I
9	would say getting an active firefighter component on
10	the vessel did not meet the criteria as required by the
11	regulations.
12	Q. Okay, and this is my last question. But you
13	mentioned this Ardent, I assume it was the Ardent
14	Global rep that you indicated was a little challenging?
15	A. CDR ESPINOSA-YOUNG: The subcontractor, right.
16	Q. Okay.
17	A. CDR ESPINOSA-YOUNG: He was the subcontractor
18	to Ardent Global.
19	Q. Okay, thank you. Commander Capelli, thank you
20	very much, I have no further questions.
21	WITNESSES
22	COMMANDER JANET ESPINO-YOUNG
23	MR. JERRY McMILLAN
24	EXAMINATION
25	BY MR. TUCKER:

Q. Commander, Adam Tucker with the NTSB, just one follow-up question really. You mentioned, I just want to seek clarification, you mentioned when the salvage marine firefighters arrived on island, and you said there were some problems with getting them to the ship, I believe, because of the helo. Was there any other discussion about getting them to the ship via a boat or anything?

A. CDR ESPINOSA-YOUNG: Correct, I mean, I think the big issue is the safety component. So the embarkation ladder, that was a steep climb, you had a four degree list on the vessel. They are bringing equipment, pretty substantial amount of equipment with them to gain access to the vessel, the best way and the safest way -- considering we have a site safety plan that's also provided by the salvers.

We have to take those into consideration that those emergent needs, but at what operational risk are you going to take to the personnel. So there was discussion via water side to gain that control, and get those personnel on board.

But, it was because it was the initial phase of it, bringing them waterside was virtually impossible without some safety concerns to overcome. And we felt at that time there was, you know, it was better suited

to get the right asset to get the people on board.

1

2

3

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

- Thank you. And I did forget one other question, Commander. If you don't know, while the 4 vessel was alongside the pier, and also the survival craft were brought in to the port of San Juan, were you 5 aware of when those vessels, when the lifeboats, in 6 particular were removed from the water and put on the 7 dock? 8
  - CDR ESPINOSA-YOUNG: I can't give you a specific. But the -- I noticed the lifeboats on blocks when I went to the pier. Mr. Henson, which is the representative, obviously the owner of Baja Ferries was with us. I went there because this was our first major start-up operation that we can gain access to the vessel.

And we had a contingency of personnel to, in order to secure and shadow crewmembers throughout the operations, when I saw them at the pier. And I had had a previous discussion with Mr. Yates from the NCOE, with regard to lifesaving. That they were supposed to marshal the lifeboats and bring them alongside the pier, and that was it. That nobody was supposed to go inside the vessels.

But it wasn't until that morning where I actually saw them in the crater, and I had a serious

1	discussion with Mr. Payne, again from San Suan Towing
2	who took it upon himself to do this action, without
3	notifying anybody or requesting that.
4	At that point, we had some discussion with
5	regards to accessing. And one of the attending marine
6	inspectors, LTJG Jesse Collins, actually grabbed
7	caution tape, and we taped the entrances of the
8	lifeboats to ensure further entry was not made. But it
9	was well after, and nobody cleared it through us,
10	nobody contacted us. So, and I immediately reported t
11	the Coast Guard investigators the condition of what we
12	found the lifesaving appliance to be.
13	Q. Commander, thank you very much.
14	A. Um-hmm.
15	CDR CAPELLI: Commander thanks. I have no
16	follow-up questions. Panama do you have any follow-up
17	questions?
18	MR. ARENAS: No.
19	CDR CAPELLI: Panama has no questions.
20	MR. BLASINI: No sir.
21	CDR CAPELLI: Baja Ferries has no questions.
22	WITNESSES
23	COMMANDER JANET ESPINO-YOUNG
24	MR. JERRY McMILLAN
25	EXAMINATION

## MR. BOWLING:

- Q. Sorry Commander.
- A. CDR ESPINOSA-YOUNG: No, that's all right.
- Q. The ah -- Larry Bowling with the National
  Transportation Safety Board. We heard through
  statements, and testimony earlier, I want to say it is
  from one of your subordinates, Joel Morgado.

About an individual, a local fire chief, or
firefighting, member of the Puerto Rican Fire

Department, and I believe, PREMA. The individuals name
was Angel Crespo.

And apparently there were come conversations down at Pier 6 or the landing site about the local firefighting team being put onto the vessel. Do you know any, have any detail on that, are you aware of that? Any information there?

A. CDR ESPINOSA-YOUNG: We unfortunately were aware of it post-event. So it was some discussions with regards to what assistance the local fire department can provide and we, we felt pretty confident that based on training that is conducted, you know, just in the course of planning, our planning efforts, that the marine firefighter capabilities for the local fire department can only be in support of an alongside pier event.

1 That they were inadequately trained for an offshore event or can provide the necessary assistance 2 because, again, you don't have the crew there, you 3 4 don't have an operational vessel, you don't have the 5 capability of somebody running the emergency pumps and providing and supplying the necessary systems in order 6 for them to overhaul or even do boundary cooling. 7 So we were specific and directed that no 8 9 marine firefighting from land base should be going on board the ships to render assistance. 10 Okay, thanks again Commander. 11 Ο. Α. Um-hmm. 12 Thank you, Commander Capelli. 0. 13 CDR CAPELLI: Okay, does Panama have any 14 further questions? 15 MR. ARENAS: No questions. 16 CDR CAPELLI: Does Baja Ferries have any 17 further questions? 18 19 MR. BLASINI: No sir. 20 CDR CAPELLI: Okay, witnesses, you are now 21 released from witnesses at this hearing, thank you for your testimony and cooperation. If I later determine 22 that we need additional information from you, I will 23 contact you through your counsel. If you have any 24

questions about this investigation, you may contact the

1	recorder, LTJG Diaz-Colon. The time is 1225 we will
2	recess until 1330.
3	(Whereupon a luncheon recess was taken.)
4	CDR CAPELLI: Good afternoon the time is
5	1338, the hearing will now commence, recommence. We
6	will now hear testimony from Chief Warrant Officer Roth
7	the last Port State Control Inspector from the Coast
8	Guard who saw the Caribbean Fantasy. Please come
9	forward to the witness table, and LTJG Diaz-Colon will
0	administer the oath and ask you some preliminary
1	questions.
2	LTJG DIAZ-COLON: Please raise your right
3	hand.
4	WITNESS
5	CWO ALAN ROTH
6	Whereupon a witness produced on call of the
7	Coast Guard was duly sworn according to the law, was
8	examined, and testified as follows:
9	THE WITNESS: I do.
20	LTJG DIAZ-COLON: Please be seated. For the
21	record, please state your full name and spell your
22	last.
23	THE WITNESS: Alan Roth, R-O-T-H.
23	THE WITNESS: Alan Roth, R-O-T-H.  LTJG DIAZ-COLON: For the record, would the

1 last? COUNSEL: Lieutenant Shannon Price, P-R-I-C-E. 2 3 LTJG DIAZ-COLON: Thank you. Sir, can you 4 please let us know your current -- where you currently 5 are employed and what your position is. THE WITNESS: I'm a marine inspector at U.S. 6 7 Coast Guard Sector San Juan, in the Prevention 8 Department. 9 LTJG DIAZ-COLON: Thank you. CDR CAPELLI: Good afternoon Mr. Roth, we are 10 going to start off questions from Mr. Larry Bowling, 11 from the NTSB. 12 13 MR. BOWLING: Thank you. 14 **EXAMINATION** BY MR. BOWLING: Chief Warrant Officer Roth, just for the 16 17 record, I am going to try and narrow the scope of the questions to just the last Port State Control 18 19 Examination performed by Sector San Juan. And if I am 20 not mistaken, that's MISLE activity 5963390. We had a 21 preliminary interview, and your credentials, and 22 everything are a matter of that record. And that's Exhibit E024. 23

So, can you start me out with that particular

Port State Control Examination? And I understand that

24

you were lead for that examination?

- A. That is correct, I was.
- Q. So can you just start me out from the initial scheduling on that, and walk me through the completion of that exam, please.
- A. So the initial scheduling started off in the office, where we gathered all the basic certificates and documentation from the vessel to go and conduct an annual exam on board the vessel.

Mr. McMillan provided me the information the background information that they had been previously detained in Gibraltar. And, which we were unaware of prior to that. And then we gathered our team together, and set the schedule, and we were on board on the ninth of August.

When we arrived at the vessel, we did a cursory view of the exterior of the vessel. Checking the, you know the doors, the hull, the load line, just basic requirements that we have to go with. And then we went on board and had a meeting with the chief engineer, the captain, some of the other staff, the senior staff from the vessel.

During that, we ask questions, if there is any outstanding conditions of class. We also brought up the detention in Gibraltar. Which (inaudible word)

- said everything was corrected. Class was also on board and they gave us a copy of their conditions, outstanding conditions that they had.
  - So we were also going to address some of those, those items during our walk through and material inspection. I was assigned as the team leader, but I was also in charge of Team Number 4, which is the machinery space.
    - So after we discussed the game plan for when to conduct drills, and the outstanding conditions of class, and other logistical issues for the exam, we broke off into our designated teams, and I went below to the engine room.
    - Actually, correction, I first went to the emergency diesel generator and conducted a test with that, and then we went down below into the engine room and did our material inspection of the engine room.
- Would you like me to continue with that?
  - Q. Yes, please.

- A. Okay. So as we went through, I explained to the chief engineer which, at the time they had a changeover, so they had two chief engineers currently on there. And we were working more with the off-going chief engineer.
- And explained to him that we are going to be

doing no operational tests of machinery, with the exception of the oily water separator. A water mist system that I found out that day that they had installed, and some quick closing valves, water tight doors, and some bilge alarms, and smoke detectors.

So, and then we continued on. Went down into the engine room, conducted a test of the oily water separator, continued our walk through, did some bilge alarms while we were going that as well. And just did an overview of the engine room.

We paid closer attention to the bilge based off of the detention that they had in Gibraltar. At the time of inspection, the bilge was fairly clean, so no concern from our end. And all the machinery, and equipment that we had tested, functioned as designed.

Towards the end of the material inspection we did a test of the quick closing valves. Which, in this system are actuated by one valve that is located just outside of the ECR, on a ladderway going up. There is a little box that has a pneumatic valve, that once it is opened, it closes all the quick closing valves inside of the engine room and surrounding spaces that are in there.

So we did that test, I asked the chief engineer how he would like to test it, and he said that

he didn't want to drop power or fuel to the generator, it was on line, so he wanted to block the service tank so we can maintain fuel going to the generator.

I said if that is your normal procedure for testing it, we can go forth and continue to test this. So that at that point is when they grabbed a bolt placed it in, underneath one of the flanges for the service tank, showed me that it was loose, indicating that it wasn't tight in there.

We verified the location of all the other quick closing valves, verifying that they were open, and then he opened the valve actuating the quick closing valves and then we went around verifying that all the valves did close.

When we got back to the service tank, the bolt was tight, indicating that the flange had dropped; we had him reset the system and remove the bolt. We checked some basic documentation, engineering wise, oily record book, (inaudible word) procedures, their engine room log, and then from there we went into running of drills. We got to the point where we were going to be doing drills.

So for the drills, I was assigned to be on scene. Which, in this case, we were doing a fire drill in a CO2 protected machinery space, which happened to

be the auxiliary machinery room. We -- they initially
-- they started the drill off, I followed the fire
team, the very first fire team down into the space,
observed their hose handling, their equipment that they
had on, and their general communications.

After I was satisfied with the fire team on scene, I went into the ECR, where I spoke and observed with the safety officer, and her communication between the on scene fire team and the bridge. And then, once we were good from there, we moved back up, one deck up to where they actuate the CO2 system. And we observed the CO2, simulated discharging.

When we got the team together, and everybody was satisfied of the drill, they moved on to the next phase, which was going to be an abandon ship drill.

From the abandon ship drill, I stayed at the aft stairway, I believe it was, I don't remember how many, it had to be either two or three, but I was one of the aft stairways, and we began questioning the stairway guides on their emergency positions.

As we made our way through all the stairway guides and out onto the embarkation deck, I went back to the MES stations which are located aft, and all the way up to the upper decks. Well actually, they are below the life rafts. So I went up to the life raft

station first, and questioned the life raft teams. And then we made our way to the MES station and questioned the MES stations.

Once we finished questioning them, I went and observed the outboard lifeboats exercised in the water. I didn't see the actual lowering because at the time I was still questioning the MES stations, and so I didn't see that, but I did see them being exercised, in the water.

When we were satisfied with the retrieval of the lifeboat, we got the team together, and we went through any deficiencies that we had observed. And then we continued from there, which was the cargo portion, which Mr. McMillan was assigned to team two and three, which was all the passenger accommodations. But he also was going to be doing the cargo portion.

Since we were running a little behind on the cargo portion, I assisted him on going through, and we went through the RORO decks, where we witnessed the drencher system being activated. We did two zones, and during that we identified that there was approximately 21 nozzles that were not functioning.

We had them, after that we went physically through all three decks, cargo decks, A, B, and C, and looked at all the other nozzles to see if they were

- either in place or appeared to be damaged. So we didn't find anything else other than those initial 21.
- 4 captain, discussed the deficiencies that we had come
- 5 across, we spent our time writing our deficiencies, and

We went back up, had a meeting with the

- 6 from the activity we issue seven deficiencies, we
- 7 | cleared four of them, and had three outstanding.
- 8 Q. Okay, thank you. If I could ask that Exhibit
- 9 | E053 be brought up, and I'll ask several questions from
- 10 | that particular document. And Chief Warrant Officer
- 11 Roth does this look like, was this your handwriting?
- 12 A. It is not my handwriting.
- Q. Who completed Form A and Form B for you that
- 14 day?

- 15 A. That was going to be one of our people on Team
- 16 One which is most likely our Port State Control
- 17 Examiner that we had up there.
- 18 Q. Okay.
- 19 A. Which is pretty typical they will, they can
- 20 prepare the documentation, we review it, and then we
- 21 | sign as the qualified.
- 22 Q. Okay, and when you say we review, and we sign,
- 23 | is it you as the team lead?
- A. Me as a team lead, but we, as a team in
- 25 | general, will go over all the deficiencies, so the team

lead on these exams is not the overall authority, he is the voice of the team. So we -- he is the designated person, you know the one team one voice, and he is the communication between the ship and our team, so we don't have multiple people speaking.

- I mean, I do have some influence on what decisions are going to be made on how to issue the deficiency, and what timeframe we are going to give. But we try to use it as, you know, a group effort in deciding on what we are going to write up and how to write it up.
- Q. I understand, thank you. We are going to talk in detail, and I'll turn the floor over to Adam Tucker here in a minute or two with regard to the quick closing valves. But I want to focus on some of the other areas here. You mentioned the external visual examination of the hull, and at any time did you or any of the other members, team members see any hull insets or water tight integrity issues that raised any concern?
  - A. Nothing that raised any concern.
- Q. Okay. You also mentioned that class was on board, but you didn't specify class, were you referring to RINA?
  - A. Yes, I am referring to RINA.

Q. Do you know the name of the individual from RINA, the surveyor that was there?

- A. I had previously worked, and in my previous testimony I had mentioned Eric Mark. But from thinking back, the surveyor that attended that day was a different one who I do not remember his name.
  - Q. Okay, thank you. You did mention the conditions, the outstanding conditions of class. Do you recall any of those that were provided to you?
  - A. I actually have the report in front me, if I can reference that?
- Q. Yes, please do. And you say report, is that the MISLE ID activity, or MISLE activity?
  - A. No, this is a report from RINA, it is the condition -- it is their ship status report that has any conditions that they have issued to the vessel. The vessel provided us this during our initial brief to say these are the outstanding items that class has issued. And so we did not write deficiencies of these, since these were already addressed by class.
  - Q. Okay, and just give me some document information so we know exactly what document you are referring to, please. The date and the --
- A. Oh, the date?
- 25 | Q. -- control number.

- A. So this is RINA number 76747.
- 2 Q. Um-hmm.

- A. The date of issue is 8 August, 2016.
- Q. Okay, and the conditions that were outstanding they provided to you on that particular document are what?
  - A. The conditions they had were they had a hydraulic system of the internal ramps (was to be) repaired in order to provide complete closure while securing pins, those are on the cargo deck. The pins were leaking, the hydraulics were leaking and they had addressed that these were going to be repaired and postponed until 1 October, 2016.

The fire main permanent pressurization, they said that they found that it was not operational, a result of the absence of a relevant jockey pump. And they were due to correct this by 18 August, 2016.

They had an unapproved deck generator which was out on the aft uppermost deck, and they were due to remove it from the vessel, completely remove it by 31 August, 2016.

They also identified that diesel generator number one had oil leakage on the outer side in the way of cylinder heads. Which is supposed to be corrected by 3, August, but postponed until 19 August, 2016.

And they also had an updated fire control plan that needed to be submitted and approved by RINA no later 18 August, 2016.

- Q. Okay, thank you. With regard to the engine room, you indicated you were working with two chief engineers, would you have happened to recall either individual's name?
- A. The off-going chief engineer, his first name, I believe, was Igor, and I don't remember the second chief engineer's name, but he was the oncoming one at the time. Which he was kind of sporadic on working with the team, with the Coast Guard Inspection Team. We were mainly working with the off-going one, which was Igor.
- Q. And earlier you indicated that when you were in the engine room you looked at the condition of the bilge, and I think you said it was based on the fact that there was some information that came in from the Port of Gibraltar. You had been made aware of that earlier Port State Control detention.

You used the term, fairly clean, can you build on that a little bit just to make sure I understand what you are -- your definition of fairly clean is?

A. For me, fairly clean, that there isn't oil sloshing down in the bilge. You are always going to

have a certain amount of residue down in the bilge,

just because that's the nature of the engine room. You

know, these are older engines as well. So they are

going to be leaking a little bit, and you are going to

have some residual -- or just from maintenance that's

being conducted.

- But there is no pooled up oil, is what I, my what I get at, is there was no oil pooled up or
  accumulated anywhere in the bilge that I had seen. So
  -- which was my interpretation of being fairly clean.
- Q. Okay, thank you. And when you were talking about your role during the fire drill, you were doing, you used the term fire team assessment, you were assessing the activity, and the fire team on scene, and what it was, whether they were sufficient or not. Are you using -- what standard are you using to make that judgement call on their efficiency, their capabilities? Is it a Coast Guard standard? Or is the ship's fire control plan, what do you use as the basis?
- A. Well, we use their, also their standard of how they, you know, fight fires, so it is based off of the ship. But I also use my knowledge and experience in shipboard firefighting to assess hose handling and firefighting techniques.

In addition, we also have a lot of guidance in

- 1 | the Coast Guard, our TTP, which is our Tactic,
- 2 Techniques, and Procedures that gives us guidance on
- 3 | firefighting procedures as such.
- 4 Q. All right, thank you. And during the drill,
- 5 | and as far as the fire drill, not when it rolled over
- 6 into the abandon ship, but during the fire drill, do
- 7 | you recall seeing the staff captain down on scene with
- 8 | the fire -- you mentioned the safety officer, but do
- 9 | you recall seeing the staff captain down there?
- 10 A. I don't recall seeing the staff captain; he
- 11 | may or may not have been down there, I'm not sure. But
- 12 | I was focused on the safety officer, and observing her
- 13 role during the drill.
- 14 Q. And while you are there, tell me what you
- 15 | recall about the safety officer, not -- and
- 16 | specifically related to her communication ability with
- 17 | the fire team, her functionality during that drill.
- 18 And your assessment of her, and her performance.
- 19 A. During the time of the drill I thought she was
- 20 | very competent in her position from what I had
- 21 | witnessed during the drill. She maintained very good
- 22 | communication between the on scene fire team and the
- 23 | bridge. Even during the de-brief I actually told the
- 24 | captain, I commended her, saying that she did an
- 25 | excellent job in maintaining the communication during

the fire drill.

- Q. And was there something specific that you recall that prompted you to say that there -- it was an excellent, she did an excellent job? I mean, what prompted you to make that determination, or make that --
- A. Just a general comment based off of, you know, doing briefs. A lot of foreign flag vessels, you know, appreciate comments, either good or bad, what we have, and any time we get a chance to praise I like to do it, especially with the higher management.
- Q. Okay, thank you. You mentioned that there -something to the effect that there were limited (in
  the) accommodation space. But there were stair tower
  guides on the vessel and you had, I assume interacted
  with them during the drill. Can you tell me, verify
  whether you did interact with them, and if you did,
  what was your assessment of their English proficiency?
- A. They spoke English well enough. I interacted with all of them going all the way up to as far as the stairways went. They, they spoke English well enough for their emergency position, is what I had gathered. They answered their emergency position and the general basic questions that I had asked them, sufficiently. I had no issue with their English ability.

Q. Okay and just -- tell me, what kind of questions are you asking those stair tower guides, or stairway guides?

A. So we normally begin by asking them their emergency position. And they, you know, begin to tell you whatever their position is, which is going to be as a stairway guide, and I ask them what does that entail. So they begin to explain what they are supposed to in case of an emergency on how to direct people to the embarkation deck.

know, basic scenarios on if you have a person that is disabled how you will direct them to the embarkation deck, or if you have a person that does not speak English or Spanish, how do you direct them to the embarkation deck. Or if you have a child that has been separated from one of their parents, how would you reunite them, or what do you tell the parents to, you know, reunite them with their child?

Medications, or basic fire in one of the accommodations, we also ask them general ship knowledge, how many life rafts do you have on board, how many lifeboats do you have on board, so just general questions regarding their emergency position or anything they may interact with people on board the

- vessel while being in a stair tower, in an emergency situation.
- Q. Okay, thank you. And I think this is on the record with your earlier interview, but I don't recall, had you previously been on the Caribbean Fantasy for Port State, earlier Port State Control exams? And if so, how many, roughly?
  - A. Roughly I'd say three times I had been on board. There may have been one other one in there, but I know at least maybe three times.

- Q. Okay, in your earlier visits to the ship do you recall ever running into any communications issues? Specifically English to Spanish, and Spanish to English or anything to that affect?
- A. We have, we have run into issues where there were some people in -- on -- mainly with the stairway guides, that their English was not sufficient, and we would normally address that with the staff captain, or the captain during our out brief. And they would either give them remedial training, or remove them from that position.
- Q. Okay, thank you. I want to step up now, after the drill rolled into the abandon ship phase, I understand that you went to life raft location and the, I think you used the term, outboard lifeboat location,

- and also MES, if I understand correctly, Marine
- 2 Evacuation Systems.
- 3 A. That is correct.
- Q. Okay. Were you checking, as you made your rounds, did you look at the individuals there, and validate their safety card was related to the position you were at, or they were in the right spots?
- 8 A. No, I did not.

10

15

16

17

18

19

20

21

22

23

- Q. Okay, you used the term outboard lifeboat, do you know what number that would have been?
- 11 A. That would have been lifeboat #2.
- Q. Okay. And would you have happened to remember or recall who the lifeboat commander was at that time, with that particular lifeboat?
  - A. I do not. Like I had mentioned previously I the boat was already in the water by the time I had
    come up to it.
  - Q. Okay, if we could -- let's walk through the deficiencies and we will close this one down here. I'm looking at Port State Control Form B. Can you walk me through those deficiencies, just tell me a little bit about each one, and if you recall what the three outstanding deficiencies were when you left the ship, point those out as well.
- 25 A. Well, based off of the Form B that you have

- right there, the top three have 10C's, which are
- 2 actions taken. Which those are corrected, you know, to
- 3 | our satisfaction, so those were corrected prior to our
- 4 departure. The ones after that are going to be the
- 5 | remaining deficiencies, and there was, like I said,
- 6 there was a total of three remaining.
- 7 Q. So the first one, fire doors, was resolved.
- 8 | The second one related to fire doors, self-closing was
- 9 resolved.
- 10 A. Was resolved.
- 11 Q. The third one, was fire detection and fire
- 12 | alarm system, what is the detail on that one, if you
- 13 | don't mind?
- 14 A. The detail on that was a smoke detector that
- 15 | was kind of just hanging below, so it was just hanging
- 16 though. So they repaired it, they fixed it and tested
- 17 | it, and we cleared the deficiency.
- Q. Okay. And then Item Number 4, Deficiency #4,
- 19 | boundaries of bulkheads, looks like a category A60
- 20 issue.
- 21 A. It says -- (reading to himself) -- that one
- 22 | had a piece of missing insulation. So it was -- it
- 23 | wasn't complete with their structural fire protection
- 24 as an A60 boundary. We had them find another piece of
- 25 insulation, the correct insulation and they re-

installed it.

1

5

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

- And roughly where was that at? Frame 33, Deck 2 3 B?
- Deck B, I don't know the exact location besides what is written in the deficiency since I was not on that team during the inspection and found that 6 deficiency.
  - Okay, thank you. Lieutenant Diaz, roll on up, Ο. please. Deficiency #5, ventilation ducts serving RORO cargo spaces capable of being effectively sealed shall be separated for each cargo space. Port State Control officer found the aft D17, B garage C, two fire dampers not closing. Can you put some detail on that, please?
  - I also did not test this. I mean, I can shed some light on it, but I did not test this, so I was not there for the testing of these fire dampers. We periodically test them after the drencher system, it's going to automatically activate the dampers as well, and then we have them remove some of the hatches to go and look at the dampers. Two of these were not closed, from that zone in B.
  - Okay, thank you. And I believe that that is one of the items, that deficiency may have been outstanding at the time of the fire on August 17<sup>th</sup>. Is that one of the deficiencies that was outstanding?

- A. Yes, it was, it had a 16AC, which is two weeks, 14 days.
- Q. All right and the -- I think it was Item #5
  that we looked at, with -- they had the piece of
  missing insulation according to some notes I had, I
  think that was another -- the second of three
  deficiencies that were outstanding at the time of the
  fire, would that be correct?
  - A. That is correct.

- Q. Okay. So let's roll on down to #6 please, so just go through that -- that's the drencher nozzles,

  Items #5, or Item #7 -- (Reads). "All electrical apparatus shall be so constructed, and so insulated as not to cause injury when handled or touched in a normal manner. Port State Control officer found that duplex 120 volt electrical outlet, and a 110 duplex volt outlet both hanging and improperly installed", tell me something about that.
  - A. Again, I was not on that part of the inspection, that was during the accommodations, and I believe that was in a crew cabin. From what I received, my brief from the team, that it was an outlet that was hanging out, so it was exposed, it had exposed wiring hanging out.
    - Q. Okay, and based on that code, 16AC, would that

1	be the third deficiency?
2	A. That's the third deficiency.
3	Q. That was outstanding at the time of the fire?
4	A. Yes.
5	Q. Okay. And I believe that is the list, right?
6	A. Yes.
7	Q. I think that is all the questions I have at
8	this time, thank you very much.
9	CDR CAPELLI: Now from Mr. Adam Tucker with
10	the NTSB.
11	WITNESS
12	CWO ALAN ROTH
13	EXAMINATION
14	BY MR. TUCKER:
15	Q. Good afternoon Chief Warrant Officer Roth.
16	A. Good afternoon.
17	Q. Just really a few follow-up questions from me
18	I just wanted to drill down to you touched on it
19	earlier when you were talking with Mr. Bowling. The
20	quick closing valves, can you, you mentioned chief
21	engineer had a process, did he produce that process to
22	you in the in writing as to how they tested the
23	quick closing valves?

produced to us.

- Q. Okay. And, so as I understand this was the off-going chief engineer that you were primarily interacting with in the engine room.
  - A. That is correct.

- Q. And I just wanted, if you can just go back and walk me through what he told you his process was for checking the guick closing valves, what it was.
- A. So during the quick closing valve test, I was interacting, like I said earlier, with the off-going.

  But I believe the on-coming was also there, so he was assisting the other one in checking the valves.

So we explained the process that I wanted to see them all open, and the locations of the valves.

And that he was going to block it, based off of not wanted to secure the generator field supply. So he walked me through, we placed a bolt on the service tank that it was loose.

Then we went back and verified that all the other tanks, or quick closing valves, correct, the quick closing valves were open. He actuated the valve, and then we went back through and verified that all the quick closing valves had shut. And that the bolt in the service tank was tight. We had him reset it, remove the bolt.

Q. And after he reset it and removed the bolts,

- 1 did you witness any bolts on any other valves after
  2 that?
- 3 A. No, I did not.

- Q. Okay. Carlos I want to bring up Exhibit #216.

  This is the diesel oil fuel tank, and that's the

  condition that we found it in, post-accident. And I

  believe this is the particular fuel tank that was

  supplying the engine at the time. Again, I just wanted

  to confirm that there was no -- you never saw any bolts

  after you left the engine space?
  - A. That is correct, I did not see any bolts. We verified that all -- there was nothing obstructing the quick closing valves during the test.
  - Q. Understood. That is all I have for the quick closing valves. My last question is, you mentioned you were on deck, and I understand you didn't witness the launching of the lifeboat, I just wanted to confirm what Mr. Bowling had asked earlier, with respect to the recovery of the boat. Did you hear any of the radio communications between the persons on deck and the lifeboat that was in the water trying to return to the ship?
- A. No, I don't remember and of the radio communication.
  - Q. All right Chief Warrant Officer Roth, thank

1	you very much, I appreciate it.
2	A. Thank you.
3	WITNESS
4	CWO ALAN ROTH
5	EXAMINATION
6	BY MS. McATEE:
7	Q. Hi, this is Nancy McAtee with the National
8	Transportation Safety Board. I just have one question
9	You mentioned that you were going to test the water
10	mist system that had recently been installed, what
11	location was that system in?
12	A. The actual system is located just forward of
13	the main engine room, in the AC space. So the valves
14	and location are just forward of that. That is so
15	outside of the main engine room, crossing a bulkhead
16	into the main AC space there was a small, it is a
17	Nebula High Pressure Water Mist System. We did not
18	conduct a functional test during that exam.
19	WITNESS
20	CWO ALAN ROTH
21	EXAMINATION
22	BY MR. BOWLING:
23	Q. Lieutenant Diaz, bring up Exhibit #078. And
24	Mr. Roth, when he does that, just this is a RINA
25	it's a document, it's similar to a vessel critical

- 1 | profile for the Coast Guard. This is something they
- 2 | call the Leonardo Status. We are going to go to page 7
- 3 of this, which covers outstanding class
- 4 | recommendations. And I want to go to -- there was one
- 5 | related -- I want to say page 7 -- related to the fire
- 6 pump.
- 7 Actually it is right at the top of the page,
- 8 | got it -- FURA, but Fire Main System, Permanent
- 9 Pressurization, (reading), "The permanent
- 10 pressurization of the fire pump, fire main system, is
- 11 required by -- firing -- SOLAS Chapter 2-2, Regulation
- 12 | 10, paragraph 2.1.2.1.1, was found not operational as a
- 13 result of absence of the relevant jockey pump. Line
- 14 | pressurization to be -- in pump to be tested".
- RINA issued that on 26 July, 2017 (sic), and
- 16 | it looks like it was due after the Coast Guard Port
- 17 | State Control Exam. Was that provided -- that
- 18 information provided to you by the RINA surveyor as one
- 19 of the class recommendations that you just referenced
- 20 | earlier?
- 21 A. It was.
- 22 Q. And do you -- did you look at that particular
- 23 | system during the Port State Control Exam on the ninth?
- A. We did.
- 25 Q. Do you have any information you can expand on

1 that? I'll get to talk to the RINA rep, but what was your recollection of that particular problem? 2

3

7

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

- Well, the jockey pump, I mean, if it was not 4 operational, they had to repair it. So they couldn't 5 maintain the line pressure on there. These are what they call a wet system on the fire main. So they have 6 to have, maintain a certain amount of pressure. And the jockey pump, which is a smaller pump, is going to 8 maintain that pressure in the system until it gets to a point where it can't maintain it, and the main fire pump will energize.
  - Okay. And with the engine, the two chief engineers, and your interaction there, at any time, did you hear either individual reference any type of preventative maintenance system, or did you ever happen to see any plan or preventative maintenance list of work being done in his room during your examination or visit to the engine room on that date?
  - On that date, I did not go through the Α. preventative maintenance system, no.
  - But on earlier visits had you seen such a document?
  - On earlier visits we have asked them about preventative maintenance, because they have had machinery disassembled, or pieces of machinery or

equipment torn apart. So we have asked them about the condition of that equipment, and they said it was under their preventative maintenance.

Q. Okay, all right, thank you very much. Thank you, Commander.

## CWO ALAN ROTH

WITNESS

## WITNESS

## 9 BY CDR CAPELLI:

- Q. Good afternoon Chief Warrant Officer Roth, this is Commander Mike Capelli with the U.S. Coast Guard. And you had mentioned that you did not verify whether the persons doing the job were in accordance with their muster list. When would the Coast Guard verify positions being filled by the muster list on the exam?
- A. If we would suspect that there was somebody filling a billet that -- or they were unaware of their billet. The muster lists on those ships, on most cruise ships is very large. So in order for us to go and verify every single person it would take the entire day.

So we take it by asking them what is your emergency position, and if they can clearly state their emergency position we, we leave it at that. And I

```
1
    don't verify it against the muster list, or the watch
    quarter station bill.
2
             CDR CAPELLI: Thank you. I have no further
3
4
    questions. Does Panama have questions for the witness?
5
             MR. ARENAS: No questions.
              CDR CAPELLI: Panama doesn't have questions.
6
    Does Baja Ferries have questions for the witness?
7
             MR. BLASINI: No sir, we don't have any
8
9
    questions.
             CDR CAPELLI: Baja Ferries has no questions
10
    for the witness. Chief Warrant Officer Roth, you are
11
    now released as a witness at this hearing, thank you
12
    for your testimony and cooperation. If I later
13
    determine that we need additional information from you
14
    I will contact you through your counsel. If you have
15
    any questions about this investigation you may contact
16
    the Recorder, LTJG Diaz-Colon. The time is 1415 we
17
    will now recess until tomorrow 0800.
18
19
              THE WITNESS: Okay, thank you.
```

(Whereupon the proceeding concluded for the day.)

V-179

CERTIFICATION

This certificate is valid only for a transcript accompanied

by my original required signature on this page.

I hereby certify that the proceedings in the matter of Formal

Investigation of the Caribbean Fantasy Marine Casualty

Investigation, heard in the Hilton Caribe, San Juan, Puerto Rico,

Friday March 24, 2017, were recorded by means of audiotape.

I further certify that, to the best of my knowledge and

belief, page numbers one to one hundred seventy-eight constitute a

complete and accurate transcript of the proceedings as transcribed

by me.

I further certify that I am neither a relative to nor an

employee of any attorney or party herein, and that I have no

interest in the outcome of this case.

In witness whereof, I have affixed my signature this 8th day

of May, 2017.

\_\_\_\_\_\_

Sally S. Gessner, Court Reporter