WEEK 27. 1999

- 1. CONTINUE WORKING WITH SHEETMETAL AND INSULATION MB.21
- 2. OVERHAULED FIRE PUMP NO.24 SHAFT SEAL BROKEN.
- 3. REPAIR LEAK SEWATER PIPES FOR EJECTORTANK EVAP.#21-22
- 4. CONTINUE WORKING WITH EMERGENCY BILGE VALVES IN AFT ENG. ROOM.
- 5. PREFABRICATED DOSING LINE FOR BOILER 23.
- 6. REPACKED FLANGE FOR BUTTERFLY VALVE S/B HATCH NO.3
- 7. CHANGED STEAM EJECTORS 1.AND 2. STAGE TG.#20
- 8. OVERHAULED DRAIN PUMP NO.22
- 9. CHANGED EL.MOTOR ON FIRE PUMP NO.22
- 10. PREFABRICATED PIPES FOR FIRE HYDRANT AFT BOILER ROOM.

WEEK 26. 1999

- 1. PREFABEICATED PIPES FROM SUCTION 3.5 TO PUMP FOR SWIMMING POOL SKY DECK.
- 2. CONTINUE WORKING WITH SHEETMETAL AND INSULATION MB.21
- 3. OVERHAULED CONDENSAT PUMP FOR EVAP.22
- 4. CONTINUE WORKING WITH BILGE LINE IN FWD.AUX.ENG.ROOM.
- 5. REPACKED PORT STERN TUBE PACKING GLAND. ONE PACKNING.
- 6. OVERHAULED EMERGENCY BILGE VALVE IN AFT AUX.ENG.ROOM.
- 7. OVERHAULED CIRCULATION PUMP LUB OIL S/B FOR GRAVITY TANK STEERING GEAR.
- 8. OVERHAULED SEWATER PUMP FOR TG. 10
- 9. CONTINUE WORKING WITH COVERNOR ON TG. 22
- 10. PREFABRICATED PIPE FOR FIRE HYDRANT, AFT AUX. ENG.ROOM.

WEEK 29. 1999

- 1. CONTINUE WORKING WITH SHEETMETAL AND INSULATION MB.21
- 2. ACID CLEANING OF PLATE HEAT EXCHANGER FOR MAK.17-18
- 3. D&D MARINE CHANGED LUB OIL SHAFT SEAL ON P/S TURBINE TG.11
- 4. REPACKED STUFFING BOX ON DRAIN, NOZZLES VALVES S/B-P/S MT.
- 5. CLEANING CONDENSER AND CHANGED STEAM EJECTORS 1. AND 2. STAG TG.#22
- 6. REPACKED STUFFING BOX ON TRIP, STEAM VALVES AND CHANGED TOP NOZZLE VALVE. FWP. #21
- 7. PREFABRICATED PIPES FOR SEWAGE, INLET LINE P/S. AFT.ENG.
- 8. MAKE NEW DRAIN PIPE FROM MP. 1 S/B MAIN TURBINE.
- 9. MAKE NEW FOUNDATION FOR FIRE PUMP #12 OVERHAULED.
- 10. OVERHAULED SEAWATER PUMPS #22-24 FOR REF.DEP.
- 11. OVERHAULED SANITEARY PUMP#11 AND GEN.SERVICE PUMP #23

WEEK 28. 1999

- 1. CONTINUE WORKING WITH SHEETMETAL AND INSULATION MB.21
- 2. CHANGED HYDRAULICS PIPE TO GOVERNOR TG.20
- 3. CHANGED BUTTERFLY VALVE SEWATER FOR BILGE EJECTOR IN AFT AUX. ENG.ROOM.
- 4. PREFABRICATED PIPES FOR BALLAST TANK NO.1-1
- 5. CONTINUE CLEANING TANKTOP IN ENGINE ROOM.
- 6. CHANGED SHAFT SEAL ON FIRE PUMP 24 AND COOLING PUMP NO.13
- 7. D&D MARINE STARTED ASSEMBLY WORK WITH TURBO GEN.#21
- 8. OVERHAULED PNEUMATIC BALLAST VALVES NO.28-32-34
- 9. CDANGED IBEXRING ON FLANGE S/B MANOEUVRE VALVES.
- 10. CLEANING MAIN CONDENSER S/B P/S NO SEA SHELL.
- 11. CLEANING SOAP TANK FROM LAUNDRY IN TUNNEL.

WEEK 32. 1999

- 1. CONTINUE WORKING WITH SHEETMETAL AND INSULATION BOILER #21-23
- 2. TIGHTING UP S/B STERN TUBE GLAND.
- 3. CHANGED CYLINDER HEAD CYL.5 MAK.18
- 4. INTEC WORKING WITH LEAK SEAWATER PIPES FOR MAK. 14-16
- 5. CHANGED IBEXRING ON FLANGE FOR EJECTORSTEAM TG. 22.
- 6. REPACKED EMERGENCY VALVE B-76 P/S FOR EJECTORSTEAM.
- 7. CHANGED GOVERNOR ON MAK.17
- 8. CLEANING CONDENSER, LUB OIL COOLER AND GEN. COOLER TG. 21-22
- 9. STARTED ISOLATION OF STEAM PIPES FOR SOOTBLOWERS IN AFT BOILER ROOM.
- 10. CHANGED SHAFT SEAL ON FIRE PUMP. #24
- 11. CHANGED GOVERNOR ON S/B TURBINE TG.21

WEEK 31. 1999

- 1. CONTINUE WORKING WITH SHEETMETAL AND INSULATION MB.23
- 2. TIGHTING UP S/B STERN TUBE GLAND.
- 3. OVERHAULED BRINE PUMP FOR EVAP.#21
- 4. OVERHAULED BOTH FEEDWATER PUMPS FOR STEAM/STEAM GEN.
- 5. CHECKED MATS, GASKET AND TUBE BUNDLE EVAP.#21
- 6. OVERHAULED SAFETY VALVE FOR FUELTRANSFER PUMP #13/ 3.5bar.
- 7. PREFABRICATED PIPES FOR SKIMMING LINE MAIN BOILERS.
- 8. CLEANING S/B. MAIN CONDENSER.
- 9. REPAIR LEAK LUB OIL CONTROLGLASS S/B. MAIN GEAR.
- 10. REPACKED STUFFING BOX DRAIN VALVES S/B. MANOEUVRE VALVS.
- 11. PREFABRICATED DESTILLATE PIPES, 4"x 5m IN AFT ENG.ROOM.
- 12. INTEC REPAIR, WELDING LEAK SEWATER PIPES FOR MAK. 12-14-16
- 13. WELDING LEAK STEAM PIPES FOR HOTWATER HEATERS.
- 14. OVERHAULED SAFETY VALVES FOR HP.COLL. FWD.ENG.ROOM. 6 Gar.
- 15. ACID CLEANING EVAPORATOR. #22

WEEK 30. 1999

- 1. CONTINUE WORKING WITH SHEETMETAL AND INSULATION MB.21
- 2. MOVING UP THE STERN TUBE GLAND S/B-P/S.
- 3. PREFABRICATED PIPES FOR BILGE EJECTOR IN AFT AUX.ENG.ROOM
- 4. STARTED DISSEMBLED ASHSPIRAL AND ASHPAN ON INCINERATOR.
- 5. CHANGED ALL CHAM SHAFT BEARINGS ON MAK.17
- 6. CHANGED EXH.TURBINE ROTOR MAK.17
- 7. WELDING DOUBLE PLATES OUTSIDE TANK TOP #10-12
- 8. ACID CLEANING EVAPORATOR #21
- 9. SCALING BULKHEAD ON S/B SIDE FWD.BOILER ROOM.
- 10. OVERHAULED ASHCONVEYING FOR INCINERATOR.
- 11. CHANGED EXHAUST VALVE CYL 2 ,PISTON,CYLINDER HEAD AND NEW CRANCK SHAFT BEARINGS CYL.5 MAK.17

WEEK 33. 1999

- 1. CLEANING TANKS 10.17 & 10.18.
- 2. DISMANTLED EL.MOTORS FOR ENGINE ROOM FANS, 1 FORWARD & 1 AFT.
- 3. OVERHAULED HANDHOLD ON MB21.
- 4. CONTINUE WORKING WITH SHEET METAL AND INSULATION BOILER 21,22 & 24
- 5. FOUNDATION FOR LUB OIL PURIFIERS FOR THRUSTERS 4 & 5.
- 6. CHANGE ROTOR ON TURBO CHARGER FOR MAK 18.
- 7. INSPECTION OF EVAPORATOR 22.
- 8. FOUNDATION FOR LUB OIL PURIFIERS FOR STEERING GEAR.
- 9. CHANGED PART OF SKIMMING LINE FOR MB'S.
- 10. OVERHAULING OF STAIRS IN THE ENGINE ROOM.