

Activity Summary Report

Title: Activity ID: Activity Start Time: Originating Unit: Owner Unit: Controlling Unit: Activity Type: Team Lead: Status: Status Date: Prompt Date: Subject POC:	3703045 03/25/2010 8:04 SEC DelwrBy SEC DelwrBy SEC DelwrBy Vessel Inspectio Schock, Andrew Open - In Progre 03/25/2010	n/PSC J.			
Operating Organization Name	ONIAL LLO		Corneration	2	
RIDE THE DUCKS INTERNATION Address P.O. Box 1837	City Branson	State MO	Corporation Zip 65615	Country US	Province
Vessel Information					
Vessel Name:	VIN:	Flag:	¬ エ ۸ ボ 厂 (^	Length:	Tonnage(GRT/ITC):
DUKW 34 Year Completed:	CG35318940 Vessel Type:	UNITED S	DIAIES	33	Propulsion Type:
1945	Passenger Ship-				Gasoline Engine
Engine Compartment: Unknown	Fuel Compartm Unknown	ent:	Constructi Unknown	ion;	
Activities Conducted:		: 1000 1000 1000 1000 1000 1000 1000 10			
Туре	Date	,	Unit		·
Inspection Results			part which pairs were some some large (part) and back hand about the	_ w w w w w	
System	Date R	Results			
Inspection Results - Defi	iciencies				
(None)					
Documents and Certifica					
(none)	M	: = # # # # # # # # # # # # # # # # # #			
Narrative Summary:					
Vessel name: DUKW 34 Insp. location: Philadelphia, PA		, , , , , , , , , , , , , , , , , , , 	was vone blad third tipes were some your base hand arms about it		

Owner's representative: Jennifer Haydt

Contact phone number: In completing this inspection I utilized the small passenger vessel inspection book CG-840T started

12 Mar 2009.

COI Inspection -

Date: 25 Mar 10

Number of items found deficient: 3

1. Repair Prop Engager, Issued CG-835. This CG-835 was originall written for prior to carrying passengers. However, after speaking to Mr. English the new style prop engager had a 2 week lead time. As this was only a small fracture of a single

tooth. This requirement was changed to thirty days with the understanding that the prop will be engaged and checked prior to entering the water, IAW company policy, additionally the prop engager will be inspected prior to each trip and will be immediately taken out of service if there is any evidence of any additional wear.

- 2. Relocate coolant overflow hose from on top of port muffler. This was relocated while entering the space and not properly replaced. Issued CG-835.
- Remove dead end starter solenoid wire. This was left over from a repair. Issued CG-835.

Items retained for Sec Del Bay files:

CG-840 book.

Comments:

- 1. Attended vessel in company of owner's rep Jennifer Haydt to conduct Annual Inspection. DUKW 34 is a 9/66 year old, 33', 9 GT, steel hull, single gasoline inboard vessel certificated under 46 CFR Subchapter T. All seats & deck plates aft of the helm area were removed.
- 2. Inspected all applicable documents and certificates. All documents and certificates satisfactory.
- 3. Conducted operational test of all bridge electronics. All satisfactory.
- 4. All lifesaving equipment was inspected satisfactory.
- 5. Witnessed test of both submersible bilge pumps, and Higgins pump, all sat. Witnessed test of all bilge alarms all. The fwd bilge alarm stuck on after testing. Debris was cleared from the float swith and the alarm was retested sat.
- 5. Fire protection equipment inspected satisfactory. Fixed fire fighting system inspected satisfactory. Bottles hydro was Nov 2002.
- 6. Tested port & stbd curtain release, all sat.
- 7. Conducted abbreviated hull exam all sat.
- 8. Verified immersion marks IAW new stability letter. Found set screw missing from cutlass bearing, this was corrected on the spot, all sat. Found small crack IWO the rear axle boot bracket, this was corrected on the spot.
- (3)CG-835's issued, (0) CG-835 Corrected, (3) CG-835's remaining outstanding. horn, and observed inspection tag on fixed system. Cleared CG-835'erved new bilge pump hoseround both rear bumper supports is
- 31 Mar 10: Attended vessel witnessed sat test of prop engager, all sat. Witnessed radiator hose relocated, all sat. Witnessed starter wire removed, all sat. Cleared CG-835's.

In my opinion, vessel found structurally fit for route and service as indicated on the certificate of inspection.

Insp hrs: 2 Trng hrs: 0 TI trl hrs: .5

Activity A		Description				
03/25/2010 Progress"	SEC DelwrBy	Schock, Andrew J.	Activity Created. Status: "Open - In			
TWIC Verification Details:						
Radiation	Details:					