

| Port of survey | Date of survey | File |    |     |    |
|----------------|----------------|------|----|-----|----|
| GIBRALTAR      | 11-14/07/2016  | 16   | XA | 695 | 01 |

| Name of ship CARIBBEAN FANTASY | RINA number 76747 |
|--------------------------------|-------------------|
|--------------------------------|-------------------|

## PSC FOLLOW-UP REPORT

After a PSC inspection the ship has been detained in the port of Gibraltar. The vessel has been attended as per Owner's request and according to the ITS II-A11-1. Inspection has been started on 11/07/2016 and has been completed on 14/07/2016. With reference to the PSC report deficiencies list as per attached form B/1, the following has been carried out:

| Item | Deficiency description   | PSC<br>Group<br>Code | Action<br>taken<br>by PSC<br>(specify<br>code) | Deficiency rectified before<br>departure (specify how)   | Deficiency not rectified before<br>departure (specify in this case<br>actions taken such as<br>recommendations issued/conditional<br>certificates issued, other)   |
|------|--|----------------------|--|--|--|
| 1    | Auxiliary engines no.1-2-3 not operational.                    | 1310 2               | 30   | A dedicated dock trial has been satisfactorily carried out on D/G no.1 and D/G no2, including alarms and safety devices. Aux. engines no.1 and no.2 are currently properly working.  | Auxiliary engine no.3 is still under maintenance and repairs. Recommendation issued, related to Class Certificate and Safety Passenger, with due date 03/08/2016 has been now issued.  Electrical balance onboard verified for compliance with SOLAS II-1 reg 41 of remaining generating set.  Bow thrusters have been put temporarily out of service.  Under master responsibility tug/tugs assistance is to be called during berthing operation and/or navigation into narrow channels and/or confined waters. |
| 2    | Sea water feed pump<br>to auxiliary engines<br>not operational | 1319<br>9            | 17   | Sea water feed pump<br>has been satisfactorily<br>tested and it is now<br>working properly   | /  |
| 3    | General engine room cleanliness insufficient                   | 1842                 | 17   | Cleanliness of engine room has been improved during inspection and now it is in satisfactory condition. By the way a Class Recommendation has been now issued, in order to keep the cleanliness monitored and have an additional check of cleaning improvement. Due date |  |

| RINA N. 76747 | Nome della nave CARIBBEAN FANTASY | Pratica 16 XA 695 01 |      |  |
|---------------|-----------------------------------|----------------------|------|--|
|               | Name of ship                      | File.                | Page |  |

|  |  | of Recommandation will |  |
|--|--|------------------------|--|
|  |  | be 17/07/2016 .        |  |

Date 14/07/2016

## RINA Surveyor name and signature VINCENZO VEZZI

