

Fire Department New York Incident Report

Amendments

Amended By 900011 - CALDERONE JOHN A. 05/19/2010 22:03:45
Battalion Chief

Incident Reviewed By

Reviewer 900011 - CALDERONE JOHN A. Battalion Chief
Date 05/19/2010

Incident

Incident # 3-0040-0
Status Closed
Incident Date/Time 05/08/2010 09:25:11
Incident Type 300 - Rescue, EMS incident, other
Box# 0014
Address 30 RICHMOND TER Staten Island
Borough 3 - Staten Island
Action Taken1 213 - Performed primary search
Action Taken2 214 - Performed secondary search
Action Taken3 301 - Operated /Assigned C.F.R.-D Engine
Rescued (civilians) 19
Evacuated (civilians) 271
Property Use 898 - Dock, marina, pier, wharf

Resources

Unit Responsible for Report: BC22

Unit Type 92 - Chief officer car
Action Taken1 81 - Incident command
Dispatch Date/Time 05/08/2010 09:29:30
Enroute Date/Time 05/08/2010 09:29:35
Arrival Date/Time 05/08/2010 09:30:31
Cleared Date/Time 05/08/2010 12:09:56
Unit Report By 900011 - CALDERONE JOHN A. Battalion Chief
Narrative Incident Narrative
Incident number 05/08/2010-3-0040-0
The incident location is street address 30 RICHMOND TER Staten
Island NY, 10301.

Unit Responsible for Report: BC22

Upon arrival found ferryboat Andrew J. Barberi (252 passengers, 17 crew, 2 NYPD POs on board) had struck dock resulting in numerous injuries to passengers. Treated injuries, conducted searches, assisted in removing victims. Total of 35 injuries treated on scene with 33 removed to RUMC. Units operated as follows:

DC08 arrived at 09:33 hours and cleared at 12:06 hours.
Actions taken - incident command

BC22 arrived at 09:30 hours and cleared at 12:09 hours.
Actions taken - incident command until relieved by Division 8, then supervised operations on lower decks of ferryboat.

BC21 arrived at 09:32 hours and cleared at 11:15 hours.
Actions taken - supervised operations on upper deck of ferryboat.

BC40 arrived at 09:57 hours and cleared at 12:24 hours.
Actions taken - supervised triage sector

BC23 arrived at 10:02 hours and cleared at 11:52 hours.
Actions taken - operated as resource unit officer.

SB01 arrived at 09:50 hours and cleared at 11:16 hours.
Actions taken - incident safety officer

RB01 arrived at 09:56 hours and cleared at 10:29 hours.
Actions taken - Performed survey of below deck area. Found all stable and no evidence of vessel flooding. Conferred with PD and Ship's officers on bridge, verified patient count with Command.

E155 arrived at 09:30 hours and cleared at 10:52 hours.
Actions taken - Assisted with the assessment, treatment, stabilization and boarding of approximately 6 injured passengers. Assisted EMS Personnel by carrying many injured civilians off the Ferry. Conducted search of upper level with L-78, search was negative. Ordered to set up and cordoned off Triage Area.

E153 arrived at 09:31 hours and cleared at 11:01 hours.
Actions taken - Operated on second deck, provided aid to 3 females and 1 male patient. Boarded 1 female and provided oxygen to 1 male. Assisted with triage of 13 yellow tag patients.

E152 arrived at 09:34 hours and cleared at 11:08 hours.
Actions taken - Operated under BC Calderone on the middle level of the ferry. Conducting patient assessment of victim with a leg injury and removed via long board. Then assisted with the removal and triage of other patients.

E161 arrived at 09:40 hours and cleared at 12:21 hours.
Actions taken - Designated as Water Rescue. Div. 8 ordered E-161 to operate as CFR company and report to slip #5 at Ferry Terminal. E-161 boarded a patient on the second deck and removed to EMS triage area. E-161 also assisted EMS loading patients in to ambulances.

E159 arrived at 09:58 hours and cleared at 11:06 hours.

Unit Responsible for Report: BC22

Actions taken - Assigned to coordinate triage area.

E160 arrived at 09:50 hours and cleared at 11:09 hours.

Actions taken - Placed a victim on a backboard and removed victim to triage area.

E156 arrived at 09:52 hours and cleared at 12:04 hours.

Actions taken - Assisted with injured victim removal from ferry.

E157 arrived at 09:53 hours and cleared at 10:49 hours.

Actions taken - Treated and transported multiple victims.

E158 arrived at 09:57 hours and cleared at 11:09 hours.

Actions taken - stood fast at command post.

E166 arrived at 09:56 hours and cleared at 12:21 hours.

Actions taken - Treated one ferry employee then was assigned to the number two (yellow) triage area under the direction of Chief Wing 40BN to assist EMS carrying injured to busses.

L078

Actions taken - Operated under the supervision of Bn 21. Performed primary and secondary searches of the main and upper levels. Assisted EMS with placing numerous patients on backboards on the main deck.

L077 arrived at 09:31 hours and cleared at 11:02 hours.

Actions taken - Instructed the civilians to take seats and remain calm. Noted the nature and number of injuries and members began administering first aide while Lt Daly and inside team conducted a primary search of the first and second deck. Reported to Bn. 21 on the upper deck and continued to stabilize trama injuries and carry patients off the ferry on backboards. Lt Daly conducted a second search of the upper levels and of the water around the boat, both were negative.

L079 arrived at 09:35 hours and cleared at 10:46 hours.

Actions taken - Assigned as SOC Support Ladder. Reported on ferry with CFR-D equipment and multiple backboards as requested by Batt-22 Chief Calderone. Ordered to help triage and patient packaging. Helped carry multiple patients off ferry. Conducted secondary search on 2nd level of vessel. Results negative

L080 arrived at 09:54 hours and cleared at 11:51 hours.

Actions taken - Assigned as FAST Truck. After incident was placed under control assisted triaging and removing patients to an MTA Bus for transportation to RUMC.

L081 arrived at 09:51 hours and cleared at 12:10 hours.

Actions taken - Conducted search on top deck of ferry, pilot houses and exterior top deck. Assisted with patient transport from triage area to buses.

L083 arrived at 09:55 hours and cleared at 10:57 hours.

Actions taken - Assisted with the injured in the triage area after they were taken off the boat.

RS05 arrived at 09:33 hours and cleared at 10:38 hours.

Unit Responsible for Report: BC22

Actions taken - Rescue 5 reported into Bn. 22 and was ordered to split company in half. Evaluated damage and injuries in wheel house and below decks. No injuries in these areas however there was damage to wheel house caused by collision with ramp and below deck areas caused by collision with Ferry Terminal Building. This damage below decks was to the hull above the water line and no concern that the Ferry might sink. Damage to both the Port and Starboard sides were approximately areas 6' x 4' were metal was crushed and torn away. Assisted in packaging patients on the second level. R5 members also preformed secondary searches on the first level and all below deck areas with negative results.

SQ01 arrived at 09:43 hours and cleared at 10:35 hours.

Actions taken - Conducted searches on the upper levels of the ship under the supervision of B-22. Assisted companies with searches on the upper decks. All searches negative.

TS02 arrived at 09:34 hours and cleared at 10:41 hours.

Actions taken - Worked in conjunction with Rescue 5.

MR09 arrived at 09:53 hours and cleared at 14:01 hours.

Actions taken - Conducted a visual assessment of the ferry's hull from the water side. Relayed a damage report (containing information obtained from R-5) to the Marine Division. Conducted a search for victims on the water side. All searches negative.

MR06 arrived at 09:40 hours and cleared at 10:37 hours.

Actions taken - Conducted primary and secondary search of water near ferry. Results negative.

FC01 arrived at 10:15 hours and cleared at 11:58 hours.

Actions taken - Established Field Headquarters, monitored all radio communications, transmitted progress reports as directed, provided necessary incident history and reports as needed and returned to service.

ST05 arrived at 09:59 hours and cleared at 10:49 hours.

Actions taken - did not operate

RA05

Actions taken - established rehab area

CT01

Actions taken - technical support

Injuries:

Lt Murphy E-152 strained back

On scene:

CC Woznica

DC Tanzosh D8

BC Calderone Batt. 22

BC Flood Batt. 21

BC Wing Batt. 40

ABC Russell Batt. 23

BC Hayde RO Batt.

BC Kozlowski Safety

Unit Responsible for Report: BC22

BC Gala FC Liaison
NYPD Berchini
OEM Wilde #619
EMS Capt. Baskin, DC Kwok
DOT Land, Longe
USCG Rogers, Johnson

Reporting Member: 900011 JOHN A CALDERONE
Unit Responsible: BC22

Fire

Cause of Ignition	5 - Cause under investigation
Case	50112
Area Of Origin	001 - None (No Fire)
Heat Source	001 - None (No Fire)
Item First Ignited	001 - None (No Fire)
Condition on Arrival	6 - None (No Fire)
Factor Contributing To Ignition1	NN - None
Equipment Involved In Ignition	None
Mobile Property Involved	None