


MIC

DAILY RECORD OF FACILITY OPERATION				PAGE NO Page 1 of 1
				DATE May 23, 2015
LOCATION	IDENTIFICATION	TYPE FACILITY	OPERATING POSITION	CHECKED BY <i>SMK</i>
West Columbia, SC	CAE	ATCT	ALL	AIR TRAFFIC MANAGER Chris Rickenbaker
UTC TIME	REMARKS			
0400	T. TATE ON. CFPL: WEST SIDE TWR WINDOW SPRAYER OTS. CFPL: RY23 VASI OTS. REPORTED BY AIR OPS. AOCN NOTIFIED. CFPL: RADAR OPERATIONS TRANSFERRED TO LC. LC AT CD. -- TE			
0530	WCLC. -- TE			
1004	RADAR OPERATIONS TRANSFERRED TO TRACON. LC AT LC. -- TE			
1013	S. DI PIAZZA ON, ABOVE NOTED. -- TE			
1330	WCLC. -- SD			
Q 1703	N42BR AN HXC DEPARTED CAE FOR A VFR FLIGHT TO AVL. AIRCRAFT DECLARED MAYDAY APPROXIMATELY 6 NM NW OF CAE AIRPORT. AIRCRAFT ATTEMPTED TO RETURN TO CAE RWY 11 BUT CRASHED APPROXIMATELY 2 MILES FROM THE AIRPORT. -- CB			
1721	C. BRYANT ON, ABOVE NOTED. -- CB			
2130	WCLC. -- CB			
0041	J. BRUMMEL ON, ABOVE NOTED. -- CB			
0045	RADAR OPERATIONS TRANSFERRED TO TRACON. LC AT LC. -- CB			
0345	DELWYN JAMES ON, ABOVE NOTED. -- DN			
0359	COB. -- DN			
I CERTIFY that entries above are correct, that all scheduled operations have been accomplished except as noted, and that all abnormal occurrences and conditions have been recorded		SIGNATURE(S) OF WATCH SUPERVISOR(S) 		

FAA Form 7230-4

CAE-ATCT-0081  
N42BR, HXC