

Location	Identification	Type Facility	Operating Position	Checked By
Hilliard, FL	ZJX	ARTCC	WMIC	Air Traffic Manager Miles R. Miller

Time (UTC)	REMARKS
0400	J. SANDERS [JG] ON. WCLC. CFPL: R11 243.0 M RCVR OTS. R78 ERIDS 7/18 CENTRAL ESIS OTS.
0405	WCLC
E 0449	HOST SYSTEM CERTIFICATION IN PROGRESS.
E 0527	HOST SYSTEM CERTIFICATION COMPLETE.
0705	SECURITY CHECK COMPLETE.
0950	AC ACCIDENT COVERED EVENT FDX1478, B72Q, MEM./TLH. TOUCHED DOWN 100 FT SHORT RWY 9. 3 SOB NO FATALITIES. AC DESTROYED.
1040	ROBERT M. DRAUGHON (WX) ON
1100	WCLC
E 1211	D71 KEYBOARD OTS.
E 1211	D71 KEYBOARD OTS
E 1230	QHN (ASHBURN) LRR OTS
E 1231	D71 KEYBOARD RTS.
E 1231	ILM VORTAC OTS
1232	D. DEHNE (DN) ON.
E 1300	MAI VORTAC OTS
E 1330	QHN LRR RTS.
E 1711	LOST TLH RCAGS M/S/B POSSIBLE LIGHTENING STRIKE. ASO-CCC MOWRY, ASO-505 RUTHERFORD ADVISED. MIT IMPLEMENTED.
E 1721	TLH BUECS WORKING BUT WEAK. STAYING ON COMBINED CONFIGURATION.
1730	CHARLES C. PHILLIPS, JR. (DJ) ON.
E 1734	CENTRAL R33/R34 NORMAL OPS USING SPARE FREQ. MIT LIFTED. ASO-505 RUTHERFORD ADVISED.
E 1811	R73 KEYBOARD INOP.
1833	CRAIG LASKER (TX) ON.
E 1835	R73 KEYBOARD RTS.
1841	WCLC.
E 1930	USING 125.75/226.8 @ R34 135.65 DID NOT MEET COVERAGE REQUIREMENTS.
E 1942	MAI VORTAC RTS.
E 2130	3 OF 4 TLH RCAG FREQS RTS (125.05, 135.2 & 290.22). 128.07 STILL OTS.
E 2152	QFN LRR OTS UFA.
E 0153	128.07/307.2 RTS.
E 0223	128.07 RLSD TO MAINT.
0230	ROOSEVELT LENARD, JR. (QZ) ON.
E 0258	FREQ 128.07 RTS.
0326	TRAFFIC COUNT FOR 7/26/02. TOTAL -5897. VFR -126.
0330	2 HOURS HO/OT WEST AREA
0359	COB.

I CERTIFY that entries above are correct; that all scheduled operations have been accomplished, except as noted, and that all abnormal occurrences and conditions have been recorded.

Watch Supervisor(s)	Signature	Watch Supervisor(s)	Signature	Watch Supervisor(s)	Signature
					