

<b>MSR990</b>		↑	KJFK SHIPP LINND LACKS DOVEY NATZ STG UN725 QUV UM601 ALG B35 CDC UM620 RAPIS UM728 PIDAS***HECA OICAO STG/N0465F350 ALG/N0460F370 EET/4*	1712
H/B763/W M080 59 099 02			330	NC1 JFK
		KJFK P0330		

<b>MSR990</b>	KJFK		KJFK SHIPP LINND LACKS DOVEY NATZ STG UN725 QUV UM601 ALG B35 CDC UM620 RAPIS UM728 PIDAS***HECA OICAO STG/N0465F350 ALG/N0460F370 EET/4*	1712
H/B763/W M080 G466 66 099 01	P0330		330	
	+6	SHERL		

*Handwritten: 1130, 737, R*

<b>MSR990</b>	LACKS	20	KJFK./LACKS DOVEY NATZ STG UN725 QUV UM601 ALG B35 CDC UM620 RAPIS UM728 PIDAS UM978***HECA OICAO STG/N0465F350 ALG/N0460F370 EET/4*	1712
H/B763/W M080 G466 65 XXX 06	0409	04	330	707
		DOVEX		

<b>MSR990</b>	LACKS	12	JFK./LACKS DOVEY NATZ STG HECA	1712
H/B763/W M080 G466 65 605 05	0701	07	330	ZCZ
		DOVEX		

*Handwritten: 330, R, ZCZ*

<b>MSR990</b> H/B763/W M080 6496 72 470	DOVEX	07 12	330
	0712		330
	01	DOVEY	

4125 6500	JFK./ .LACKS DOVEY 4200N/06000W 4300N/ 05000W 4400N/04000W 0723 4400N/03000W 4400N/ 02000W MUDOS STG HECA O NATZ
--------------	--

<b>MSR990</b> H/B763/W M080 6495 72 470	DOVEY	07 23	330
	0712		
	02	4125/6500	

42N60 0750	JFK./ .DOVEY 4200N/ 06000W 4300N/05000W 4400N/04000W 4400N/ 03000W 4400N/02000W MUDOS STG HECA O NATZ
---------------	--

<b>MSR990</b> H/B763/W M080 6501 72 470	04260	07 50	330
	0746 <i>Dovey</i>		
	03	42N60	

4237 5500	JFK./ .DOVEY 4200N/ 06000W 4300N/05000W 4400N/04000W 4400N/ 03000W 4400N/02000W MUDOS STG HECA ● NATZ	1712
0816		

<b>MSR990</b> H/B763/W M080 6543 72 470	4237 5500	08 41	330
	0816 <i>4260</i>		
	05	4300/5000	

4336 4500	JFK./ .4200N/06000W 4300N/05000W 4400N/ 04000W 4400N/03000W 0905 4400N/02000W MUDOS STG HECA O NATZ	317 C Prog
--------------	--	------------------

<b>MSR990</b> H/B763/W M080 6553 72 470	4336 4500	09 29	330
	0905 <i>4310</i>		
	07	4400/4000	

330	JFK./ .4300N/05000W 4400N/04000W 4400N/ 03000W 4400N/02000W MUDOS STG HECA O NATZ	Lost com ZCS
-----	---	-----------------