

NATIONAL TRANSPORTATION SAFETY BOARD
Office of Aviation Safety
Washington, D.C. 20594

March 6, 2007

Errata 1 to Group Chairman's Factual Report

Air Traffic Control

NYC05IA095AB

A. AIRCRAFT ACCIDENT

Location: Boston, Massachusetts

Date: June 9, 2005

Time: 1940 Eastern Daylight Time / 2340 Coordinated Universal Time

Aircraft: Aer Lingus Flight 132, A333 and US Airways Flight 1170, B737

ERRATA to:

Page 2, last line: Change "LCE" to "LCW".

Pages 3 and 4: Clarifying the time discrepancy between pictures 1, 2, and 3. Picture 1, (about 2339:48) referenced the ARTS clock that is verified every 8 hours. The other two pictures were from the AMASS which is not checked as often and is not as accurate. The times for pictures 2 and 3, using ARTS information, is about 2340:00 and 2340:01, respectively.

Page 4: Section D.2 change "gate control" to "Gate Hold".

Page 19, paragraph 8: "BG" refers to "Boston Gate" which is the name of the gate hold position.

Sandra L. Rowlett
ATC Group Chairman