




#24 V

UNSATISFACTORY CONDITION REPORT		Reports Identification Symbol OA 1800-1	
1. NAME OF ORIGINATOR (last, first, middle initial) SPARKS, MICHAEL J.		DOCUMENT NUMBER UCR- 383079	
2. OFFICE ADDRESS OF ORIGINATOR #1 Airport Drive, Little Rock, AR 72202		ROUTING SYMBOL	3. DATE CONDITION OBSERVED March 8, 1998
4. CONDITION REPORTED <input type="checkbox"/> PROCEDURE <input checked="" type="checkbox"/> EQUIPMENT <input type="checkbox"/> WORKING ENVIRONMENT <input type="checkbox"/> SERVICES <input type="checkbox"/> PUBLICATIONS <input type="checkbox"/> OTHER (Specify in item 7)			
5. (Check if applicable) <input type="checkbox"/> PROPOSED SOLUTION ATTACHED (see item 4 on reverse)		6. ORIGINAL FORWARDED TO → WASHINGTON OFFICE OR SERVICE	ROUTING SYMBOL   DATE
7. DESCRIPTION OF UNSATISFACTORY CONDITION (Refer to item 2 of instructions for conditions to be reported.) LLWAS is unreliable when wind shear situations / weather is in the immediate AREA. Situation occurred with wind indicator showing 290 @ 21. Alert on Centerfield sensor indicating 280 @ 21. There was "NO" alert on the SW sensor and it indicated wind 230 @ 04. There is no explanation for the discrepancy other than the system is wrong. This problem is not new, yet we continually use false indications.			
8. SIGNATURE OF ORIGINATOR 		9. DATE SUBMITTED BY ORIGINATOR March 9, 1998	
10. EVALUATIONS AND REVIEWS (continue on attached sheets as needed—show UCR No., office, name, and date)			
10a. IMMEDIATE SUPERVISOR On March 18, 1998, the facility experienced what was interpreted to be a system malfunction on the LLWAS. A review of maintenance records indicates that all calibration and preventive maintenance had been completed. An analysis of the historical data indicated no malfunction with the system, only a misunderstanding of the performance characteristics of the hidden sensor.			
SIGNATURE (Print or type and sign) 		ROUTING SYMBOL	DATE 3/18/98
10b. AREA OFFICE See Attached Sheet			
SIGNATURE (Print or type and sign) Michael W. Baker 		ROUTING SYMBOL LIT-500	DATE 4/1/98
10c. REGION OR CENTER			
SIGNATURE (Print or type and sign)		ROUTING SYMBOL	DATE
11. OFFICE TAKING FINAL ACTION			
11a. RESULTS OF EVALUATION (check appropriate block and describe)		<input type="checkbox"/> CONDITION CORRECTED	<input type="checkbox"/> ACTION NOT POSSIBLE <input type="checkbox"/> OTHER (Specify)
11b. REMARKS			
SIGNATURE (Print or type and sign)		ROUTING SYMBOL	DATE