

Docket No. SA-509

Exhibit No. 3F

NATIONAL TRANSPORTATION SAFETY BOARD

WASHINGTON, D.C.

DAILY RECORD OF FACILITY OPERATION
CLT TRACON AREA MANAGER - JULY 2, 1994

8

PAGE NO.
1 of 1

DATE
July 02, 1994

CHECKED BY

GROUP

DAILY RECORD OF FACILITY OPERATION

LOCATION	IDENTIFICATION	TYPE FACILITY	OPERATING POSITION
Charlotte, NC	CLT	TRACON	Area Manager

TIME (GMT)	REMARKS
0400	P. NICHOLS ON, UCLC. CPL: 127.2 OBS; FLT 101 RVR OBS; ASB-9 CHNL A AND BRACON CHNL 1 IN USE. NOISE SUPR OPERATOR.
1000	J. BARKER ON, ABOVE NOTED.
1045	BRACON CHNL 2 IN USE.
1100	UCLC.
1800	C.A. GENSCH ON, ABOVE NOTED.
1900	UCLC.
2236	ASB-9 E/G ON, BEHINDING E/G ON.
2242	USAL016, DC-9, ON FINAL TO RYLR, PILOT INITIATED GO AROUND, LC-W LOST COMMUNICATION WITH USAL016 AFTER THE GO AROUND WAS INITIATED.
2243	TOWER PERSONNEL OBSERVED SMOKE WING OF RYLR AND NOTIFIED CFR. RECEIVED CALL FROM CHARLOTTE DECEMBER'S AMBULANCE SERVICE/BRCONS, ADVISED THEY WERE RESPONDING TO A REPORT OF HEAVY SMOKE ON OLD DOWD ROAD. AMPLIFICATION NEEDED.
2349	REC/STAND, TWR/AREA MANAGER, TWRP REGARDING USAL016.
2357	USNO, BRACON TWR, WASHINGTON OPERATIONS CENTER/BRACON, REGARDING USAL016.
2350	MAIN AND STANBY RECEIVERS OBS, ASB/AT. RECEIVERS ON EMERGENCY RECEIVERS.
0130	ASB SCHEDULE TO RYLR OBS, ASB/AT.
0210	ASB-9 TRANSFERRED TO RYLR ASB/AT. FROM TO REC/STAND.
0230	ASB SCHEDULE TO RYLR OBS, ASB/AT.
0359	OBS.

JFK

K

I CERTIFY that entries above are correct, that all scheduled operations have been accomplished, except as noted, and that all abnormal occurrences and conditions have been reported.

SIGNATURE(S) OF WATCH SUPERVISOR(S)

