



## **NATIONAL TRANSPORTATION SAFETY BOARD**

Office of Aviation Safety  
Washington, D.C. 20594

April 22, 2016

Attachment 5 – Equipment Logs

# **AIR TRAFFIC CONTROL SPECIALIST'S REPORT**

**CEN15FA190**

# ATTACHMENT 5 // FIGURE 1

This is a screen shot of one page taken from the electronic system status log for the ILS system to runway 02 and runway 20 at Central Illinois Regional Airport (BMI). This log was provided by the Midstates Operational Control

**Column 1 (EVENT DATE)**

Indicated the date and time (UTC) that the logged status change occurred .

**Column 2 (ATOW)**

Indicated the actual Work Center who had maintenance responsibility for that equipment.

**Column 3 (ARTCCID)**

Identifier of the Air Route Traffic Control Center (ARTCC) in which the system fell under, ZAU - Chicago ARTCC.

**Column 4 (SITETYPEID)**

Type of site/equipment being reported on, LOC-Localizer.

**Column 5 (SITELOCID)**

Site identifier, TXN - Identifier for the localizer to runway 02 and LHJ - Identifier for the localizer to runway 20.

**Column 6 (LUID)**

Logical Unit ID, numerical value that indicated the state of the sites being reported.

**Column 7 (ACTUALVALUE)**

Indicated whether that runway was selected or not selected at the time of that reporting.

**Column 8 (POINTDESC)**

Point Description indicated where the actual physical equipment was located.

**Column 9 (STATUS)**

Indicated the status being reported, "Site Data Report" indicated the normal daily Site Data Report polling that occurred at 0913 UTC for runway 20 and 0920 UTC for runway 02. "State Change" indicated that the particular runway was either selected or de-selected.

The highlighted rows show that runway 20 was selected at the time of the 4/6/2016 Site Report (0913 UTC) and remained selected until 4/7/2015 at 1059 UTC when runway 02 was selected.

## ATTACHMENT 5 // FIGURE 1

EVENT_DATE	ATOW	ARTCCID	SITETYPEID	SITELOCID	LUID	ACTUALVALUE	POINTDESC	STATUS
4/8/2015 21:10	WCP25	ZAU	LOC	TXN	2038	NOT SELECTED	Runway	C - State Change
4/8/2015 21:10	WCP25	ZAU	LOC	TXN	2038	SELECTED	Runway	C - State Change
4/8/2015 21:03	WCP25	ZAU	LOC	TXN	2038	NOT SELECTED	Runway	C - State Change
4/8/2015 18:08	WCP25	ZAU	LOC	TXN	2038	SELECTED	Runway	C - State Change
4/8/2015 15:03	WCP25	ZAU	LOC	TXN	2038	NOT SELECTED	Runway	C - State Change
4/8/2015 15:03	WCP25	ZAU	LOC	TXN	2038	SELECTED	Runway	C - State Change
4/8/2015 15:03	WCP25	ZAU	LOC	TXN	2038	NOT SELECTED	Runway	C - State Change
4/8/2015 15:02	WCP25	ZAU	LOC	TXN	2038	SELECTED	Runway	C - State Change
4/8/2015 14:59	WCP25	ZAU	LOC	TXN	2038	NOT SELECTED	Runway	C - State Change
4/8/2015 9:20	WCP25	ZAU	LOC	TXN	2038	SELECTED	Runway	S - Site Data Report
4/8/2015 7:19	WCP25	ZAU	LOC	TXN	2038	SELECTED	Runway	C - State Change
4/7/2015 22:37	WCP25	ZAU	LOC	TXN	2038	NOT SELECTED	Runway	C - State Change
4/7/2015 20:51	WCP25	ZAU	LOC	TXN	2038	SELECTED	Runway	C - State Change
4/7/2015 20:50	WCP25	ZAU	LOC	TXN	2038	NOT SELECTED	Runway	C - State Change
4/7/2015 10:59	WCP25	ZAU	LOC	TXN	2038	SELECTED	Runway	C - State Change
4/7/2015 9:20	WCP25	ZAU	LOC	TXN	2038	NOT SELECTED	Runway	S - Site Data Report
4/6/2015 9:20	WCP25	ZAU	LOC	TXN	2038	NOT SELECTED	Runway	S - Site Data Report
4/8/2015 21:11	WCP25	ZAU	LOC	LHJ	2038	SELECTED	Runway	C - State Change
4/8/2015 21:10	WCP25	ZAU	LOC	LHJ	2038	NOT SELECTED	Runway	C - State Change
4/8/2015 21:05	WCP25	ZAU	LOC	LHJ	2038	SELECTED	Runway	C - State Change
4/8/2015 18:06	WCP25	ZAU	LOC	LHJ	2038	NOT SELECTED	Runway	C - State Change
4/8/2015 15:16	WCP25	ZAU	LOC	LHJ	2038	SELECTED	Runway	C - State Change
4/8/2015 9:13	WCP25	ZAU	LOC	LHJ	2038	NOT SELECTED	Runway	S - Site Data Report
4/7/2015 22:37	WCP25	ZAU	LOC	LHJ	2038	SELECTED	Runway	C - State Change
4/7/2015 20:51	WCP25	ZAU	LOC	LHJ	2038	NOT SELECTED	Runway	C - State Change
4/7/2015 20:50	WCP25	ZAU	LOC	LHJ	2038	SELECTED	Runway	C - State Change
4/7/2015 10:59	WCP25	ZAU	LOC	LHJ	2038	NOT SELECTED	Runway	C - State Change
4/7/2015 9:13	WCP25	ZAU	LOC	LHJ	2038	SELECTED	Runway	S - Site Data Report
4/6/2015 9:13	WCP25	ZAU	LOC	LHJ	2038	SELECTED	Runway	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

EVENT_DATE	SITETYPEID	SITELOCID	LUID	ACTUALVALUE	POINTDESC	STATUS
4/6/2015 9:13	LOC	LHJ	2329		5 Pre Al Dly Tmr	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2420		2015 Year	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2421		4 Month	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2422		6 Day	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2423		9 Hour	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2424		13 Minute	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2425		15 Second	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2426		30 Ins Temp High Lim	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2427		5 Ins Temp Low Lim	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2428		48 Out Temp High Lim	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2429		-30 Out Temp Low Lim	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2020		2015 Year	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2021		4 Month	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2022		6 Day	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2023		9 Hour	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2024		13 Minute	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2025		15 Second	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2026	MAIN	Xmtrr1 Designat	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2027	ANT	Xmtrr1 Config	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2028	ON	Xmtrr1 State	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2029	STANDBY	Xmtrr2 Designat	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	202A	LOAD	Xmtrr2 Config	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	202B	ON	Xmtrr2 State	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	202C	NORMAL	Exec Monitor1	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	202D	NORMAL	Exec Monitor2	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	202E	NORMAL	Standby Monitor1	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	202F	NORMAL	Standby Monitor2	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2030	NORMAL	Field Mon1	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2031	NORMAL	Field Mon2	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2032	NORMAL	Maint Status	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2033	NORMAL	Elec Power Status	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2034	NORMAL	RCSU Comm	S - Site Data Report
4/6/2015 9:13	LOC	LHJ	2035	ENABLE	Remote Access	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/6/2015 9:13 LOC	LHJ	2036 DISCONNECT	Portable Terminal	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2038 SELECTED	Runway	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2039 CLEARED	Sch Poll Flag	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2220	2015 Year	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2221	4 Month	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2222	6 Day	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2223	9 Hour	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2224	13 Minute	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2225	15 Second	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2226 NORMAL	Smoke Detector	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2227 NORMAL	Intrusion Detctr	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2228	21 Inside Temp	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2229	12 Outside Temp	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	222A NORMAL	Obstruction Light	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	222B ENABLE	Smoke Detectr En	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	222C ENABLE	Intr Detectr Ena	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2320	2015 Year	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2321	4 Month	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2322	6 Day	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2323	9 Hour	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2324	13 Minute	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2325	15 Second	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2326	516 Cmpltd Frame Cnt	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2327	0.2 Sec Respns Del	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2328	7 Window Size	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2859	2 MON 1 Maj Rev	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	285A	10 MON 1 Min Rev	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	285B	2 MON 2 Maj Rev	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	285C	10 MON 2 Min Rev	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A20	2015 Year	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A21	4 Month	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A22	6 Day	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A23	9 Hour	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A24	13 Minute	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/6/2015 9:13 LOC	LHJ	2A25		16 Second	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A26	NORMAL	AG1 Modulat Type	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A27	WVFRM 1	AG1 Active Wavfrm	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A28	PASSED	Integrity Status	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A29	NORMAL	Mon1 Exec Bit Sta	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A2A	NORMAL	Mon1 Fld Bit Sta	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A2B	NORMAL	Mon1 Stby Bit Sta	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A2C	NORMAL	Mon1 Wvfrm Prm E	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A2D	NORMAL	Mon1 NV File Er	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A2E	NORMAL	Mon1 A/D Calib	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A2F	NORMAL	Mon1 Audio Cal	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A30	KEYED	Mon1 Loc ID Keying	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A31	Not Monitored	Mon1 DME Keying	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A32	QUADRATURE	AG1 Audio Phasing	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2820		2015 Year	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2821		4 Month	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2822		6 Day	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2823		9 Hour	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2824		13 Minute	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2825		15 Second	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A33	NORMAL	AG2 Modulat Type	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A34	WVFRM 1	AG2 Active Wvfrm	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A35	NORMAL	Mon2 Exec Bit Sta	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A36	NORMAL	Mon2 Fld Bit Sta	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A37	NORMAL	Mon2 Stby Bit Sta	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A38	NORMAL	Mon2 Wvfrm Prm E	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A39	NORMAL	Mon2 NV File Er	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A3A	NORMAL	Mon2 A/D Calib	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A3B	NORMAL	Mon2 Audio Cal	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A3C	KEYED	Mon2 Loc ID Keying	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A3D	Not Monitored	Mon2 DME Keying	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2A3E	QUADRATURE	AG2 Audio Phasing	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3020		2015 Year	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3021		4 Month	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/6/2015 9:13 LOC	LHJ	3022	6 Day	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3023	9 Hour	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3024	13 Minute	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3025	16 Second	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3026	99.8 RF Level	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3027	-0.001 Crs/P DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3028	40 SDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3029	8.2 Ident Mod	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	302B	0.154 Width DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	302D	100.7 Clr RF Lev	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	302E	0.171 Clr Width 1 DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	302F	40.4 Clr SDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3032	0.228 Clr Width 2 DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3034	7998 Crs/Clr Freq Diff	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3035 KEYED	Ident Keying	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3036 NORMAL	RF Channel	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3037 NORMAL	Synthesizer Lock	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3038 NORMAL	Mon A/D Calib	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3039 NORMAL	Mon Exec Bit	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	303A NORMAL	Cable Fault	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2826 LOCALIZER	Station Type	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2827 DUAL FREQ	Xmtr Type	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2828 Not Monitored	GS Ant Sngl Freq	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2829 Not Monitored	GS Ant Dual Freq	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	282A BOTH	Xmtr Present	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	282B BOTH	Monitor Present	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	282C BOTH	Field Mon Present	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	282D BOTH	Aud Generator Pr	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	282E YES	Hot Standby	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	282F KEYED	Mon1 DME Keying	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2830 KEYED	Mon2 DME Keying	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2831	5 Time Difference	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2832 111.90/331.10MH	RF Channel	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2833 XMTTR 1	Main Xmtr	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/6/2015 9:13 LOC	LHJ	2834	XMTTR 1	On Antenna	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2839	XMTTR 2	On Load	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	283F	ENABLE	Interlock	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2843		1 RCSU Station Add	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2852	DISABLED	Auto Fault Diag	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2854		99 Integ Test Period	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2855	CAT II / III	Category	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2856	AVAILABLE	RMT CAT I CMDS	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2857		3 RMMC Maj Rev	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	2858		30 RMMC Min Rev	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3321		4 Month	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3322		6 Day	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3323		9 Hour	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3324		13 Minute	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3325		17 Second	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3326		102.4 RF Level	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3327		0 Crs/P DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3328		40 SDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	332B		0.155 Width DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	332D		102.3 Clr RF Lev	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	332E		0 Clr Width 1 DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	332F		39.9 Clr SDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3332		0.155 Clr Width 2 DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3334		8001 Crs/Clr Freq Diff	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3336	NORMAL	RF Channel	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3337	NORMAL	Synthesizer Lock	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3338	NORMAL	Mon Stby Bit	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3420		2015 Year	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3421		4 Month	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3422		6 Day	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3423		9 Hour	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3424		13 Minute	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3425		17 Second	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3426	NORMAL	FFM1 RF Signal	S - Site Data Report



## ATTACHMENT 5 // FIGURE 2

4/6/2015 9:13 LOC	LHJ	3427		0.002 FFM1 DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	342A	NORMAL	FFM2 RF Signal	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	342B		0.001 FFM2 DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	342C		0 Mon1 Fld Bit	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	342D		0 Mon2 Fld Bit	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3120		2015 Year	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3121		4 Month	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3122		6 Day	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3123		9 Hour	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3124		13 Minute	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3125		17 Second	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3126		99.8 RF Level	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3127		-0.001 Crs/P DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3128		40 SDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3129		8 Ident Mod	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	312B		0.155 Width DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	312D		101 Clr RF Lev	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	312E		0.166 Clr Width 1 DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	312F		40 Clr SDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3132		0.228 Clr Width 2 DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3134		8007 Crs/Clr Freq Diff	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3135	KEYED	Ident Keying	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3136	Not Monitored	RF Channel	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3137	Not Monitored	Synthesizer Lock	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3138	NORMAL	Mon A/D Calib	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3139	NORMAL	Mon Exec Bit	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	313A	NORMAL	Cable Fault	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3220		2015 Year	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3221		4 Month	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3222		6 Day	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3223		9 Hour	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3224		13 Minute	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3225		17 Second	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3226		102.5 RF Level	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/6/2015 9:13 LOC	LHJ	3227	0 Crs/P DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3228	39.9 SDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	322B	0.155 Width DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	322D	102.4 Clr RF Lev	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	322E	0 Clr Width 1 DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	322F	39.9 Clr SDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3232	0.155 Clr Width 2 DDM	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3234	8002 Crs/Clr Freq Diff	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3236 Not Monitored	RF Channel	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3237 Not Monitored	Synthesizer Lock	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3238 NORMAL	Mon Stby Bit	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3320	2015 Year	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3566	0.255 Clr Wid2 DDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3567	0.205 Clr Wid2 DDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	356E	8500 Crs/Clr F Dif AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	356F	7500 Crs/Clr F Dif AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3570	8375 Crs/Clr F Dif PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3571	7625 Crs/Clr F Dif PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3620	2015 Year	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3621	4 Month	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3622	6 Day	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3623	9 Hour	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3624	13 Minute	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3625	18 Second	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3626	4 Alarm Delay Time	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3628	100 RF Level AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3629	93 RF Level AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	362A	100 RF Level PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	362B	93.5 RF Level PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	362D	0.008 Crs/P DDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	362E	-0.008 Crs/P DDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	362F	0.005 Crs/P DDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3630	-0.005 Crs/P DDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3632	44 SDM AL H	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/6/2015 9:13 LOC	LHJ	3633	36 SDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3634	43 SDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3635	37 SDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3637	10 Ident Mod AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3638	6 Ident Mod AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3639	9 Ident Mod PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	363A	7 Ident Mod PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3641	0.168 Width DDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3642	0.144 Width DDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3643	0.164 Width DDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3644	0.148 Width DDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	364B	100 Clr RF Lev AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	364C	94 Clr RF Lev AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	364D	100 Clr RF Lev PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	364E	94.5 Clr RF Lev PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3650	0.195 Clr Wid1 DDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3651	0.152 Clr Wid1 DDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3652	0.19 Clr Wid1 DDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3653	0.155 Clr Wid1 DDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3655	43.5 Clr SDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3656	37 Clr SDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3657	43 Clr SDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3658	37.5 Clr SDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3664	0.26 Clr Wid2 DDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3665	0.2 Clr Wid2 DDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3666	0.255 Clr Wid2 DDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3667	0.205 Clr Wid2 DDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	366E	8500 Crs/Clr F Dif AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	366F	7500 Crs/Clr F Dif AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3670	8375 Crs/Clr F Dif PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3671	7625 Crs/Clr F Dif PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3520	2015 Year	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3521	4 Month	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3522	6 Day	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/6/2015 9:13 LOC	LHJ	3523	9 Hour	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3524	13 Minute	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3525	18 Second	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3526	4 Alarm Delay Time	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3528	100 RF Level AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3529	93 RF Level AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	352A	100 RF Level PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	352B	93.5 RF Level PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	352D	0.008 Crs/P DDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	352E	-0.008 Crs/P DDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	352F	0.005 Crs/P DDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3530	-0.005 Crs/P DDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3532	44 SDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3533	36 SDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3534	43 SDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3535	37 SDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3537	10 Ident Mod AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3538	6 Ident Mod AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3539	9 Ident Mod PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	353A	7 Ident Mod PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3541	0.168 Width DDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3542	0.144 Width DDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3543	0.164 Width DDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3544	0.148 Width DDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	354B	100 Clr RF Lev AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	354C	94 Clr RF Lev AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	354D	100 Clr RF Lev PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	354E	94.5 Clr RF Lev PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3550	0.195 Clr Wid1 DDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3551	0.152 Clr Wid1 DDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3552	0.19 Clr Wid1 DDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3553	0.155 Clr Wid1 DDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3555	43.5 Clr SDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3556	37 Clr SDM AL L	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/6/2015 9:13 LOC	LHJ	3557	43 Clr SDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3558	37.5 Clr SDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3564	0.26 Clr Wid2 DDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3565	0.2 Clr Wid2 DDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	372D	0.007 Crs/P DDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	372B	97 RF Level PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	372F	0.004 Crs/P DDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3730	-0.004 Crs/P DDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3732	43 SDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3733	37 SDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3734	42 SDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3735	38 SDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3741	0.168 Width DDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3742	0.144 Width DDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3743	0.164 Width DDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3744	0.148 Width DDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	374B	100 Clr RF Lev AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	374C	95 Clr RF Lev AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	374D	100 Clr RF Lev PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	374E	97 Clr RF Lev PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3750	0.007 Clr Wid1 DDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3751	-0.007 Clr Wid1 DDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3752	0.004 Clr Wid1 DDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3753	-0.004 Clr Wid1 DDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3755	43 Clr SDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3756	37 Clr SDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3757	42 Clr SDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3758	38 Clr SDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3764	0.168 Clr Wid2 DDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3765	0.145 Clr Wid2 DDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3766	0.164 Clr Wid2 DDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3767	0.148 Clr Wid2 DDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	376E	8500 Crs/Clr F Dif AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	376F	7500 Crs/Clr F Dif AL L	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/6/2015 9:13 LOC	LHJ	3770	8375 Crs/Clr F Dif PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3771	7625 Crs/Clr F Dif PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3720	2015 Year	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3721	4 Month	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3722	6 Day	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3723	9 Hour	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3724	13 Minute	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3725	18 Second	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3726	15 Alarm Delay Time	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3728	100 RF Level AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3729	95 RF Level AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	372A	100 RF Level PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	372E	-0.007 Crs/P DDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3820	2015 Year	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3871	7625 Crs/Clr F Dif PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3822	6 Day	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3823	9 Hour	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3824	13 Minute	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3825	19 Second	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3826	15 Alarm Delay Time	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3828	100 RF Level AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3829	95 RF Level AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	382A	100 RF Level PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	382B	97 RF Level PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	382D	0.007 Crs/P DDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	382E	-0.007 Crs/P DDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	382F	0.004 Crs/P DDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3830	-0.004 Crs/P DDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3832	43 SDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3833	37 SDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3834	42 SDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3835	38 SDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3841	0.168 Width DDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3842	0.144 Width DDM AL L	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/6/2015 9:13 LOC	LHJ	3843	0.164 Width DDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3844	0.148 Width DDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	384B	100 Clr RF Lev AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	384C	95 Clr RF Lev AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	384D	100 Clr RF Lev PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	384E	97 Clr RF Lev PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3850	0.007 Clr Wid1 DDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3851	-0.007 Clr Wid1 DDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3852	0.004 Clr Wid1 DDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3853	-0.004 Clr Wid1 DDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3855	43 Clr SDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3856	37 Clr SDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3857	42 Clr SDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3858	38 Clr SDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3864	0.168 Clr Wid2 DDM AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3865	0.144 Clr Wid2 DDM AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3866	0.164 Clr Wid2 DDM PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3867	0.148 Clr Wid2 DDM PA L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	386E	8500 Crs/Clr F Dif AL H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	386F	7500 Crs/Clr F Dif AL L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3870	8375 Crs/Clr F Dif PA H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3821	4 Month	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4136	0.5 Pwr Supply Gnd HL	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4137	-0.5 Pwr Supply Gnd LL	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3920	2015 Year	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3921	4 Month	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3922	6 Day	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3923	9 Hour	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3924	13 Minute	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3925	19 Second	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3926	90 FFM1 Al Del Time	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	392D	0.009 FFM1 DDM AL HL	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	392E	-0.009 FFM1 DDM AL LL	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	392F	0.006 FFM1 DDM PA HL	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/6/2015 9:13 LOC	LHJ	3930	-0.006 FFM1 DDM PA LL	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	393B	90 FFM2 AI Del Time	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3941	0.009 FFM2 DDM AL HL	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3942	-0.009 FFM2 DDM AL LL	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3943	0.006 FFM2 DDM PA HL	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	3944	-0.006 FFM2 DDM PA LL	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4020	2015 Year	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4021	4 Month	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4022	6 Day	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4023	9 Hour	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4024	13 Minute	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4025	19 Second	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4026	26.94 Eqpmt1 Bus Vltg	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4027	27.17 Eqpmt2 Bus Vltg	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4028	4.92 5V Supply	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	402A	14.65 15V Supply	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	402C	-14.99 -15V Supply	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	402E	0 Pwr Supply Gnd	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4030 NO	AC Power Failure	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4031 NO	E1 Rev Pwr Fail	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4032 NO	E2 Rev Pwr Fail	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4033 NO	RMS-Mon1 Link Fail	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4034 NO	RMS-Mon2 Link Fail	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4035 NO	Xmtr Integ Alert	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4036 NO	Integ Test Abort	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4037 NORMAL	Int Tst DDM Aler	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4120	2015 Year	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4121	4 Month	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4122	6 Day	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4123	9 Hour	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4124	13 Minute	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4125	19 Second	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4126	30 Eqp Bus1 Vlt HL	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4127	22 Eqp Bus1 Vlt LL	S - Site Data Report



## ATTACHMENT 5 // FIGURE 2

4/6/2015 9:13 LOC	LHJ	4128		30 Eqp Bus2 Vlt HL	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4129		22 Eqp Bus2 Vlt LL	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	412A		5.5 5V Supply HL	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	412B		4.5 5V Supply LL	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	412E		15.5 15V Supply H	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	412F		14 15V Supply L	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4132		-14 -15V Supp HL	S - Site Data Report
4/6/2015 9:13 LOC	LHJ	4133		-15.5 -15V Supp LL	S - Site Data Report
4/7/2015 7:13 LOC	LHJ	342B		-0.008 FFM2 DDM	P - Unacknowledged Alert
4/7/2015 7:13 LOC	LHJ	3427		-0.009 FFM1 DDM	N - Unacknowledged Alarm
4/7/2015 7:13 LOC	LHJ	3427		-0.008 FFM1 DDM	P - Unacknowledged Alert
4/7/2015 7:13 LOC	LHJ	342B		-0.009 FFM2 DDM	N - Unacknowledged Alarm
4/7/2015 7:13 LOC	LHJ	3427		-0.003 FFM1 DDM	R - Return
4/7/2015 7:13 LOC	LHJ	342B		-0.004 FFM2 DDM	R - Return
4/7/2015 7:17 LOC	LHJ	3427		-0.01 FFM1 DDM	N - Unacknowledged Alarm
4/7/2015 7:17 LOC	LHJ	342B		-0.009 FFM2 DDM	N - Unacknowledged Alarm
4/7/2015 7:17 LOC	LHJ	342B		-0.005 FFM2 DDM	R - Return
4/7/2015 7:17 LOC	LHJ	3427		-0.006 FFM1 DDM	P - Unacknowledged Alert
4/7/2015 7:17 LOC	LHJ	342B		-0.006 FFM2 DDM	P - Unacknowledged Alert
4/7/2015 7:17 LOC	LHJ	3427		-0.005 FFM1 DDM	R - Return
4/7/2015 9:13 LOC	LHJ	202E	NORMAL	Standby Monitor1	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	202F	NORMAL	Standby Monitor2	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2030	NORMAL	Field Mon1	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2031	NORMAL	Field Mon2	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2032	NORMAL	Maint Status	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2033	NORMAL	Elec Power Status	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2034	NORMAL	RCSU Comm	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2035	ENABLE	Remote Access	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2036	DISCONNECT	Portable Terminal	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2038	SELECTED	Runway	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2039	CLEARED	Sch Poll Flag	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2220		2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2221		4 Month	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2222		7 Day	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/7/2015 9:13 LOC	LHJ	2223		9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2224		13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2225		4 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2226	NORMAL	Smoke Detector	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2227	NORMAL	Intrusion Detctr	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2228		24 Inside Temp	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2229		13 Outside Temp	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	222A	NORMAL	Obstruction Light	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	222B	ENABLE	Smoke Detectr En	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	222C	ENABLE	Intr Detectr Ena	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2023		9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2022		7 Day	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2021		4 Month	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	202D	NORMAL	Exec Monitor2	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	202C	NORMAL	Exec Monitor1	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	202B	ON	Xmttr2 State	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	202A	LOAD	Xmttr2 Config	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2029	STANDBY	Xmttr2 Designat	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2028	ON	Xmttr1 State	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2027	ANT	Xmttr1 Config	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2026	MAIN	Xmttr1 Designat	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2020		2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2024		13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2025		4 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2322		7 Day	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2321		4 Month	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2320		2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2329		5 Pre Al Dly Tmr	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2323		9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2327		0.2 Sec Respns Del	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2326		516 Cmpltd Frame Cnt	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2325		4 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2324		13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2328		7 Window Size	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/7/2015 9:13 LOC	LHJ	2424		13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2423		9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2426		30 Ins Temp High Lim	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2427		5 Ins Temp Low Lim	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2428		48 Out Temp High Lim	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2429		-30 Out Temp Low Lim	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2425		4 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2422		7 Day	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2421		4 Month	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2420		2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A38	NORMAL	Mon2 Wvfrm Prm E	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A39	NORMAL	Mon2 NV File Er	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A3A	NORMAL	Mon2 A/D Calib	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A3B	NORMAL	Mon2 Audio Cal	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A3C	KEYED	Mon2 Loc ID Keying	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A3D	Not Monitored	Mon2 DME Keying	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A3E	QUADRATURE	AG2 Audio Phasing	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3020		2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3021		4 Month	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3022		7 Day	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3023		9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3024		13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3025		5 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3026		99.8 RF Level	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3027		0.001 Crs/P DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3028		40 SDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3029		8.2 Ident Mod	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	302B		0.155 Width DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	302D		100.4 Clr RF Lev	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	302E		0.172 Clr Width 1 DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	302F		40.4 Clr SDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3032		0.229 Clr Width 2 DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3034		7999 Crs/Clr Freq Diff	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3035	KEYED	Ident Keying	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/7/2015 9:13 LOC	LHJ	3036 NORMAL	RF Channel	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3037 NORMAL	Synthesizer Lock	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3038 NORMAL	Mon A/D Calib	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3039 NORMAL	Mon Exec Bit	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	303A NORMAL	Cable Fault	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2820	2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2821	4 Month	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2822	7 Day	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2823	9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2824	13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2825	4 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2826 LOCALIZER	Station Type	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2827 DUAL FREQ	Xmttr Type	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2828 Not Monitored	GS Ant Sngl Freq	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2829 Not Monitored	GS Ant Dual Freq	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	282A BOTH	Xmttr Present	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	282B BOTH	Monitor Present	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	282C BOTH	Field Mon Present	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	282D BOTH	Aud Generator Pr	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	282E YES	Hot Standby	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	282F KEYED	Mon1 DME Keying	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2830 KEYED	Mon2 DME Keying	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2831	5 Time Difference	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2832 111.90/331.10MH	RF Channel	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2833 XMTTR 1	Main Xmttr	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2834 XMTTR 1	On Antenna	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2839 XMTTR 2	On Load	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	283F ENABLE	Interlock	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2843	1 RCSU Station Add	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2852 DISABLED	Auto Fault Diag	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2854	99 Integ Test Period	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2855 CAT II / III	Category	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2856 AVAILABLE	RMT CAT I CMDS	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2857	3 RMMC Maj Rev	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/7/2015 9:13 LOC	LHJ	2858		30 RMMC Min Rev	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2859		2 MON 1 Maj Rev	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	285A		10 MON 1 Min Rev	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	285B		2 MON 2 Maj Rev	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	285C		10 MON 2 Min Rev	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A20		2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A21		4 Month	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A22		7 Day	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A23		9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A24		13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A25		4 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A26	NORMAL	AG1 Modulat Type	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A27	WVFRM 1	AG1 Active Wavfrm	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A28	PASSED	Integrity Status	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A29	NORMAL	Mon1 Exec Bit Sta	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A2A	NORMAL	Mon1 Fld Bit Sta	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A2B	NORMAL	Mon1 Stby Bit Sta	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A2C	NORMAL	Mon1 Wvfrm Prm E	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A2D	NORMAL	Mon1 NV File Er	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A2E	NORMAL	Mon1 A/D Calib	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A2F	NORMAL	Mon1 Audio Cal	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A30	KEYED	Mon1 Loc ID Keying	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A31	Not Monitored	Mon1 DME Keying	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A32	QUADRATURE	AG1 Audio Phasing	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A33	NORMAL	AG2 Modulat Type	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A34	WVFRM 1	AG2 Active Wvfrm	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A35	NORMAL	Mon2 Exec Bit Sta	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A36	NORMAL	Mon2 Fld Bit Sta	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	2A37	NORMAL	Mon2 Stby Bit Sta	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3232		0.155 Clr Width 2 DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	322F		39.9 Clr SDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3236	Not Monitored	RF Channel	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3237	Not Monitored	Synthesizer Lock	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3238	NORMAL	Mon Stby Bit	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/7/2015 9:13 LOC	LHJ	3320	2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3321	4 Month	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3322	7 Day	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3323	9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3324	13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3325	6 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3326	102.3 RF Level	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3327	-0.001 Crs/P DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3328	40 SDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	332B	0.155 Width DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	332D	102.1 Clr RF Lev	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	332E	0 Clr Width 1 DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	332F	39.9 Clr SDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3332	0.157 Clr Width 2 DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3334	7997 Crs/Clr Freq Diff	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3336 NORMAL	RF Channel	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3337 NORMAL	Synthesizer Lock	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3338 NORMAL	Mon Stby Bit	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3120	2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3121	4 Month	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3122	7 Day	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3123	9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3124	13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3125	6 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3126	99.9 RF Level	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3127	-0.001 Crs/P DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3128	40 SDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3129	8 Ident Mod	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	312B	0.155 Width DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	312D	100.6 Clr RF Lev	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	312E	0.175 Clr Width 1 DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	312F	40.2 Clr SDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3132	0.228 Clr Width 2 DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3134	8001 Crs/Clr Freq Diff	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/7/2015 9:13 LOC	LHJ	3135 KEYED	Ident Keying	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3136 Not Monitored	RF Channel	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3137 Not Monitored	Synthesizer Lock	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3138 NORMAL	Mon A/D Calib	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3139 NORMAL	Mon Exec Bit	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	313A NORMAL	Cable Fault	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3220	2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3221	4 Month	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3222	7 Day	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3223	9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3224	13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3225	6 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3226	102.3 RF Level	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3227	0 Crs/P DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3228	39.9 SDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	322B	0.155 Width DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	322D	102.1 Clr RF Lev	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	322E	-0.002 Clr Width 1 DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3234	8008 Crs/Clr Freq Diff	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	354D	100 Clr RF Lev PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	354C	94 Clr RF Lev AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3550	0.195 Clr Wid1 DDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3551	0.152 Clr Wid1 DDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3552	0.19 Clr Wid1 DDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3553	0.155 Clr Wid1 DDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3555	43.5 Clr SDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3556	37 Clr SDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3557	43 Clr SDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3558	37.5 Clr SDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3564	0.26 Clr Wid2 DDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3565	0.2 Clr Wid2 DDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3566	0.255 Clr Wid2 DDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3567	0.205 Clr Wid2 DDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	356E	8500 Crs/Clr F Dif AL H	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/7/2015 9:13 LOC	LHJ	356F	7500 Crs/Clr F Dif AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3570	8375 Crs/Clr F Dif PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3571	7625 Crs/Clr F Dif PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3420	2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3421	4 Month	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3422	7 Day	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3423	9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3424	13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3425	6 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3426 NORMAL	FFM1 RF Signal	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3427	0 FFM1 DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	342A NORMAL	FFM2 RF Signal	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	342B	0 FFM2 DDM	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	342C	0 Mon1 Fld Bit	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	342D	0 Mon2 Fld Bit	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3520	2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3521	4 Month	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3522	7 Day	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3523	9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3524	13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3525	6 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3526	4 Alarm Delay Time	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3528	100 RF Level AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3529	93 RF Level AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	352A	100 RF Level PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	352B	93.5 RF Level PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	352D	0.008 Crs/P DDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	352E	-0.008 Crs/P DDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	352F	0.005 Crs/P DDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3530	-0.005 Crs/P DDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3532	44 SDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3533	36 SDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3534	43 SDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3535	37 SDM PA L	S - Site Data Report



## ATTACHMENT 5 // FIGURE 2

4/7/2015 9:13 LOC	LHJ	3537	10 Ident Mod AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3538	6 Ident Mod AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3539	9 Ident Mod PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	353A	7 Ident Mod PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3541	0.168 Width DDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3542	0.144 Width DDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3543	0.164 Width DDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3544	0.148 Width DDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	354B	100 Clr RF Lev AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	354E	94.5 Clr RF Lev PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3620	2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3621	4 Month	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3622	7 Day	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3623	9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3624	13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3625	7 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3626	4 Alarm Delay Time	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3628	100 RF Level AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3629	93 RF Level AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	362A	100 RF Level PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	362B	93.5 RF Level PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	362D	0.008 Crs/P DDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	362E	-0.008 Crs/P DDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	362F	0.005 Crs/P DDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3630	-0.005 Crs/P DDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3632	44 SDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3633	36 SDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3634	43 SDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3635	37 SDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3637	10 Ident Mod AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3638	6 Ident Mod AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3639	9 Ident Mod PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	363A	7 Ident Mod PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3641	0.168 Width DDM AL H	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/7/2015 9:13 LOC	LHJ	3642	0.144 Width DDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3643	0.164 Width DDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3644	0.148 Width DDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	364B	100 Clr RF Lev AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	364C	94 Clr RF Lev AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	364D	100 Clr RF Lev PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	364E	94.5 Clr RF Lev PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3650	0.195 Clr Wid1 DDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3651	0.152 Clr Wid1 DDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3652	0.19 Clr Wid1 DDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3653	0.155 Clr Wid1 DDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3655	43.5 Clr SDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3656	37 Clr SDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3657	43 Clr SDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3658	37.5 Clr SDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3664	0.26 Clr Wid2 DDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3665	0.2 Clr Wid2 DDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3666	0.255 Clr Wid2 DDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3667	0.205 Clr Wid2 DDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	366E	8500 Crs/Clr F Dif AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	366F	7500 Crs/Clr F Dif AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3670	8375 Crs/Clr F Dif PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3671	7625 Crs/Clr F Dif PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3720	2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3721	4 Month	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3722	7 Day	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3723	9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3724	13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3725	7 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3726	15 Alarm Delay Time	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3728	100 RF Level AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3729	95 RF Level AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	372A	100 RF Level PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	372B	97 RF Level PA L	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/7/2015 9:13 LOC	LHJ	372D	0.007 Crs/P DDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	372E	-0.007 Crs/P DDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	372F	0.004 Crs/P DDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3730	-0.004 Crs/P DDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3732	43 SDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3733	37 SDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3734	42 SDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3735	38 SDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3741	0.168 Width DDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3742	0.144 Width DDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3743	0.164 Width DDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3744	0.148 Width DDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	374B	100 Clr RF Lev AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	374C	95 Clr RF Lev AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	374D	100 Clr RF Lev PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	374E	97 Clr RF Lev PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3750	0.007 Clr Wid1 DDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3751	-0.007 Clr Wid1 DDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3752	0.004 Clr Wid1 DDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3753	-0.004 Clr Wid1 DDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3755	43 Clr SDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3756	37 Clr SDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3757	42 Clr SDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3758	38 Clr SDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3764	0.168 Clr Wid2 DDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3765	0.145 Clr Wid2 DDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3766	0.164 Clr Wid2 DDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3767	0.148 Clr Wid2 DDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	376E	8500 Crs/Clr F Dif AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	376F	7500 Crs/Clr F Dif AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3770	8375 Crs/Clr F Dif PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3771	7625 Crs/Clr F Dif PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3926	90 FFM1 Al Del Time	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	392D	0.009 FFM1 DDM AL HL	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/7/2015 9:13 LOC	LHJ	392E	-0.009 FFM1 DDM AL LL	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	392F	0.006 FFM1 DDM PA HL	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3930	-0.006 FFM1 DDM PA LL	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	393B	90 FFM2 AI Del Time	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3941	0.009 FFM2 DDM AL HL	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3942	-0.009 FFM2 DDM AL LL	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3943	0.006 FFM2 DDM PA HL	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3944	-0.006 FFM2 DDM PA LL	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3820	2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3821	4 Month	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3822	7 Day	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3823	9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3824	13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3825	8 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3826	15 Alarm Delay Time	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3828	100 RF Level AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3829	95 RF Level AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	382A	100 RF Level PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	382B	97 RF Level PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	382D	0.007 Crs/P DDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	382E	-0.007 Crs/P DDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	382F	0.004 Crs/P DDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3830	-0.004 Crs/P DDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3832	43 SDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3833	37 SDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3834	42 SDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3835	38 SDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3841	0.168 Width DDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3842	0.144 Width DDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3843	0.164 Width DDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3844	0.148 Width DDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	384B	100 Clr RF Lev AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	384C	95 Clr RF Lev AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	384D	100 Clr RF Lev PA H	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/7/2015 9:13 LOC	LHJ	384E	97 Clr RF Lev PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3850	0.007 Clr Wid1 DDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3851	-0.007 Clr Wid1 DDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3852	0.004 Clr Wid1 DDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3853	-0.004 Clr Wid1 DDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3855	43 Clr SDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3856	37 Clr SDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3857	42 Clr SDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3858	38 Clr SDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3864	0.168 Clr Wid2 DDM AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3865	0.144 Clr Wid2 DDM AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3866	0.164 Clr Wid2 DDM PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3867	0.148 Clr Wid2 DDM PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	386E	8500 Crs/Clr F Dif AL H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	386F	7500 Crs/Clr F Dif AL L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3870	8375 Crs/Clr F Dif PA H	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3871	7625 Crs/Clr F Dif PA L	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3920	2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3921	4 Month	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3922	7 Day	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3923	9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3924	13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	3925	8 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	4020	2015 Year	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	4037 NORMAL	Int Tst DDM Aler	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	4022	7 Day	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	4023	9 Hour	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	4024	13 Minute	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	4025	8 Second	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	4026	26.94 Eqpmt1 Bus Vltg	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	4027	27.12 Eqpmt2 Bus Vltg	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	4028	4.95 5V Supply	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	402A	14.55 15V Supply	S - Site Data Report
4/7/2015 9:13 LOC	LHJ	402C	-14.93 -15V Supply	S - Site Data Report

## ATTACHMENT 5 // FIGURE 2

4/7/2015 9:13	LOC	LHJ	402E	0 Pwr Supply Gnd	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4030 NO	AC Power Failure	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4031 NO	E1 Rev Pwr Fail	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4032 NO	E2 Rev Pwr Fail	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4033 NO	RMS-Mon1 Link Fail	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4034 NO	RMS-Mon2 Link Fail	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4035 NO	Xmtr Integ Alert	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4036 NO	Integ Test Abort	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4021	4 Month	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4120	2015 Year	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4121	4 Month	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4122	7 Day	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4123	9 Hour	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4124	13 Minute	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4125	8 Second	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4126	30 Eqp Bus1 Vlt HL	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4127	22 Eqp Bus1 Vlt LL	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4128	30 Eqp Bus2 Vlt HL	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4129	22 Eqp Bus2 Vlt LL	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	412A	5.5 5V Supply HL	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	412B	4.5 5V Supply LL	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	412E	15.5 15V Supply H	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	412F	14 15V Supply L	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4132	-14 -15V Supp HL	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4133	-15.5 -15V Supp LL	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4136	0.5 Pwr Supply Gnd HL	S - Site Data Report	
4/7/2015 9:13	LOC	LHJ	4137	-0.5 Pwr Supply Gnd LL	S - Site Data Report	
4/7/2015 10:59	LOC	LHJ	202B	ILOCKED OFF	Xmtr2 State	C - State Change