



**Photo 1 – View of damaged vertical stabilizer and rudder of N704VM (Photo courtesy of the airport operations)**



**Photo 2 – View of internal rudder damage of N704VM (Photo courtesy of the student pilot)**