



Photo 1 – View of damage to firewall (courtesy of the FAA)



Photo 2 – View of damage to upper engine mount (courtesy of the FAA)