

DAILY RECORD OF FACILITY OPERATION				PAGE NO Page 1 of 2
				DATE Jan 27, 2016
LOCATION Detroit, MI	IDENTIFICATION DTW	TYPE FACILITY ATCT	OPERATING POSITION DTW Front-Line Manager	CHECKED BY AIR TRAFFIC MANAGER Stephen W. Ritchey
UTC TIME	REMARKS			
0500	M. HOLT ON SOUTH FLOW, WCLC, ASDE-X ONLINE, RWYS 22L, 21R, 21L, 27L, 27R, CLSD, SECON LEVEL YELLOW CFPL: DELTA COM SHOUT LINE OTS. (MOCC-DS) CFPL: DO NOT SWITCH SERVERS AT FD/CD POSITION. IF YOU NEED TO ADVISE TECH OPS. CFPL: TOWER HAS NO CONTROL OF ROTATING BEACON CFPL: RWSL OTM; EXPECTED RETURN 11/9 @ 1700Z (TECH OPS-DH) CFPL: RY 22R AND 22L RUNWAY EDGE SIGNS WCAA CONTROL UFA CFPL: BM24 SIDE CAR FOR TELEPHONE IN THE TOWER OTS PER JM. (MOCC-MW) CFPL: 27R ILS OTS. CFPL: RY 22L MALSR CAN NOT BE USED WITH HIGH SETTING AND FLASHERS, ALL OTHER OPERATIONS NORMAL CFPL: RY21R REILS RIGHT BANK INTERMITTENT. MOCC NOTIFIED RM/RF. -- MH			
0700	J DOLFUS ON, ABV NOTED -- PD			
0944	RWYS 21L AND 27L OPEN -- PD			
1024	RWYS 22L AND 21R OPEN -- PD			
1030	Z. LORENZ ON, ABV NOTED. -- LO			
1207	R. FERGUSON ON. -- RF			
1246	M6 CLSD DUE TO FOD. -- RF			
1252	M6 OPEN. -- RF			
1302	WCLC. -- RF			
1316	DTW-M-2016/01/27-0001 -- FLG3860 -- RF			
1343	RY27L CLSD. -- RF			
1408	L BIRD ON, ABOVE NOTED -- MB			
1408	D21 ATC ALERT UNTIL 1800 DUE TO PTK SITE OUT -- MB			
1412	RY 22R CLSD -- MB			
1450	RY22R OPEN. -- RF			
1514	R. FERGUSON ON. -- RF			
1527	JUNCTION LEVEL WATER FOUNTAIN USABLE BUT PARTS ON ORDER. MOCC NOTIFIED RF/DE. -- RF			
1614	RY21L CLSD. -- RF			
I CERTIFY that entries above are correct, that all scheduled operations have been accomplished except as noted, and that all abnormal occurrences and conditions have been recorded.		SIGNATURE(S) OF WATCH SUPERVISOR(S)		

DAILY RECORD OF FACILITY OPERATION				PAGE NO Page 2 of 2	
				DATE Jan 27, 2016	
LOCATION Detroit, MI		IDENTIFICATION DTW	TYPE FACILITY ATCT	OPERATING POSITION DTW Front-Line Manager	CHECKED BY
				AIR TRAFFIC MANAGER Stephen W. Ritchey	
UTC TIME		REMARKS			
1704		RY21L AND 27L OPEN. -- RF			
1724		B YAX ON, ABV NOTED. -- BY			
2041		WCAA ADVISED THAT OPS 371 ON THE MOVEMENT AREA APPEARS TO HAVE AN INOP TRANSPONDER. -- BY			
2100		WCLC -- BY			
2313		ABV NOTED. -- VM			
0021		B YAX ON, ABV NOTED. -- BY			
E	0111	RY22L MALSR OFM 0300-0500Z -- BY			
E	0130	RY4R ILS OFM 0130-0400Z -- BY			
0250		Z. LORENZ ON, ABV NOTED. -- LO			
E	0301	22L MALSR OTM. -- LO			
E	0316	RY4R ILS OFM 0130-0400Z -- LO			
0330		R. BERRIEN ON, ABOVE NOTED. -- AB			
E	0415	RY22L MALSR RTS. -- AB			
0453		RWY'S 22R, 21R, 21L, 27L CLOSED. -- AB			
0459		COB. -- AB			
I CERTIFY that entries above are correct, that all scheduled operations have been accomplished except as noted, and that all abnormal occurrences and conditions have been recorded.			SIGNATURES(S) OF WATCH SUPERVISOR(S)		