

DAILY RECORD OF FACILITY OPERATION				PAGE NO
				Page 1 of 1
LOCATION North Canton, OH				DATE
				Nov 10, 2015
IDENTIFICATION CAK		TYPE FACILITY ATCT		OPERATING POSITION
				CAK ATCT
CHECKED BY 				AIR TRAFFIC MANAGER
				David C. Zakaski
UTC TIME	REMARKS			
0500	J. Deis on ABV noted. WCLC. ASP RLSD to ZOB. CFPL: SECON baseline. ILS RWY 1 and ILS RWY 5 APCH in use, DEP RWY 1. CFPL: ASOS internet wire in tower frayed, connection intermittent. CAK WX Observer/NWS ntfed. CFPL: 127.05 Main and STBY TX OTS. TPG MOCC. -- JA			
1019	ILS RWY 19 and ILS RWY 23 APCH in use, DEP RWY 23. -- WS			
1045	R. Ramsdell on ABV noted. -- JA			
1100	ASP returned from ZOB. RADAR OPN in TWR. -- JA			
E 1200	CONRAC making intermittent loud vibrating noise. MOCC/DST notified. -- RL			
1220	RADAR OPN in TRACON. -- BM			
1240	MSAW checks completed, WCLC. -- BM			
1253	L. Blackman on ABV noted. -- RL			
E 1433	MAIN TX/RX RLSD TO MAINTENCE 1500-2000Z MOCC/DME -- BM			
E 1436	CONRAC making intermittent loud vibrating noise. MOCC/DST notified. RTS/JV -- BM			
1603	W. Schaber on ABV noted. -- BM			
1757	MSAW checks completed, WCLC. -- WS			
1821	D. McKenzie on, ABV noted. -- DM			
2005	K. Thomas on ABV noted. -- KT			
2020	1958Z AIRCRAFT ACCIDENT EFT1526/H25B CRASHED DURING LANDING, ROC/PZ, ATM, HUB, NATCA/OL NTFD -- KT			
E 2047	AKR LOC OTS UFA -- KT			
2053	ILS RWY 23 APCH in use, DEP RWY 23. -- KT			
0049	RADAR OPN in TWR. -- KT			
E 0106	AKR LOC OTS UFA. RTS -- KT			
0135	M. Wilson on ABV noted. -- MW			
0310	R. Ramsdell on ABV noted. -- MW			
0459	cob. -- RL			
I CERTIFY that entries above are correct, that all scheduled operations have been accomplished except as noted, and that all abnormal occurrences and conditions have been recorded.		SIGNATURE(S) OF WATCH SUPERVISOR(S) 		