

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
<del>2008</del>				
5/2	1152.6			Replaced battery
5/28	1155.7			replaced vna pump shear coupling. (last time 6/15/03)
11/30	1174.6			Vacuum pump - installed O/H kit (pump installed @ 40 hrs)
				Dir Gyro - O/H by Kelley Inst.
1/2/09	1181.7			condition insp. completed IAW FAR 43 APP D found to be in safe operating condition
1/11/10	1229.5		1229.5	condition insp completed IAW FAR 43 APP D found to be in safe operating condition
2/19/10	1232.3			Replaced battery
1/2/11	1262.7		1262.7	Condition insp completed IAW FAR 43 APP D found to be in safe operating condition
1/8/12				Condition insp IAW FAR 43 APP D found in safe operating condition
10/21/12	1300.2			Replaced tire
1/4/2013	1305.6		1305.6	Condition insp completed IAW FAR 43 APP D found in safe operating condition
4/6/13	1305.9		1305.9	Test flight - pre-sale Checked

NO FURTHER ENTRIES FOR THIS OWNER

TRCH	DATE
	2011
	29
	6/11
	6/11
	8/11
	9/2
	11/1
	11
	12



TACH-1306 SCOTT OLSON 2nd OWNER 1-22-2013

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
6/11	1338.6		1338.6	Repaired and replaced broken alt. wire 10 GA. WIRE AT ALT. Elec system changing alt. normal - SMO
6/11	1338.6		1338.6	Removed fuel - checked all connections. SMO
8/15	1356.4	.2	1356.6	ROTATED RIGHT MAIN - placed bearings on both axles Repaired left main - balanced both tanks. SMO
9/25	1365.5		1365.5	REPLACED VACUUM HOSE AND CLAMPS. ✓ is good SMO
11/1	1372.1		1372.1	REMOVED FUEL TANKS DUE TO SLOSH FIBRING/PEELING
11-	"		"	REF SERVICE Bulletin 11-9-13 VANS slosh inspection SMO
-	Paul Beck - William			TANKS TAKEN TO Paul Beck, keep no more - removed old slosh, installed safety wire "B" nut - RESEALED TANKS
12-2	1372.1		1372.1	REINSTALLED TANKS AFTER NEW SEALANT AND NEW SAF-AIR EAV-110 push type Fuel Drain Valves EACH TANK. LEAK checked 5 gal each tank - NONE
				FLIGHT TEST 12-14-13 All ok - [REDACTED]





JAN. 22, 2013 -

NEW OWNER - SCOTT OLSON ENGINE LOG SERIAL No. L-33015-36A

DATE	TIME		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	SIGNATURE	LICENSE NUMBER
	Hrs.	Min.			
6-11-13	1338	6	oil change - Phillips XE 20-50 bolts oil filter changed C448110		
4-19-14	1373		Comp. #1 68 #3 78 #2 70 #4 68 R&R D FRONT CRANK SEAL, TIGHTENED OIL FILLER TUBE, INSTALLED NEW DOG BONE LINKS ON EXHAUST, TIGHTENED MAN PRESS LINE CONDITION INSPECTION COMPLETED IAW APP D PART 43 AND EN9 IN CONDITION FOR SAFE FLIGHT. [REDACTED] AAP [REDACTED]		

Page Total  
 Brought Forward  
 Total to Date

All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.