

National Transportation Safety Board
Office of Research and Engineering
Washington, D.C. 20594

Performance Erratum

Specialist Report
Marie Moler

A. EVENT SUMMARY

Location: Ypsilanti, Michigan
Date: March 8, 2017
Time: 1452 EST
Airplane: Boeing MD-83, N786TW
NTSB Number: DCA17FA076

B. ERRATUM

In the Performance Study for DCA17FA076, the last sentence on page 6 of the Integration of accelerometer data section incorrectly stated the time of brake release to be 15:51:28 when it was 14:51:28.

Marie Moler
Specialist – Airplane Performance
National Transportation Safety Board