




DATE	TACH TIME	TOTAL TIME	DESCRIPTION									
<div> <div> Aviation Performance Solutions DATE: 03/26/2008 REG.#: N133EE S/N: 009 </div> <div>  EMERGENCY MANEUVER TRAINING </div> <div> TACH: 1703.09 TT: 1703.09 </div> </div>												
<p>C/W 50hr. inspection I/A/W EA-300L service manual No. 06702. Serviced hydraulic fluid. Checked condition of tires and brake linings. Checked ops of nav. Lights and strobes. Lubed all flight controls and torque tube bearing and tail wheel. Replaced tail wheel with new. Bled brake system.</p> <p>This airframe was found to be in an airworthy condition at the time of inspection.</p>												
<table border="0"> <tr> <td>AD Compliance:</td> <td>Description:</td> <td>Next Due:</td> </tr> <tr> <td>AD98-24-07</td> <td>Rudder Pedals</td> <td>1753.09</td> </tr> </table> <p>For more details refer to checklist/discrep. sheet on file dated this date.</p> <p>John Vazquez A&P [Signature]</p>				AD Compliance:	Description:	Next Due:	AD98-24-07	Rudder Pedals	1753.09			
AD Compliance:	Description:	Next Due:										
AD98-24-07	Rudder Pedals	1753.09										
<div> <div> Aviation Performance Solutions DATE: 04/17/2008 REG.#: N133EE S/N: 009 </div> <div>  EMERGENCY MANEUVER TRAINING </div> <div> TACH: 1734.13 TT: 1734.13 </div> </div>												
<p>C/W 100hr. inspection I/A/W EA-300L service manual No. 06702. Serviced hydraulic fluid. Checked condition of tires and brake linings. Checked ops of nav. Lights and strobes. Lubed all flight controls and torque tube bearing and tail wheel. Replaced LH & RH top wing root gap seal. Replaced both brake caliper springs P/N MS28775-224 and bled brake system. Resealed RH rear brake master cylinder. Replaced all brake linings with new P/N 66-064. Replaced LH IB wing access panel P/N PC-13101.5P2. Removed Digital G-Meter P/N DSA12, S/N 3C72679 and installed analog G-meter P/N1470, S/N 73. Weight change is negligible.</p> <p>This airframe was found to be in an airworthy condition at the time of inspection.</p>												
<table border="0"> <tr> <td>AD Compliance:</td> <td>Description:</td> <td>Next Due:</td> </tr> <tr> <td>AD2005-11-07</td> <td>Belly Panel</td> <td>N/A</td> </tr> <tr> <td>AD98-24-07</td> <td>Rudder Pedals</td> <td>1784.13</td> </tr> </table> <p>For more details refer to checklist/discrep. sheet on file dated this date.</p> <p>John Vazquez A&P [Signature]</p>				AD Compliance:	Description:	Next Due:	AD2005-11-07	Belly Panel	N/A	AD98-24-07	Rudder Pedals	1784.13
AD Compliance:	Description:	Next Due:										
AD2005-11-07	Belly Panel	N/A										
AD98-24-07	Rudder Pedals	1784.13										
4/18/08	1737.94	1737.94	Bled brake system, serviced reserves with Mil-5606.									
<div> <div> Aviation Performance Solutions Date: 5/1/2008 Reg.#: N133EE S/N: 9 </div> <div>  EMERGENCY MANEUVER TRAINING </div> <div> Tach: 1763.10 TT: 1763.1 </div> </div>												
<p>C/W 25hr. Inspection I/A/W Extra 300L Service Manual No. 06702.</p> <p>Lubed torque tube bearing. Checked light ops, tire and brake condition.</p> <p>Replaced right rear nav bulb P/N 34-0412070-63. Airframe RTS.</p> <p>John Vazquez A&P [Signature]</p>												

[illegible]