Aircraft Record Genera	I Information			
Manufacturer	202	Model PA-32-260  Registration Number N 3357 W		
Date of Manufacture				
Engine(s) currently installe	d:			
Manufacturer	Model	S	erial	
Manufacturer	Model	<b>S</b>	erial	
Propeller(s) currently instal	lled:	**************************************		
Manufacturer		Model		
HUB Model	Serial	S	erial	
Blade Model	Serial	Serial	Serial	
Blade Model	Serial	Serial	Serial	

YEAR: RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and A Entries must be endorsed with Name, Rating and Certificate Technician or Repair Facility. (See back pages for other spec	Number of
Hinois Aviation Academy  N3357W Tach:2356.7 7/1/2008  Drained oil, removed filter. Installed new CH48110-1 oil filter. Added 11 quarts of Aeroshell 15w-50 oil. No leaks present. Returned to service.	Kenneth Morgan III	Resea (switch 95-26- C53a T Replac Ma: LH ma 'eplac naviga and ro I cer the Al condit	Illinois Aviation Academy 57W Tach:2392.6 AFTT:5694.6 8/17/2008 arched AD's through Bi-weekly 08-16. C/W 76-07-12 n). C/W 75-24-02 (seats). C/W 78-23-01(fuel door). C/W 13(oil cooler hoses) by replacing both oil cooler hoses-TSO Type D hoses were installed. C/W FAR 91.207 (ELT), ced ELT battery, #BS2166. Battery due September 2010. ain landing gear torque links were inspected and lubricated. ain landing gear torque links were replaced, #78032-000. ced missing cowl fastener, #460-045. Replaced broken green ation lens, #68-4230020-40. All flight control surface hinges and ends were inspected and lubricated. rtify that this aircraft has been inspected in accordance with NNUAL inspection checklist and is found in an airworthy tion at this time.	

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repai</b> Entries must be endorsed with Name, Rating and C Technician or Repair Facility. ( <i>See</i> back pages for a	Certificate Number of
DATE				ois Aviation Academy	
				018 A Dittitudit A Citation 19	
			Removed:	and replaced left nav bulb P/N CMA-75 12-	
		<u> </u>	Temove	d and replaced right strobe tube P/N 02-	
				. Returned to service.	
		.02	20210-00	. Returned to services	
			.4 mili +4 a		
		I Jo	nathan Tay	lor	
			&P		-
		NISSI	57\M Tach	2536.4 7/24/09	
		Ren	laced both r	main tires and tubes with new re-treads.	
		Don	laced areas	e rings P/N 153-01500 and 153-30015.	
		Don	laced RH no	ay/strobe assy with new P/N 11-03217. Sent out	
		BH1	in tank for o	composite repair and repaint. Reinstalled upon	
		- orriv	al Panlace	Id hattery with new G-35S. I certify that this	
		airfr	ame has be	en inspected in accordance with a 100 nour	
		insp	ection and	is found airworthy END -	
		T ,			
		— Chr	is Heiter	-	

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and</b> Entries must be endorsed with Name, Rating and Certifica Technician or Repair Facility. (See back pages for other s	rtificate Number of	
DATE						
				Illinois Aviation Academy Airframe Log N#3357W Tach:2472.2 Date:03/03/09 Removed serviceable transponder (p/n:AT50A s/n:29109).		
				Chane Tijerina AP		
	P/N 14635-0			atch P/N 14627-03, perationally checked		
			N3357W	V Tach: 2594.2 AFTT: 5,895.1 8/6/09		
hris He	iter AP			used wheel bearings. Performed ELT inspection per FAF	; ·. ₹ -:	
				d). ELT battery due 9/2010. Verified all AD's through this		
				W AD 76-07-12 (switch), AD 75-24-02 (seats) and AD		
			new. Op	1 (fuel door). Replaced LH main fuel tank wiring lug with perationally checked good. I certify that this airframe has spected in accordance with a 100 hour / ANNUAL on and is found airworthy END -		
			Chris He	eiter AP		