Elliott Aviation of the Quad Cities 1000 action Report
o Be Solely For (Check One) Maintenance Trar This Maintenance Transaction Repor 6601 74th Aven **Quad City Airport** APU Airframe Eng. #1 Milan, IL 61264 Entries DB0060 Serial No. N/A DB0059 Serial No. Serial No. 309-799-3183 Aircraft Identification and Status Total A/C Landings Engine 1 Total Hrs Engine 2 Total Hrs Engine 1 Ttl Cycles Engine 2 Ttl Cycles APU Events A/C Registration Date City ID Total A/C Hours A/C Serial No. A/C Unit No. 9/7/12 MLI 5032 N108EK 560-5032 Hobbs: 4510.9 Component Changes, Inspections, Service Bulletins, or Airworthiness Directives Accomplished Installed TSO Material Man Mod Removal Transaction Part Installed Costs Hours Level Part Serial No. Type Item Name Position Part Number/Alternative Part Number Reason item Status Clean up lavatory fluid spill. Removed left, right and aisle cabin floorboards and cleaned all lavatory fluid and fluid residual from under, around and on cabin floorboards. Cleaned area Comments: around escape hatch. Reinstalled all removed floorboards and lavatory tank with new drain o-ring P/N MS29513-343. 1 Perform two-position horizontal stabilizer oper 2 Performed two position stabilizer operational check. Functional check is normal at this time Comments: 3 Cessna recommends horizontal stabilizer actu Complied with horizontal stabilizer actuator case drain leak check. Performed case drain leak check in both directions. Found no fluid in down travel and 50CC Comments:

Repair Facility Elliott Aviation of the Quad Cities Inc	Certified Repair CGHR812C EASA-145 Station Number	.5686 Work Order No. 2513873
Work Performed By Elliott Aviation of the Quad Cities Inc I certify that the above stated maintenance and/or inspection was	Certificate No.	EASA-145.5686 Date Sep-07-12
X Federal Aviation Administration Other (Specify)		and


of fluid in up travel, limit is 150CC

4

Comments:

1 Remove interior as necessary to gain access

Removed and reinstalled interior as necessary to gain access for lavatory spill clean up.





MTR ID # 2049654

Page 1 of 1

Maintenance Transaction Record

This Maintenance Report is To Be Used Solely For (Check One)

CAMP Systems International 8200 E. 341'H STREET **BUILDING 1600, SUITE 1607**

	COST ACCOMP Systems		☑ Airframe Entries		ng, #1 erial No	☐ Eng Seri	, #2 al No.	☐ APU Seria			BUILDIN Wichita,	NG 1600, SU KS 87228		82-0701
					Ai	rcraft Identification	and Status					879.00		Calculation of the calculation o
A/C Serial #	A/C Unit#	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 Total Hr	Engine 1 Ttt Cycles	s Engin	e 2 Ttl Cycles	APU Hrs	APU Events	Freen Hrs
560-5032	5032	N108EK	24-Aug-2012	KDSM	4510.2	3110	4510.2	4510.2	3110		3110			761.4
			Cor	nponent Ch	anges, Inspections,	Service Bulletins,	or Airworthiness Di	rectives Accompl	shed					
(tem	Transaction No, Type	Ite	m Name		Position	Part Number /	Alternate Part	Mod Level Par		emoval eason		led Part N/TSO/TSR	Materi Costs	
221010 221010 : E	1 1 ELE	VATOR DRIVE SERV	V O		ELEVATOR	4006719-921		990	62398 N		\$ 0 N	/TH 0 HRS		
		stalled a modified SM			art no: 4008719-921.	The part number t	was changed due to	compliance with	Cessna Service Let	tter SL56t	XL-22-02. T	The servo w	25	
	mstalled and te	isted referencing Ces	ena SL560XL-2:	2-02. (Remo	oved part no: 400671	19-906 serial no: 9:								
273004	2 1 SER	VO ACTUATOR			oved part no: 400671	44430-3739	9011069).	T75	5 N		0 0 N	ATH 9 HRS		
273004	2 1 SER				oved part no: 400671	44430-3739	9011069).	T75	5 N		0 0 N	ATH 9 HRS		
	2 1 SER Comments; Ins	VO ACTUATOR stalled an overhauled CKPIT VOICE RECOI	Sigmatek Eleva RDER	tor Electric	oved part no: 400671	44430-3739 noing Gessna 560) \$200-0012-00	9011069). KL Maintenance Ma A200S	T75 Inual chapter 27- 112	5 N 32-04. (Removed par 1 N	rt no: 444	O 0 N 30-3739 ser	MTH 9 HRS rial no: T150 MTH 9 HRS		
	2 1 SER Comments; Ins	VO ACTUATOR stalled an overhauled	Sigmatek Eleva RDER	tor Electric	oved part no: 400671	44430-3739 noing Gessna 560) \$200-0012-00	9011069). KL Maintenance Ma A200S	T75 Inual chapter 27- 112	5 N 32-04. (Removed par 1 N	rt no: 444	O 0 N 30-3739 ser	MTH 9 HRS rial no: T150 MTH 9 HRS		· ·
237001	2 1 SER Comments; Ins 3 1 COC Comments; Re	VO ACTUATOR stalled an overhauled CKPIT VOICE RECOI	Sigmatek Eleva RDER	tor Electric	oved part no: 400671	44430-3739 noing Cessna 560) \$200-0012-00 and sent it to the 6660161-20	9011069). KL Maintenance Ma A200S	T75 Inual chapter 27- 112	5 N 32-04. (Removed par 1 N	rt no: 444	O 0 M 30-3739 ser S 0 M L. # 23-00-0	MTH 9 HRS rial no: T150 MTH 9 HRS		
237001	2 1 SER Comments; Ins 3 1 COC Comments; Re 4 - TRII	VO ACTUATOR stalled an overhauled CKPIT VOICE RECOI emoved cockpit voice	Sigmatek Elevai RDER recorder part no	tor Electric	oved part no: 400671 Trim Actuator reference 2-00, serial no: 1121 LEFT ELEVATOR	44430-3739 noing Cessna 5602 \$200-0012-00 and sent it to the \$660161-20	9C11069). KL Maintenance Ma A200S NTSB for evaluatio	T75 Inual chapter 27- 112	5 N 32-04. (Removed par 1 N	rt no: 444	O 0 M 30-3739 ser S 0 M L. # 23-00-0	MTH 0 HRS rial no: T150 MTH 0 HRS 6-02.		
273004 237001 2049654004 2049654005	2 1 SER Comments; Ins 3 1 COC Comments; Re 4 - TRII	EVO ACTUATOR stalled an overhauled CKPIT VOICE RECOI emoved cockpit voice VI ACTUATOR	Sigmatek Elevai RDER recorder part no	tor Electric	oved part no: 400671 Trim Actuator reference 2-00, serial no: 1121 LEFT ELEVATOR	44430-3739 noing Cessna 5603 S200-0012-00 and sent it to the 6660161-20 sintenance Manual	9C11069). KL Maintenance Ma A200S NTSB for evaluatio	T75 Inual chapter 27- 112	5 N 32-04. (Removed par 1 N	rt no: 444	O 0 N 30-3739 ser S 0 N L. # 23-00-0 N 0 N	MTH 0 HRS rial no: T150 MTH 0 HRS 6-02.		

Trans, Type: 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, Misc, Removal Reasons; WO - Worn to Limits, SC - Scheduled, U	N - Unscheduled, CO - Convenience, N - Other(note is comments)	installed Part Status: N - No	w, R - Repaired/Rebuill, S - Serviceable, O - Overhaule
Repair Facility ELLIGIT AVIATION OF DES MOINES Certified Repair Station Number CRS JEMR166F	Work 381343 Order No.		Maintenance Log Section Page
Work Performed By ELLIOTT AVIATION OF DES MOINES	Certificate No. CRS JEMR156F	Date 24-Aug-2012	
I certify that the above stated maintenance and/or inspection was performed in accordance with the	current regulations of the		
☑ Federal Aviation Administration ☐ Other (Specify)	an	nd ,	
THE AIRCRAFT IDENTIFIED ABOVE IS PRESENTLY APPROVED FOR RETURN TO SERVICE			
Work Inspected By MICHAEL NEWHALL Pertinent details of this maintenance are on file at our facility under the above Work/Service Order Nur	Certificate No. CRS JEMR166F	Date 24-Aug-2012	
The state of the s	act of otherwise.		



Maintenance Transaction Record

MTR ID # 2049549

☐ APU Serial No.

Page 1 of 1

CAMP Systems International 8200 E. 34TH STREET BUILDING 1600, SUITE 1607 Wichita, KS 87226

Phone: 316-462-2267/ Fax: 316-462-0791

, and the same of		. т	îhis Maintenance Report is To Be	Used Solely For (Check One)
A Division of CAMP Systems	<u>i</u> ∑ Airframé Entries	☐ Eng. #1 Serial No	☐ Eng. #2 Serial N	_

Comments: Replaced RH fuel boost pump panel on RH wing with new.

												1 110110.01	O TOL LLO		VA. 0101
						Vircial Identification	and Status								e de la companya de l
A/C Serial #	A/C Unit#	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 7	otal Hrs	Engine 1 Ttl Cycles	Engin	e 2 Ttl Cycles	APU Hrs	APU Events	Freon Hrs
560-5032	5032	N108EK	24-Aug-2012	KDSM	4510,2	3110	4510.2	4510	0.2	3110		3110			781.4
		,	Col	nponent C	nangès, Inspections	, Service Bulletins,	or Airworthiness D	itectives Ac	complish	d					
tem	Transaction No. Type	Ite	m Name		Position	Part Number	' Alternate Part	Mod Level	Part S		moval ason	Installe Status TSN		Materi Costs	
055002	800	COMPLISH CHECK (00FT) erformed Unschedule			on 4 overeneed on	oue 8000 ft teferen	ring 560VI Mainto	nanca Mani	ual E EO O	0					80
055006	2 2 AC	COMPLISH CHECK D/OR MANEUVER erformed Unschedule	SEVERE TURBL	LENCE						u.			,		80
2049549003		EL LEAK REPAIRS epaired fuel leaks on	LH and RH wings	s from seal	LH & RH ant over Hi-Loks be	tween wing stations	s 57.16 and 101.7 i	in several ar	reas, inclu	ding Hi-Loks on al	ft spar of	RH wing inbo	pard of land	ling	
2049549004		EL BOOST PUMP PA	NEL		RH	9912514-22				\//	0	N n M	H O HRS		

Trans. Type: 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, Misc.	Removal Reasons; WO - Worn t	o Limits, SC - Scheduled, UN - Unsche	eduled, CO - Convenience, N - Other(note i	n comments)	Installed Part Status: N - N	lew, R - Repaired/Rebuilt, S - Serviceable, O - Overhaulad
Repair Facility ELLIOTT AVIATION OF MPLS	Certified Repair Station Number	KX5R005N	Work Order No.	459386		Maintenance Log Section Page
Work Performed By PETER NOLDEN		Certi	ificate No. CSRKX5R005N		Date 24-Aug-2012	
I certify that the above stated maintenance and/or	inspection was performed i	n accordance with the current	t regulations of the			
☑ Federal Aviation Administration	Other (Specify)			and		
IS APPROVED FOR RETURN TO SERVICE, PE	RTINENT DETAILS OF THE	WORK ARE ON FILE AT T	HIS AGENCY.			
		_				
Work Inspected By NATHAN BALLARD		Certi	lficate No. CSRKX5R005N		_ Date 24-Aug-2012	
Pertinent details of this maintenance are on file at our	facility under the above Wo	rk/Service Order Number as a	applicable,			

This Maintenance Report is To Be Used Solely For (Check One)

Maintenance Transaction Record

MTR ID # 2035618

Page 1 of 1

CAMP Systems International 8200 E. 34TH STREET

_		die
Ø.	cescom	***
del sur		Jan .

CES		•	☑ Airframe Entries	_	ng. #1 erial No	Eng Ser	#2 al No <u>,</u>		APU Serial N	0.	Wichita	NG 1600, SU I, KS 67226 316-462-226	ITE 1607 7/ Fax: 316-4	62-0791
	Althorn size and the pa	ne a feste de inclusion en en a ante metamore na rei	en de sou situation de partir se se de la section de l		1	ircraft Identification	ano Status	-1.2400mc/-1242	Late of References	Million All 10 C 10		25.29 19100-1922 - 191220		
A/C Serial #	A/C Unit #	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 T	otal Hrs	Engine 1 Ft Cycles	Engine 2 Ttl Cycle	s APU Hrs	APU Events	Freon Hrs
560-5032	5032	N108EK	27-Jul-2012	KFCM	4484	3094	4484	448	4	3094	3094			781.4
		. Ny Ny mandritry ny taona mandritry ny taona ao amin'ny faritr'i Austrian ao amin'ny faritr'i Austrian ao amin'ny Ny INSEE dia mandritry ny taona ao amin'ny faritr'i Austrian ao amin'ny faritr'i Austrian ao amin'ny faritr'i	Cor	nponent Ci	anges Inspections	, Service Bulletins,	or Airworthiness Di	rectives Ac	complish	∍d	region and transport to the control of the control			
ltem	Transaction No. Type	Ite	em Name		Position	Part Number /	Alternate Part	Mod Level	Part Se			alled Part SN/TSO/TSR	Materi Costs	
342510 342501 : CNTR	1 1 CE	NTER ELECTRONIC	DISPLAY UNIT		CENTER	7014300-901	DU-870		0808H	459 UN	i R			
	Comments: Re	emoved part no: 7014	4300-901 Remov	ed serial no	: 97021920									

Trans. Type: 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, -	- Misc. Removal Reasons; WO - Worn to Limits, SC - School	luted, UN - Linscheduled, CO - Convenience, N - Other(note in	n comments) In	nstelled Part Status: N - New, R - Repaired/Rebuilt, S - Serviceable, O - Overhaufed
Repair ELLIOTT AVIATION OF MPLS	Certified Repair Station Number KX5R005N	Work Order No.	459359	Majnledenter Log Section Page
Work Performed By ANDREW DALE		Certificate No. KX5R005N	Date 27-Jul-201	2
I certify that the above stated maintenance	ce and/or inspection was performed in accordance w	ith the current regulations of the		
☑ Federal Aviation Administration	Other (Specify)	-	and	·
IS APPROVED FOR RETURN TO SERV	VICE. PERTINENT DETAILS OF THE WORK ARE C	ON FILE AT THIS AGENCY.		
Work Inspected By JEFF SOLBERG		Certificate No. KX5R005N	Date 27-Jul-201	12
Pertinent details of this maintenance are on f	ile at our Mcility under the above Work/Service Orde	r Number as applicable.		

Maintenance Transaction Record

MTR ID # 2034061

Page 1 of 1

☑ Airframe Entries

☐Eng. #1

Eng. #2

This Maintenance Report is To Be Used Solely For (Check One)

CAMP Systems international 8200 E. 34TH STREET BUILDING 1600, SUITE 1607 Wichita, KS 67226

The state of the s	Zin Canadan yang dari		Culles	Se	erial No	Ser	al No <u>.</u>	Serial)	No		S 67226	/ Fax: 316-462	2.0704
	and the second section of the second section of the second second second second second second second second se	and the second second second as a second	ezopa a rozenzen eta en a optionen kon en	na canantantan da manda da ma		Aircraft Identification	and Status	de de la propieta non estado mental de la casi	and the second of the second o	Fribile, 5	10-402-2207	Fax, 310-40,	2-0791
A/C Serial #	A/C Unit#	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 Total Hrs	Engine 1 Ttl Cycles	Engine 2 Ttl Cycles	APU Hrs	APU Events F	Freon Hrs
560-5032	5032	N108EK	24-Jul-2012	KFCM	4473.7	3088	4473.7	4473,7	3088	3088			781.4
	Transaction		Co	mponent Ch	anges, Inspections	s, Service Bulletins,	or Airworthiness Di	rectives Accomplisi Mod		noval Installe	ad Part	Materia	Man
Item	No. Туре	jte	m Name		Position	Part Number /	Alternate Part,	Level Part		son Status TSN		Costs	Hour
12-09-01		DING GEAR - TORQ 560XL-32-41 R1 Pre			2/2040 4005477			,					

Trans. Type	: 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, Misc.	Removal Reasons: WO - Wom to U	imits, SC - Scheduled,	UN - Unscheduled, CO - Convenience, N -	Other(note in comments)	Installed Part Status: N - N	lew, R - Repaired/Rebuilt, S - Serviceable, O - Overhauled
Repair Facility	ELLIOTT AVIATION OF MPLS	Certified Repair K	X5R005N		ork rder No.		Mainfairence Log Section Page
Work Pe	rformed By ELLIOTT AVIATION OF MINI	NEAPOLIS		Certificate No. KX5R005N	l	Date 24-Jul-2012	
l cer	tify that the above stated maintenance and/or	inspection was performed in a	ccordance with t	he current regulations of the		-	
ØFede	eral Aviation Administration	☐ Other (Specify)			and	-	
IS A	PPROVED FOR RETURN TO SERVICE. PE	RTINENT DETAILS OF THE V	YORK ARE ON F	FILE AT THIS AGENCY.			
Work In	spected By. JEFF SOLBERG			Certificate No. KX5R005N		_ Date 24-Jul-2012	^
Pertinen	t details of this maintenance are on file at our	facility under the above Work/	Sarvice Order Nu	imber as applicable,]
	,						-

Maintenance Transaction Record

This Maintenance Report is To Be Used Solely For (Check One)

MTR ID # 2028091

Page 1 of 1 CAMP Systems International

8200 E. 34TH STREET BUILDING 1600, SUITE 1607

Wichita, KS 67226

Phone: 316-462-2267/ Fax: 316-462-0791

A/C Serial #

		Cro
K .	CESCOM	
AND DESCRIPTION OF THE PERSON	The same of the sa	

A/C Unit #

☑ Airframe Entries

Date

A/C Registration #

☐ Eng. #1 Serial No.

Eng. #2

Serial No.

Aircraft Identification and Status Total A/C Landings | Engine 1 Total Hrs | Engine 2 Total Hrs | Engine 1 Tit Cycles | Engine 2 Tit Cycles | APU Hrs APIJ Events | Freon Hrs.

Serial No.

560-5032	5032	N108EK	12-Jul-2012	KECM	4466.2	3075	4466,2	446	6.2	3075	3075			781,4
	englant semestra emperatura	, 2000	Cor	mponent Chang	ges, Inspections, S	Service Bulletins, o	r Airworthiness D	irectives Ac	complished	and the minimum state of the same			35. 40. 47. 41.	7
Item	Transaction No. Type]ter	m Name		Position	Part Number / A	Alternate Part	Mod Level	Part Serial	Removal Reason		nstalled Part s TSN/TSO/TSR	Material Costs	Man Hours
783010 783010 : E2*RI	1 1 RIG	HT INBÓARD THRUS	T REVERSER	ACTUATOR	RIGHT INBOARD	64ND-78204-7		***************************************	1694	UN	0	0 MTH 0 HRS		
	Comments: Re	emoved part no: 64ND	-78204-5 Remo	ved serial no: 0	0153.									

Trans, Type; 1	- Component, 2 - Inspection, 3 - SB, 4 - AD, Misc.	Removal Reasons: WO - Worn t	o Limits, SC - Scheduled, UN - Uns	cheduled, CO - Convenience, N	- Othèr(note in c	comments)	Installed Part Status: N - N	sw, R - Repaired/Rebuilt, S - Service	able, O - Overtrauled
Repair Facility _	ELLIOTT AVIATION OF MPLS	Certified Repair Station Number	KX5R005N		Work Order No.	459359		Maintenance Section P	age
Work Perf	ormed By ELLIOTT AVIATION OF MINN	EAPOLIS	Ce	rtificate No. KX5R008	iN		Date 12-Jul-2012		
I certify	that the above stated maintenance and/or	inspection was performed i	n accordance with the curre	ent regulations of the					
☑ Federa	l Aviation Administration	Other (Specify)		٠		and			
IS APP	ROVED FOR RETURN TO SERVICE, PER	RTINENT DETAILS OF THE	WORK ARE ON FILE AT	THIS AGENCY.					
Work insp	ected By LEIGH ZELINSKI	/ ,	Ce	rtificate No. KX5R005	.N				
-	etails of this maintenance are on file at our	gellity under the above Wo			14		Date 12-Jui-2012		

This Maintenance Report is To Be Used Solely For (Check One)

MTR ID # 2021320 **Maintenance Transaction Record**

Page 1 of 3

CAMP Systems International 8200 E. 34TH STREET BUILDING 1600, SUITE 1607

(CESCOTT)	
A Division of CAMP Systems	

CBS A Divisi	on of CAMP Systems		☑ Airframe Entries		ng, #1 erial No	☐ Eng Seri	. #2 al No <u>.</u>	☐ APU Serial I	No.	Wichita, I		TE 1607 7/ Fax: 316-46	62-0791
	13				ρ.	ircraft Identification	and Status			7 1101,0.	102 220		
A/C Serial	# A/C Unit #	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 Total Hrs	Engine 1 Tti Cycles	Engine 2 Ttl Cycles	APU Hrs	APU Events	Freon Hrs
560-5032		N108EK	29-Jun-2012	KFCM	4457,8	3075	4457.8	4457.8	3075	3075			781.4
			Con	nponent Ci	anges. Inspections	, Service Bulletins, o	or Airworthiness Di	rectives Accomplish	ned				
Item	Transaction No. Type	Ite	om Name		Position		Alternate Part	Mod Level Part 8	Rer	noval installi ison Status TSI		Materia Costs	Man Hours
5-92-02		PECTION DOCUMENT Complied with inspection		per Elliott A	viation's AAIP. No	discrepancies noted	d.						
5-92-03		PECTION DOCUMENT PER PROPERTY PROPERTY PROPERTY PER PROPERTY PROPERTY PER PROPERTY		per Elliott /	viation's AAIP, No	discrepancies noted	d,						
5-92-09		PECTION DOCUMEN Emplied with inspection		per Elliott A	viation's AAIP. No	discrepancies noted	d.						
5-92-16		PECTION DOCUMES omplied with inspection		3 per Eillott	Aviation's AAIP. N	o discrepancies not	ed.						
5-92-27		PECTION DOCUMES mplied with inspection		7 per Elliott	Aviation's AAIP. N	o discrepancies not	ed.	. ,					
5-92-34		PECTION DOCUMES omplied with inspection		4 per Elliott	Aviation's AAIP. N	o discrepancies not	ed.						
5-92-35		PECTION DOCUMES omplied with inspection		5 per Elliott	Aviation's AAIP. N	o discrepancies not	ed.						
5-92-44		PECTION DOCUMES	• •		Aviation's AAIP. N	o discrepancies not	ed.						
5-92-47		PECTION DOCUME omplied with inspection		7 per Elliott	Aviation's AAIP. N	o discrepancies not	ed.						
5-92-MB		PECTION DOCUME		B per Ellio	tt Aviation's AAIP. I	No discrepancies no	ted.	·					1,71
Trans. Type: 1 - C	omponent, 2 - Inspection	3 - SB, 4 - AD, Misc.	Removal Reason	is; WO - Wom	to Limits, SC - Scheduled	, UN - Unscheduled, CO -	Convenience, N - Other(note in comments)	lns	talled Part Status; N - New			
Repair Facility EL	LIOTT AVIATION (OF MPLS		ed Repair n Number	KX5R005N		Work Order	No. 459329			Section	/aintenance P	.og age
Work Perfor	ned By ELLIOT	TAVIATION OF MPL	.s			Certificate No	. KX5R005N		Date 29-Jun-201	2	<u> </u>	-	
I certify to	nat the above state	d maintenance and/o	r inspection was	performed	in accordance with	the current regulation	ons of the						
☑ Federal A	Aviation Administrat	tion	☐ Other (S	ipecify)				and					
ELLIOTT AGENCY		ON 560XL AAIP AND	O IS APPROVED	FOR RET	URN TO SERVICE	. PERTINENT DET	AILS OF THE WOR	RK ARE ON FILE A	THIS				
Work Inspec	ted By CHAD VE	ELTA				Certificate No	KX5R005N		_ Date 29-Jun-201	2			
Pertinent det	ails of this maintena	ance are on file at our	r facility under the	e above We	ork/Service Order N	umber as applicable).						

Maintenance Transaction Record

MTR ID #2021320

Page 2 of 3

☑ Airframe Entries

□ Eng. #1 Serial No.

☐ Eng. #2 Serial No.

This Maintenance Report is To Be Used Solely For (Check One)

☐ APU Serial No. **CAMP Systems International** 8200 E. 34TH STREET BUILDING 1600, SUITE 1607

Wichita, K\$ 67226

Phone: 316-462-2267/ Fax: 316-462-0791

									·			Phone: 3	16-462-226	7/ Fax: 316-46	2-0791
						Aircraft Identification	and Status								
A/C Serial #	A/C Unit#	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 Total I	Irs Engine	a 1 Ttl Cycles	Engine 2	Ttl Cycles	APU Hrs	APU Events	Freon Hrs
560-5032	5032	N108EK	29-Jun-2012	KFCM	4457.8	3075	4457.8	4457,8		3075	30	75			781.4
		V-13-11-11-11-11-11-11-11-11-11-11-11-11-	Con	ponent Cl	nanges, Inspections	s, Service Bulletins,	or Airworthiness Di	rectives Accom	olished					, !	
	Transaction	·.	•					Mod	•	Ren	oval	Install	led Part	Materia	1 Man
ltem	No. Type	ite	m Name		Position	Part Number /	Alternate Part	Level P	art Serial	Rea	son St	atus TS	N/TSO/TSR	Costs	Hours
62003 : FL		WARD ENGINE BO	TTLE FORWARD)		AE13083-5		3	12	sċ	١	1 0 M	ATH		
	Comments: Re	moved part no: 1308	3-5 Removed se	rial no: 607	·										
3008 32003 : FR	12 1 FOR	WARD ENGINE BO	ITLE AFT CART	RIDGE		AE13083-5		3	12	SC	١	4 0 1	ИTH		
	Comments: Re	emoved part no: 1308	3-5 Removed se	rial no: 607											
33010 52003 : AL		ENGINE BOTTLE F				AE13083-5		3	12	SC	1	N 0 V	ATH		
	Comments: Re	emoved part no: 1308	3-5 Removed se	rial no: 607	7.		:								
3012 32003 : AR	CA	ENGINE BOTTLE A RTRIDGE			_	AE13083-5		3	12	sc	ľ	1 0 V	ATH		
		emoved part no: 1308				 ,									
256007	DOC	TAILED INSPECTION CUMENT 2 - etailed inspection of li				Alpine Aeropautics	Corporation dated (8/27/2012: WO#	€ 6200-5 on	all (ten) life v	rests.				
021320016		ITAL CLOCK BATTE								sc		N 0 N	MTH 0 HRS		~
2 1320010		eplaced batteries in L		chronomet	ters with new.										
60XL-27-34	17 3 FLIG	SHT CONTROLS - E	LEVATOR TRIM												
		ound to have been co		ously by in	stalling new cable	P/N 666000-3. Elliot	t Aviation of the Qu	ad Cities W/O 2	512214, ce	ard 1505 perfo	ormed the	work. No	o further acti	on	
rans. Type: 1 - Com	ponent, 2 - Inspection	, 3 - SB, 4 - AD, Misc.	Removal Reason	s: WO - Worn	to Limits, SC - Schedule	d, UN - Unscheduled, CO -	Convenience, N - Other	note in comments)		Inst	alled Part Sta	tus; N - Nev	v, R - Repaired/I	Rebuilt, S - Service	abfe, O - Overt
Repair ELLIC	O NOITAIVA TTC	OF MPLS		ed Repair Number	KX5R005N		Work Order	No. 459329					Section	Maintenance n F	og age
Nork Performe	d Bv ELLIOT	T AVIATION OF MPL	.s			Certificate No	, KX5R005N		Date	29-Jun-2012	,			,	
		d maintenance and/o		nerformed	in accordance with					20-0411-2012	•				·
	ation Administrat		Other (S		II, doostaanso mii	ino ounoni rogaladi		ane	ı,			1			
		ON 560XL AAIP ANE		_	URN TO SERVICE	PERTINENT DET	AILS OF THE WO								
Vork inspected	By CHAD VE	ELTA				Certificate No	. KX5R005N		Date	29-Jun-201:	2				
Pertinent details	s of this mainten	ance are on file at ou	facility under the	above W	ork/Service Order N	lumber as applicabl	₽.					ļ			

Maintenance Transaction Record

MTR ID # 2021320

Page 3 of 3

CAMP Systems International 8200 E. 34TH STREET BUILDING 1600, SUITE 1607

Wichlta, KS 67226 Phone: 316-462-2267/ Fax: 316-462-0791

☑ Airframe Entries

Eng. #1 Serial No. ☐ Eng. #2 Serial No.

This Maintenance Report is To Be Used Solely For (Check One)

APU Serial No.

Aircraft Identification and Status Total A/C Hours Total A/C Landings Engine 1 Total Hrs Engine 2 Total Hrs Engine 1 Ttl Cycles APU Hrs APU Events Freon Hrs Engine 2 Ttl Cycles A/C Serial # A/C Unit # A/C Registration # Date City ID 781.4 N108EK 29-Jun-2012 KECM 4457.8 3075 4457.8 4457.8 3075 3075 560-5032 5032

		Component Chang	ges, Inspections, S	ervice Bulletins, or Airworthiness (Directives A	ccomplished					
Item	Transactio		Position	Part Number / Alternate Part	Mod Level	Part Serial	Removal Reason	-	nstalled Part s TSN/TSO/TSR	Material Costs	Man Hours
SL560XL-35-04 R1	18 3 Commen	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 SERVICE LETTER Its: SB in N/A by P/N installed in aircraft.									
2021320	19 - Commen	LH AVIONICS DOOR EXTENDER its: Instalfed new LH avionics door Extender P/N 6791051	-17	6791051-17			wo	N	OMTH OHRS		
2021320020	20 - Commen	PILOT'S SMOKE GOGGLE ats: Installed new Pilot Smoke Goggles P/N 9914067-40 in	PILOT'S aircraft.	9914067-40			wo	N	OMTH OHRS		
2021320021	21 - Commen	SURFACE SEAL hts: Applied PPG Quick Coating Kit P/N, D\$\$0200, S/N 12	PILOT'S. 102H42Z6 to the PI	DSS0200 ilot's windscreen.		12102H42Z6	WO	N	0 MTH 0 HR\$		
2021320022	22 -	BOLT	LH THRUST REVERSER	NAS6406U21D			WO	N	OMTH OHRS		
	Commen	its: Installed three new bolts P/N NAS6406U21D in the LH	thrust reverser.								

Trans. Type: 1 - Co	component, 2 - Inspection, 3 - SB, 4 - AD, Misc.	Removal Reasons: WO - Worn t	o Limita, SC - Scheduled	UN - Unscheduled, CO - Co	nvenience, N - Other(note in	comments) Installed Part Status: N - Nev
Repair Facility EL	LIOTT AVIATION OF MPLS	Certified Repair Station Number	KX5R005N		Work Order No.	459329
Work Perform	med By ELLIOTT AVIATION OF MPLS			Certificate No.	KX5R005N	Date 29-Jun-2012
certify th	hat the above stated maintenance and/or i	nspection was performed i	n accordance with	ine current regulations	s of the	
☑ Federal A	Aviation Administration	Other (Specify)				and
ELLIOTT AGENCY	TAVIATION CITATION 560XI. AAIP AND I	S APPROVED FOR RETU	JRN TO SERVICE.	. PERTINENT DETAI	LS OF THE WORK AS	RE ON FILE AT THIS
Work inspec				Certificate No.	<x5r005n< td=""><td>Date 29-Jun-2012</td></x5r005n<>	Date 29-Jun-2012
Pertinent deta	ails of this maintenance are on file at our f	acility under the above Wo	rk/Service Order N	umber as applicable.		

R - Repaired/Rebuilt, S - Serviceable, O - Overhauled Maintenance Log

Page

Section

Maintenance Transaction Record

MTR ID # 2004953

Page 1 of 1

CAMP Systems international 8200 E. 34TH STREET BUILDING 1600, SUITE 1607

Wichita, KS 67226

Phone: 316-462-2267/ Fax: 316-462-0791

cescom)
 Control of the second second

Comments: Removed part no: 10634T05Y00 Removed serial no; B580,

This Maintenance Report is To Be Used Solely For (Check One) ✓ Airframe ☐ Eng. #1 ☐ Eng. #2 Entries Serial No. Serial No

☐ APU Serial No

						CHAIL IDENTIFICATION	and otalus						
A/C Serial #	A/C Unit	# A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 Total Hrs	Engine 1 Tti Cycles	Engine 2 Tti Cycles	s APU Has	APU Events	Freon Hrs
560-5032	5032	N108EK	05-Jun-2012	KECM	4435.5	3048	4435.5	4435,5	3048	3048			781.4
			Сог	mponent Cl	nanges, Inspections,	Service Bulletins,	or Airworthiness D	irectives Accomplis	hed				
	Transaction							Mod	Re	moval Insta	lled Part	Materi	al Man
ltem	No. Type	Ite	m Name		Position	Part Number /	Alternate Part	Level Part	Serial Re	ason Status TS	N/TSO/TSR	Costs	Hours
284017 284017 : R	1 1 F	IGHT WING FUEL QTY	W4 PROBE		RIGHT WING	3 10834T05Y00	9912498-4	MN1	5727 UN	0 01	MTH 4435 HR	RS.	

Trans. Type: 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, - - Misc. Removal Reasons: WO - Worn to Limits, SC - Scheduled, UN - Unschaduled, CO - Convanience, N - Other(note in comments) Repair Certified Repair Work ELLIOTT AVIATION OF MPLS KX5R005N 459320 Facility Station Number Order No. Work Performed By ELLIOTT AVIATION OF MINNEAPOLIS Certificate No. KX5R005N Date 05-Jun-2012 I certify that the above stated maintenance and/or inspection was performed in accordance with the current regulations of the ☑ Federal Aviation Administration Other (Specify) IS APPROVED FOR RETURN TO SERVICE, PERTINENT DETAILS OF THE WORK ARE ON FILE AT THIS AGENCY. Work Inspected By LEIGH ZELINSKI Certificate No. KX5R005N Date 05-Jun-2012 Pertinent details of this maintenance are on file at our facility under the above Work/Service Order Number as applicable.

Installed Part Status: N - New, R - Repaired/Rebuilt, S - Serviceable, C - Overhauled

Page

Maintenance Transaction Record

This Maintenance Report is To Be Used Solely For (Check One)

MTR ID # 1992156

Page 1 of 1 CAMP Systems international

> **BUILDING 1600, SUITE 1607** Wichita, KS 67226

8200 E. 34TH STREET

Phone: 316-462-2287/ Fax: 316-462-0791

☑ Airframe Entries

Eng. #1 Serial No. ☐ Eng. #2 Serial No.

□ APU Serial No.

Aircraft Identification and Status A/C Serial # A/C Unit # A/C Registration # Date City ID Total A/C Hours Total A/C Landings | Engine 1 Total Hrs Engine 2 Total Hrs Engine 1 Ttl Cycles Engine 2 Ttl Cycles APU Hrs | APU Events | Freon Hrs 580-5032 5032 N108EK 17-May-2012 KFCM 4418 8 3048 44188

, Item	Transaction No. Type	Item Name	Position	Part Number / A	Iternate Part	Mod Level	Part Serial	Removal Reason	Installed Part Status TSN/TSO/TSR	Material Costs	Man Hours
5-92-01		TION DOCUMENT 1 ied with Inspection Document #1 per Elliot	t Aviation 560XL AAIP	7 500 432							
324003 324003 : L	2 1 LEFT M	AIN BRAKE ASSEMBLY	LEFT	2-1601	9912487-7		1531	WO	0		
	Comments: Remov under W/O# 42894	ved part no: 2-1601-1 Removed serial no: 129 for overhaul details. Bled brake, ops c	0681. Installed overhad heck good.	uled left hand brake a	assembly. Refe	rence Good	irich Aircraft Wheels	and Brakes FA	A form 8130 dated 3/30/12		
801000 801000 : R	3 1 RIGHT E	ENGINE STARTER/GENERATOR	RIGHT ENGINE	300\$GL138Q-4	9912499-6		6572XL	sc	0		
	Comments: Remov under W/O# 18585	ved part no: 300SGL138Q-4 Removed ser 5 for overhaul details. Ops check good	ial no: 8850XL. Installe	ed overhauled RH sta	arler generator.	Refernece	Southwind Aviation	Supply LLC FAA	A form 8130 dated 12/27/11		

rans. Type: 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, Misc.	Removal Reasons: WO - Worn to Limits, SC - Scheduled,	, UN - Unscheduled, CO - Convenience, N - Other(note in cor	omments) Installed Part Statu	s: N - New, R - Repaired/Rebuill, S - Serviceable, O - Overhad
Repair ELLIOTT AVIATION OF MPLS	Certified Repair KX5R005N Station Number	Work Order No.	459282	Maintenance Log Section Page
Work Performed By ELLIOTT AVIATION OF MPLS	7777774	Certificate No. KX5R005N	Date 17-May-2012	
I certify that the above stated maintenance and/or in	ispection was performed in accordance with t	the current regulations of the		
☑ Federal Aviation Administration	Other (Specify)		and	
ELLIOTT AVIATION CITATION 560XL AAIP AND IS AGENCY.	S APPROV A D FOR RETURN TO SERVICE	. PERTINENT DETAILS OF THE WORK ARE	E ON FILE AT THIS	
Work Inspected By TRAVIS JADAMS Pertinent details of this maintenance are on file at our fa	cillity ander the above Work/Service Order Nu	Certificate No. KX5R005N	Date 17-May-2012	_ .

Maintenance Transaction Record

MTR ID # 2034927

Page 1 of 1

CAMP Systems International

	- And the second second second second second	Chan.
	CESCOM	
-order	the Bally continues and a second	

and the same of th	or was the strong station to the strong state of				This Mainte	nance Report is To	Be Used Solely Fo	or (Check One)			4TH STREE		
(CES	COM	b	☐ Airframe	ΓTE	ng. #1	[vi Eng	#2	☐ APU		BUILDING	1600, SUI	TE 1607	
CONTRACTOR OF THE PARTY OF THE	, d	F	Entries	_	erial No.	Seri	al No. DB0060	Serial N	1 0.	Wichita, K	S 67226		
The state of the s	A THE PARTY AND ADDRESS OF THE PARTY AND ADDRE									Phone: 31	6-462-226	7/-Fax: 316-46	52-0791
	an an tamen a colorada son tamén a grapa grapa de grapa	koʻz da ishi misadiyi. Ta'yla soʻz amislanisi	and the section of th	kind Monace and agenture	A	ircraft Identification	and Slatus	and the state of t	and in a Section of the Section of S	an desiral construction of the second	(Kanadaka 1a.		
A/C Serial #	A/G Unit #	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 Total Hrs	Engine 1 Ttl Cycles	Engine 2 Ttl Cycles	APU Hrs	APU Events	Freon Hrs
560-5032	5032	N108EK	26-Jul-2012	KFCM	4474.5	3089	4474.5	4474.5	3089	3089			781.4
		entral Military States States	Со	mponent Cl	anges, Inspections	, Service Bulletins,	or Airworthiness Di	rectives Accomplist	ied				
	Transaction				•			Mod	Ren	noval Installe		Materia	al Man
Item	No. Type	Ite	em Name		Position	Part Number /	Alternate Part	Level Part S	Serial Rea	ison Status TSN	/TSO/TSR	Costs	Hours
2034927001	1 3 PW5	500-72-30443			RIGHT								
	Comments: SB	30443 not applicabl	e by fuel manifol	d installed 8	S/N 03564658-01 no	ot listed in table 3 of	builetin.			44-64-41			
2034927002		500-72-30457			RIGHT			,		-			
	Comments: No	nt applicable by eng 5	S/N as listed in a	oplicability s	section of bulletin.								

Repair Certified Repair Work	Maintenance Lot
Repair Facility ELLIOTT AVIATION OF MPLS Certified Repair Station Number Station Number Station Number Section	SHIP WATER TO SHIP OF
Work Performed By ELLIOTT AVIATION OF MINNEAPOLIS Certificate No. KX5R005N Date 28-Jul-2012	
I certify that the above stated maintenance and/or inspection was performed in accordance with the current regulations of the	
☑ Federal Aviation Administration ☐ Other (Specify) and	
THE AIRCRAFT IDENTIFIED ABOVE IS PRESENTLY APPROVED FOR RETURN TO SERVICE.	
Work Inspected By JEFF SOLBERG Certificate No. KX5R005N Date 26-Jul-2012	
Pertinent details of this maintenance are on file at our facility where the above Work/Service Order Number as applicable.	

This Maintenance Report is To Ba Used Solely For (Check One)

Maintenance Transaction Record

MTR ID # 2034916

Page 1 of 1

CAMP Systems International 8200 E. 34TH STREET

. 46	A STATE OF THE PROPERTY OF THE PARTY OF THE	ia.
A.	CESCOM	The same of the sa
William .		J
-418)	The same of the sa	,

CES	CUITI)	₽	☐ Airframe Entries	⊠ Er Se	ng, #1 erial No. DB0059	☐ Eng Seri	j. #2 jal No.	☐ APU Serial N	lo.	* BUILDING Wichita, R	3 1600, SU (S 67226	ITE 1607		
The state of the s	DAZIANO PER DE											7/ Fax: 316-4	62-0791	
			Secretary Control of Control	n in Standard Associate	A	ircreft Identification	and Status	nings on ministra	A COLUMN TO SERVICE STATE OF THE PROPERTY OF T		المالة إغرب ويستما بيايا	Park y Language		à
A/C Serial #	A/C Unit #	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 Total Hrs	Engine 1 Ttl Cycles	Engine 2 Ttl Cycles	APU Hrs	APU Events	Freon Hrs	•
560-5032	5032	N108EK	26-Jul-2012	KFCM	4474.5	3089	. 4474.5	4474.5	3089	3089			781.4	
	entres de la company de		Соп	ponent Ch	anges, inspections	Service Bulletins,	or Airworthiness D	irectives Accomplisi	ed .	The state of the s				è
	Transaction							Mod	Rem	ioval Installe	d Part	Materi	ial Man	_
Item	No. Туре	Ite	m Name		Position	Part Number /	Alternate Part	Level Part S	ierial Rea	son Status TSN	/TSO/TSR	Costs	Hours	
2034918001	1 3 PW	500-72-30443			LEFT									_
	Comments: SE	3 30443 not applicable	e by fuel manifold	installed S	S/N 03564655-01 n	ot listed in table 3 o	f bulletin.							
2034918002	2 3 PW	500-72-30457			LEFT			, , , , , , , , , , , , , , , , , , , ,						
	Comments; No	ot applicable by eng S	/N as listed in ap	plicability s	ection of bulletin									

Trans. Type:	1 - Component, 2 - Inspection, 3 - SE, 4 - AD, Misc.	Removal Reasons: WO - Worn t	o Limits, SC - Schedufed, Ut	N - Unscheduled, CO - C	Convenience, N - Other(note in co	omments)	Installed Part Status; N - N	ew, R - Repaired/Rebuilt, S - Serviceable, O - Overtrauled
Repair Facility	ELLICIT AVIATION OF MPLS	Certified Repair Station Number	KX5R005N		Work Order No.			Maintenance tob Section Page
Work Pe	rformed By ELLIOTT AVIATION OF MINNE	APOLIS		_ Certificate No.	KX5R005N		Date 26-Jul-2012	
l cent	ify that the above stated maintenance and/or in	spection was performed i	n accordance with the	current regulation	ns of the			
☑ Fede	ral Aviation Administration	Other (Specify)				and		
THE	AIRCRAFT IDENTIFIED ABOVE IS PRESENT	LY APPROVED FOR RE	TURN TO SERVICE,					
Work ins	pected By JEFF SOLBERG			_ Certificate No.	KX5R005N		Date 26-Jul-2012	
Pertinent	details of this maintenance are on file abour fa	cility under the above Wo	rk/Service Order Num	ber as applicable.				_