

**KHYI Airport
(Berry Aviation, Inc.)**

To whom it may concern:

After the aircraft accident on November 9, 2012 involving an aircraft that might possibly have been serviced here, we quarantined our fuel facility and ceased all fuel sales and fuel deliveries until after the fuel quality inspection was completed.

Separate samples of aviation gasoline were tested separately from each of the following

**10000 gallon above ground storage tank
750 gallon Avgas refueler
1000 gallon Self Serve above ground tank**

White Bucket Tests - When I put a sample of fuel in a clean white bucket, the fuel was the proper color and clarity. There was no evidence of debris or other contamination, and no water was present. The smell and feel of the fuel did not show any evidence of contamination from jet fuel or diesel fuel.

White Paper Tests - When I put a sample of fuel on a sheet of clean white paper the fuel evaporated quickly and left a slight stain of the fuel dye with no other residue. The smell of the dried sample on the white paper was the smell of gasoline. There was no evidence of contamination from water or jet fuel or diesel fuel.

**Filters were changed in March 2012, due for change in March 2013 on all three filter vessels
Received 4000 gallons of Avgas on November 8, 2012**

At the completion of the satisfactory fuel quality tests the quarantine was lifted and fuel deliveries were allowed to resume beginning at November 9, 2012, 10:00AM.

November 9, 2012, 10:00AM Chris Bagnall, Line Supervisor
