

ATTACHMENT 6 (two pages)

March 26, 2001

Mr. Steve McCreary National Transportation Safety Board 19518 Pacific Hwy South, Suite 201 Scaitle, WA 98158

Re: Southwest Flight 1455

Dear Steve:

Pursuant to our recent conversation. I have attached a copy of the current schedule for rubber deposit removal at Burbank Airport for the Year 2001. A schedule similar to the above, did exist for the prior years, unfortunately, copies were not retained. In checking our NOTAMS and accounting Files, the Following is a listing of when this work was performed in the prior two yeas:

1999

03/29/2000	Runways 8/26& 15/33	04/26/ 1999	Runway 8/26
06/16/2000	Runway 8/26	06/08/1999	Runway 5/26
09/19/2000	Runways 8/26& 15/33	08/30/1999	Runway 15/33
12/02/2000	Run way 8/26	09/02/1999	Runway 8/26
		12/16/1999	Runway 8/26

You will note from the above information that during 1999 rubber deposits were removed from Runway 15/33 on one occasion only. My recollection is that our contractor did expenence so mechanical difficulties and runway condition allowed us to waive this work on that occasion. I hope this information is of benefit to you. Should you have any further questions or concerns please do not hesitate to contact me at

Mark D. Hardyment

Director, Operations & Maintenance

MDH:mp

Enc.

RUBBER REMOVAL

SCHEDULE - 2001

MONTH RUNWAY SQUARE FOOTAGE

FEBRUARY RUNWAY 8 2000' X 60' = 120,000 SQ. FT.

RUNWAY 15 $2000' \times 60' = 120,000 \text{ SQ. FT.}$

(ACTUALLY ACCOMPLISHED 3-16 & 3-17 BECAUSE OF WEATHER AND PRIOR COMMITMENTS BY CONTRACTOR)

MAY RUNWAY 8 $2000' \times 60' = 120,000 \text{ SQ. FT.}$

AUGUST RUNWAY 8 $2000' \times 60' = 120,000 \text{ SQ. FT.}$

RUNWAY 15 $2000' \times 60' = 120,000 \text{ SQ. FT.}$

NOVEMBER RUNWAY 8 $2000' \times 60' = 120,000 \text{ SQ. FT.}$