







## **ATTACHMENT 2**

**AIRWORTHINESS GROUP CHAIRMAN'S FACTUAL REPORT**

**DCA12FA024**

**Parts Control Tag for Replacement Collective Torque Shaft Support Bracket**

**(1 page)**

PRESIDENTIAL AIRWAYS		Parts Control Tag	
Nomenclature: <u>SUPPORT BRACKET</u> Part Number: <u>214-001-111-001</u> Serial Number: <u>NSN</u> TSN <u>Ø</u> CSN _____ TSO <u>Ø</u> CSO _____ <input checked="" type="checkbox"/> New <input type="checkbox"/> Serviceable <input type="checkbox"/> Overhauled <input type="checkbox"/> Cont. Time <input type="checkbox"/> Bench Checked <input type="checkbox"/> _____ <input type="checkbox"/> Cannibalized From: _____ Flt. Log: _____		INSTALLATION INFO: Acft/Eng #: <u>N3897N</u> Position: <u>LWR COLLECTIVE</u> Date: <u>1-15-12</u> Flt Log: <u>023378</u> Tech:  A&P #: 	
Rec'd  Rep. Issn  Date <u>1-15-12</u>		REMOVAL INFO: Part Number: <u>214-001-111-001</u> Serial #: <u>NSN</u> Acft/Eng #: <u>N3897N</u> Position: <u>LWR COLLECTIVE</u> Date: <u>1-15-12</u> Flt. Log: <u>023378</u> Reason for Removal: <u>BEARING WORN</u>	
Shelf Life _____ Hydro _____ PO # _____		_____ _____ _____ _____ _____	