



Photo 5: Digital photograph of the R/H Control Tab clevis fitting. View looking aft and outboard. Note the damage to the forward face of the clevis lugs.