DOCKET NO. SA-510

NATIONAL TRANSPORTATION SAFETY BOARD WASHINGTON, D.C.

Rudder Blowdown Model

October 7, 1994 B-U01B-14950-ASI

Mr. Thomas Haueter, AS-10 National Transportation Safety Board 490 L'Enfant Plaza East SW Washington DC 20594

BOEING

Subject: US Air 737-300 Accident, N513AU/PP033 Near

Pittsburgh Pennsylvania, September 8, 1994 - Rudder Blowdown

Dear Mr. Haueter:

A copy of the enclosed rudder blowdown model was provided to Mr. Tom Jacky during the week of September 19, 1994 to be used by the Performance Group in the subject investigation.

If you have any questions, please contact Rick Howes, or me.

Very truly yours,

FLIGHT TEST


John W. Purvis

Director, Air Safety Investigation

Org. B-U01B, M/S 14-HM

Telex 32-9430, STA DIR PURVIS

Enclosure: 737-300 Rudder Blowdown Model, July 22, 1987



October 7, 1994 B-U01B-14952-ASI

Mr. Thomas Jacky, RE-60 National Transportation Safety Board 490 L'Enfant Plaza, SW Washington DC 20594-2000

BOEING

Subject: US Air 737-300 Accident, N513AU/PP033 Near

Pittsburgh, Pennsylvania, September 8, 1994 - Video

Dear Mr. Jacky:

During the NTSB Performance Group meeting in Seattle, Washington on September 21 and 22, 1994, you requested a copy of the enclosed video. This video captures on film certain wake turbulence tests that were conducted by Boeing in 1970.

If you have any questions, please contact Rick Howes,

or me.

Very truly yours,

FLIGHT TEST

John W. Purvis

Director, Air Safety Investigation

Org. B-U01B, M/S 14-HM

Enclosure: Video 6570 C7, "747-737 Jet Wake from XMP 1284, 1316, 1311,

1318, dated February 19, 1970

cc: Mr. Thomas Haueter, AS-10