From: To:

Subject: Re: CEN20CA037 - Question

**Date:** Tuesday, December 31, 2019 15:40:33

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

We landed into the wind on the tarmac before I got out wind was roughly out of 120 and we were practicing using that runway that day. So roughly around their I believe. Usually we set down closer to hanger but beings he felt more comfortable further out we landed out away from hangers bout mid way on tarmac. Please let me know if their is anything else I can do.

Thanks ahead,

Brandon Nau | Managing Member Top Gun Precision Ag, LLC. Dba Ace High Helos

Cell

Skidmore, TX 78389 | USA

Email: ; ; ; ;

On Dec 31, 2019, at 2:20 PM, Hodges Michael wrote:

Hi Brandon,

I hope you are doing well.

I have a quick question please regarding the accident – do you recall what the heading (roughly) of the helicopter was for the takeoff sequence with the solo student pilot?

Thank you.

Mike

Mike J. Hodges, MS, AHP
Air Safety Investigator
Central Regional Office - Colorado
Office of Aviation Safety
National Transportation Safety Board

4760 Oakland Street, Suite 500 Denver, Colorado 80239-2793 United States of America http://www.ntsb.gov

Cellular/SMS:
Facsimile:

Response Operations Center (24/7): 1-844-373-9922

Integrity - Transparency - Independence - Excellence "From tragedy we draw knowledge to improve the safety of us all."

CONFIDENTIALITY NOTICE - THIS E-MAIL TRANSMISSION MAY CONTAIN INFORMATION THAT IS PRIVILEGED, CONFIDENTIAL, PROPRIETARY, SUBJECT TO COPYRIGHT, AND/OR EXEMPT FROM DISCLOSURE UNDER APPLICABLE LAW. IT IS FOR THE USE OF INTENDED RECIPIENTS ONLY. If you are not an intended recipient of this message, please notify the original sender immediately by forwarding what you received and then delete all copies of the correspondence and attachments from your computer system. Any use, distribution, or disclosure of this message by unintended recipients is not authorized and may be unlawful.