

Review of CSXT LDVR Locomotive Video Downloads

CSXT 1514 Y32231 View in motion provided shows the crew pulling cars from the CSX South Yard to the BIDS Terminal in North Yard via 2 BY Tower into Y14. View is in the north direction blocked by a tank car. Accident scene is out of view.

CSXT 8726 Q43930 View provided is still, sitting on 4Main at AY facing south as the lead engine. Footage verifies Q40130 departure out of North yard. Complete loco consist consists of CSXT 8726, 7639, 694. Accident scene is out of camera view.

CSXT 694 Video footage is also in still form, of the third locomotive facing south on 4Main in the consist of Q43930. This video allowed us to view the number board of locomotive CSXT 5000 which was from the lead engine off the Q40130 passing alongside. Accident scene is out of camera view.

CSXT 5000 This lead unit, facing South on train Q40130 was traveling south on 3main in between a cut of cars to the left on Old 2Main and Q43930 on the right. At 02:44 (4/1/15) we see the Y39131 RCOF five cars away from the locomotive CSXT 8463 in addition to the yellow strobe light flashing. At 02:46 we see the lights of the car inspectors' truck in the On position and the train stopping to pick up the conductor of Q40130. At 02:28 Q40130 departs ACCA and the accident scene is out of camera view.