

Air Services, Inc.

Estimate

FAA Certified Repair Station# Z4AR547Y

[REDACTED]

Carrollton, GA 30117

Date	Estimate #
10/19/2015	746

Name / Address
Flightlease LLC

Description	Qty	Cost	Sales Tax	Total USD
N442DD - 2010 Czech Sport Aircraft Piper Sport - SN P1001046				
Labor - Travel to Spartanburg, SC disassemble aircraft and transport to Carrollton, GA	30.00	95.00		2,850.00
Equipment for transport to relocate	1.00	450.00		450.00
Labor - Replace side skins from main gear stress	60.00	95.00		5,700.00
Labor - Replace firewall assembly, belly skin and supporting structure behind firewall and under floor	90.00	95.00		8,550.00
Labor - R & R engine and propeller	18.00	95.00		1,710.00
Labor - Reassemble aircraft and rig	22.00	95.00		2,090.00
Labor - Paint to match repair areas	1.00	2,500.00		2,500.00
Freight	1.00	640.00		640.00T
Parts - Aircraft parts nose gear assembly	1.00	5,877.75		5,877.75T
Parts - SF0104N Belly skin	1.00	514.65		514.65T
Parts - SF0101N	1.00	434.35		434.35T
Parts - LH Main gear assembly	1.00	1,010.00		1,010.00T
Parts - RH Main gear assembly	1.00	1,010.00		1,010.00T
Parts - SF0194L Angle outer floor LH	1.00	36.55		36.55T
Parts - SF0194P Angle outer floor RH	3.00	36.55		109.65T
Parts - SF0193L Angle inner floor LH	1.00	69.15		69.15T
Parts - SF0193P Angle inner floor RH	1.00	69.15		69.15T
Parts - SF0182L Reinforcement LH outer	2.00	53.20		106.40T
Parts - SF0182P Reinforcement RH outer	2.00	53.20		106.40T
Parts - Propeller assembly	1.00	3,994.45		3,994.45T
Parts - SF0157L Reinforcement LH NLG	1.00	92.45		92.45T
Parts - SF0157P Reinforcement RH NLG	1.00	92.45		92.45T
Parts - SF0101P/L	2.00	404.78		809.56T
Parts - SF0150N Bracket bulkhead lower inner	1.00	71.00		71.00T
Parts - SF0131N Bracket bulkhead upper inner	1.00	67.78		67.78T
Parts - SF0152N Angle lower forward	1.00	92.15		92.15T

Sales Tax (7.0%)
Total USD

Phone #	Fax #	E-mail	Web Site
[REDACTED]	[REDACTED]	[REDACTED]	www.airservicesinc.org

Air Services, Inc.

FAA Certified Repair Station# Z4AR547Y

Carrollton, GA 30117

Estimate

Date	Estimate #
10/19/2015	746

Name / Address
Flightlease LLC

Description	Qty	Cost	Sales Tax	Total USD
NOTE: ENGINE PROP-STRIKE INSPECTION \$1500.00 to \$7500.00 Cost is unknown until Rotax clarifies what is necessary for this particular prop-strike.				

Sales Tax (7.0%)	\$1,064.27
Total USD	\$40,118.16

Phone #	Fax #	E-mail	Web Site
[REDACTED]	[REDACTED]	[REDACTED]	www.airservicesinc.org