

NATIONAL TRANSPORTATION SAFETY BOARD

Vehicle Recorder Division

Washington, D.C. 20594

November 02, 2009

Cockpit Voice Recorder - 12 Errata

**Group Chairman's Factual Report
by Joseph A. Gregor**

A. EVENT

Location: Columbia, SC
Date: September 19, 2008, 23:53 EDT *
Aircraft: LearJet 60, N999LJ
Operator: Inter Travel & Services
NTSB Number: DCA08MA098

The CVR group unanimously agreed to make the following change to CVR transcript for the purpose of clarifying the sequence of events near the end of the recording. The following items should be changed in the CVR transcript to accurately reflect the consensus of the Group:

1. Page 12-39, CVR Transcript, INTRA-COCKPIT COMMUNICATION:

Change:

23:55:19.5 HOT-1	pull out.
----------------------------	-----------

To read:

23:55:19.5 HOT-1	full out.
----------------------------	-----------

JOSEPH A. GREGOR
Vehicle Recorder Specialist

* All times are expressed in eastern daylight time (EDT), unless otherwise noted.