

DCA11FR002
Collision - BNSF
Red Oak, Iowa
April 17, 2011

BNSF
Employee PPI Detail
Conductor Striking Train

Employee PPI Detail

Hyatt, PA XXXXXXXXXX

Points Matrix

CONDUCTOR (UTU)	Engineering	Level I & II	180 0181
Supervisor	Huston, MR	Home Terminal	CRESTON, IA

Total Points 7

Points Detail	Count	Last	Points
Reportable Injuries	0		0
Nonreportable Injuries	0		0
Human Factor REI	0		0
Critical Test Failures	0		0
Other Test Failures	5	6/24/2009	7

Opts Tests	Date	Rule Book	Rule Number	Description	Points
607	5/3/2006	T	607-1	Signal Awareness Form	1
607	5/20/2006	T	607-1	Signal Awareness Form	1
699	10/4/2006	S	26.6	All Other Failures	1
609	8/28/2007	G	609-2	Whistle Signal / Grade Crossing	1
823	6/24/2009			Form A Speed Restriction	3
Total Opts Tests Point					7