

DCA11FR002
Collision - BNSF
Red Oak, Iowa
April 17, 2011

BNSF
Employee PPI Detail
Conductor Struck Train

Employee PPI Detail

Pate, CD XXXXXXXXXX

Points Matrix

CONDUCTOR (UTU) Transportation Level I & II NEB 1410
 Supervisor Lehman, SE Home Terminal CRESTON, IA

Total Points 33

Points Detail	Count	Last	Points
Reportable Injuries	0		0
Nonreportable Injuries	0		0
Human Factor REI	3	3/9/2006	0
Critical Test Failures	1	11/13/2008	13
Other Test Failures	12	10/25/2008	20

HF REIs	Date	FRA Rep	Primary Cause	Secondary Cause	Points
<u>SC-0804-113</u>	8/10/2004	N	H702		0
<u>CA-0205-105</u>	2/5/2005	Y	H702	H704	0
<u>CA-0306-116</u>	3/9/2006	N	H018	H318	0

Total HF REI Points 0

Opts Tests	Date	Rule Book	Rule Number	Description	Points
601	11/22/2006	G	MAX TT SPEED	Speed Requirements	1
699	11/22/2006	T	1 (D)7	All Other Failures	1
699	6/7/2007	S	13.1.2	All Other Failures	1
699	6/18/2007	G	1.15	All Other Failures	1
699	6/27/2007	O	G.N.528-T/S	All Other Failures	1
699	1/3/2008	S	1.3.1	All Other Failures	1
603	2/22/2008			Radio Usage	1
699	3/6/2008	S	21.1	All Other Failures	1
612	4/20/2008	T	612-3	TWC Meeting Point/Signal in	3
699	7/27/2008	G	1.15	All Other Failures	3
621	8/21/2008	G	5.8.2	Roadway Worker Compliance	3
699	10/25/2008	S	21.1	All Other Failures	3
102	11/13/2008			Between Cars/Locomotives	13

Total Opts Tests Point 33