

[49]  
**UNION PACIFIC RAILROAD 204x**  
**CONDUCTOR REPORT**

This report must be completed by the Conductor of road freight trains on each trip or tour of duty. Conductors must keep reports in their possession of the last 5 round trips, which must be presented to managers upon request. Report all signals more restrictive than Clear (abbreviations may be used). Report all Train Defect Detector (TDD) announcements. Report other train delays.

Subdivision: Sharon Spgs Train/Job ID: LDG89 15

Conductor: Iverson Engineer: Nothman

Departure Date/Time: 7/15 Arrival Date/Time:  
1750

Location	Signal Name or TDD Announcement	Time	Comments & Other Delays
mp 192		1805	x 15
1928	TDD	1810	ND 204x 28
Bavaria	Stopped	1815	5/0 2 196x
	↳ 15m		
mp 197		1838	x 35
Brookville	Stopped	1845	5/0 9 160x
	↳ 15m		
mp 208		1902	x 31
mp 207		1913	x 44
mp 212		1921	x 32
2125	TDD	1924	ND 160x
Kanopolis	Stopped	1937	5/0 4 144x 15m
mp 217			x 28
mp 222		2004	x 31
227		2012	x 46
mp 232		2052	x 17
Blackwell	Stopped	2020	P/0 3 156x
	↳ 30m		
2363	TDD	2101	ND 156x
mp 237		2101	x 45
mp 242		2108	x 40
mp 247		2119	x 45
mp 252		2124	x 30
mp 2550	TDD	2130	ND 156x
mp 257		2131	x 44
Dis. ell	Stopped	2145	5/0 17 P/0 13
			144x

1:55  
 /e:

Location	Signal Name or TDD Announcement	Time	Comments & Other Delays
262		2110 x	14
267		2345 x	45
272		2352 x	49
Walker	Stopped	2357	Move 1
LD	13m		
2710	TDD	0014	ND 144
277		0014 x	49
282		0022 x	45
287		0028 x	48
Hays	Stopped	0082	Putaway
LD	Line back	0036	JRI D. 90

Conductor Signature: \_\_\_\_\_