MP 608 – Marshall, Michigan Incident NTSB/PHMSA Information Request No. 104

104 Reference: Email request by Matt Nicholson of November 9, 2010

Preamble:

Request: Provide AOC's and FACMAN's filed from July 23rd to July 27th,

2010

Requested by November 26, 2010

Response:

The following 3 FACMANs were created No AOC were generated during this time period:

- L-6 5 min m b s alarm, (5 Min) (MBS-6-13-GT-MR;)(starts 25-jul-2010 15:02)
- L-6 465.38 densitometer not working. Had to be sent in to be fixed. (starts 26-jul-2010 08:32)
- L-6 Suspected Rate Loss, Unable to start up 6B due to problems at MR. (starts 26-jul-2010 01:00)