

June 12, 1995
B-U01B-15283-ASI

Mr. Thomas Haueter, AS-10
National Transportation Safety Board
490 L'Enfant Plaza SW
Washington D.C. 20594

BOEING

Subject: Photos USAir 737-300 N513AU Accident Near Pittsburgh -
September 8, 1994

Reference: Letter B-U01B-15280-ASI Purvis/Haueter, June 9, 1995

Dear Mr. Haueter:


Further to the reference letter, please find enclosed photographs of the crew oxygen bottle and portion of three floor track segments for the crew seats on the subject airplane. (There are eight of these floor track segments per airplane; four for the captains seat and four for the first officers seat.) These photos were taken by Rick Howes last week while working with Mr. H. Hughes at the reconstruction sight in Pittsburgh.

Each print is labeled on the reverse side for specific identification in case you want to discuss a particular print on the phone, or if you request additional photo reproduction from us.


If you have any questions, please contact me.

Very truly yours,

FLIGHT TEST.



John W. Purvis
Director, Air Safety Investigation
Org. B-U01B, Mail Stop 14-HM
Telex 32-9430, STA DIR PURVIS



Enclosure: 25 - 5 X 7 inch colored prints, REG #RH08-1 through RH08-25