## MCDONNELL DOUGLAS

Douglas Aircraft Company 3855 Lakewood Boulevard, Long Beach, California 90846-0001

> C1-L70-SRL-97-L074 30 June, 1997

Mr. Thomas Conroy Investigator-In-Charge Major Investigations Division (AS-10) National Transportation Safety Board 490 L'Enfant Plaza, S. W. Washington, D. C. 20594-2000

**Subject:** Douglas Aircraft Company Post-Hearing Submission: Delta Air Lines MD-88 Uncontained Engine Failure Accident, Pensacola, Florida, 6 July 1996 (DCA96MA068)

Reference: T. R. Conroy Letter to Party Coordinators Dated 6 May 1997

Dear Mr. Conroy:

Pursuant to the reference letter and Title 49 Code of Federal Regulations Chapter VIII, 5845.27, the attached is respectfully transmitted for the Safety Board's consideration as the Douglas Aircraft Company (DAC) submission regarding the subject accident. Fifteen copies of this submittal are hereby provided to the Board, and copies have been served on all Parties to the investigation listed in the referenced letter.

Sincerely,

will a stall

William C. Steelhammer Senior Accident Investigation Coordinator Douglas Aircraft Company Flight Operations (MC 0094-0025)