



Exhibit 24-Photo Showing Right Side Damage to Anti-Climber Assembly of BNSF 9159