



Exhibit 32-Photo Showing Left Side Centersill Separation from the Top Plate on BNSF 9159