

Fri, June 03, 2016 06:25:50 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 01/02/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 01/02/2015 06:30:44 PM
Date Inspection Closed by Inspector: 01/02/2015 06:21:04 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	452.83	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	451.19		BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	419.10	Number of Bolts : 0	121E-121.E - Less than 2 bolts	213.9B	01/02/2015	Installed bolt or bolts	01/02/2015		Missing bolts at corner where rail end meets interlocker. Took pine bluff main out of service and placed 10 MPH on LR side. Gang called to repair same day.
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	419.10		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	01/02/2015	Corr from Trk Mtce Plan	01/02/2015		Replce missing bolts at interlocker

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 06:26:35 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 01/06/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Lo Bennett
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 01/06/2015 06:14:09 PM
Date Inspection Closed by Inspector: 01/06/2015 06:08:48 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Lo Bennett inspected from texarkana to redwater, Wright and Mack redwater to Omaha, wright alone from Omaha to Mt Pleasant.

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

[Top of Page](#)

Fri, June 03, 2016 06:26:50 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 01/07/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 01/07/2015 03:40:36 PM
Date Inspection Closed by Inspector: 01/07/2015 03:32:58 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail King Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD 01 061		418.60	418.77	No	BOKENKAMP	PASLAY	#61 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD 01 044		418.60	418.98	No	BOKENKAMP	PASLAY	#44 YARD TRACK #4
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE 01 105		416.35	418.60	No	BOKENKAMP	HOOK	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD 01 053		418.57	418.57	No	BOKENKAMP	PASLAY	#53 YARD TRACK #13
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD 01 054		418.60	418.60	No	BOKENKAMP	PASLAY	#54 YARD TRACK #14
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD 01 052		418.58	418.58	No	BOKENKAMP	PASLAY	#52 YARD TRACK #12
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD 01 042		417.84	418.60	No	BOKENKAMP	PASLAY	#42 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 CROS 77 022		418.58	418.60	No	BOKENKAMP	PASLAY	#22 W. CROSSOVER 042-044
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD 01 044		417.81	418.60	No	BOKENKAMP	PASLAY	#44 YARD TRACK #4
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 CROS 77 024		418.38	418.43	No	BOKENKAMP	PASLAY	#24 E. CROSSOVER 042-044
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD 01 061		417.75	418.60	No	BOKENKAMP	PASLAY	#61 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 CROS 77 023		418.47	418.51	No	BOKENKAMP	PASLAY	#23 CROSSOVER MAIN-042
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE 01 105		418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 CROS 77 022		418.60	418.62	No	BOKENKAMP	PASLAY	W CROSSOVER 042-044
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD 01 042		418.60	419.05	No	BOKENKAMP	PASLAY	#42 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 CNRT 01 600		418.89	419.14	No	BOKENKAMP	PASLAY	OLD TRANSFER OFF LITTLE ROCK

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE 01 105		416.35	418.60	No	BOKENKAMP	HOOK	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE 01 105		418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
Comments										

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE 01 105	419.01		127A2-127.A2 - Insufficient fas	Scheduled for Repair	01/07/2015	Corr from Trk Mtce Plan	02/04/2015		Gage and plug 3 ties. Marked with one ribbon.
PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD 01 042	418.74		127A3-127.A3 - Insufficient fas	Scheduled for Repair	01/07/2015	Corr from Trk Mtce Plan	01/21/2015		1 car west of shanty joint marked with a ribbon. Plug and gage joint ties.
PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD 01 042	418.74		127A3-127.A3 - Insufficient fas	Scheduled for Repair	01/07/2015	Corr from Trk Mtce Plan	01/21/2015		1/2 car west of shanty joint marked with a ribbon. Plug and gage joint ties.

Switches Inspected

Switch Inspected by	Subdivision	Original Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
			Segment/Track	ZTS		Segment/Track	ZTS		
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 044	418.38	2766 CROS	77 -024	CROSSOVER 042-044	RBM Standard Point
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 042	418.43	2766 CROS	77 -024	CROSSOVER 042-044	RBM Standard Point
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 044	418.45	2767 YARD	01 -061	EE 061	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 042	418.47	2766 CROS	77 -023	CROSSOVER 023-#1 MAIN	

Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN	-	418.51	2766 CROS	77 -023	CROSSOVER 023-042	RBM Standard Point
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN	-	418.55	2766 YARD	01 -049	NEW TRANSFER TO LITTLE ROCK	Spring-All Rail Extd length
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 044	418.557	2766 YARD	01 -054	EE 054	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 044	418.571	2766 YARD	01 -053	EE 053	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 042	418.58	2766 CROS	77 -022	CROSSOVER 022	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 044	418.582	2766 YARD	01 -052	EE 052	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 044	418.62	2767 CROS	77 -022	CROSSOVER 044-042	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 044	418.63	2767 YARD	01 -050	EE 050	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 044	418.64	2766 YARD	01 -049	EE 049	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 044	418.66	2767 YARD	01 -046	EE 046	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 044	418.68	2767 YARD	01 -045	EE 045	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 - 105	418.77	2766 YARD	01 -061	WE 061	Solid Mang. Self Guarding
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 042	418.98	2767 YARD	01 -044	WE 044	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 - 105	419.05	2767 YARD	01 -042	WE 042	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 - 105	419.12	2779 INDU	02 -748	SIDING TO KERMAGIE LEAD	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	-	419.14	2767 CNRT	01 -600	OLD TRANSFER OFF LITTLE ROCK	Spring-All Rail Extd length
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	-	419.16	2767 SIDE	01 -105	SIMN TO SIDING	

Switch Defects
No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 06:27:04 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 01/08/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 01/08/2015 05:29:40 PM
Date Inspection Closed by Inspector: 01/08/2015 05:14:47 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	419.10		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	01/08/2015	Corr from Trk Mtce Plan	01/14/2015		missing bolts in interlockers

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 06:27:15 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 01/08/2015 **Inspected By:** RYAN Wright
Inspection Type: Special **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 01/08/2015 05:29:40 PM
Date Inspection Closed by Inspector: 01/08/2015 05:18:29 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Cold Weather Inspection

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

Top of Page

Fri, June 03, 2016 06:27:28 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 01/13/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Harris
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 01/13/2015 04:53:10 PM
Date Inspection Closed by Inspector: 01/13/2015 04:41:55 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Wright from Tex to Omaha - Harris from Omaha West.

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

[Top of Page](#)

Fri, June 03, 2016 06:27:37 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 01/16/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 01/17/2015 03:59:25 PM
Date Inspection Closed by Inspector: 01/16/2015 02:46:27 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2765 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	423.00		BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.09	Number of Bolts : 1	121E-121.E - Less than 2 bolts	Repaired Before Traffic	01/16/2015	Installed bolt or bolts	01/16/2015		
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.09		127A3-127.A3 - Insufficient fas	Repaired Before Traffic	01/16/2015	Installed additional fasteners	01/16/2015		missing spikes at joint. Replaced spikes.
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	01/16/2015	Corr from Trk Mtce Plan	01/20/2015		missing multiple frog bolts.

Switch Defects

No switch defect records found

[PRINT](#)

[PRINTER FRIENDLY](#)

[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

Top of Page

Fri, June 03, 2016 06:27:49 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 01/20/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Allen
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 01/20/2015 03:53:26 PM
Date Inspection Closed by Inspector: 01/20/2015 03:34:59 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Allen ran from 417.48 to CB419 Wright CB419 to Big Sandy

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#)

[PRINTER FRIENDLY](#)

[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

Top of Page

Fri, June 03, 2016 06:28:00 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 01/22/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** P A Allen
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 01/22/2015 10:22:24 PM
Date Inspection Closed by Inspector: 01/22/2015 10:05:39 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments
Allen from Omaha to Mt Pleasant. Wright and Harris Texarkana to Omaha.

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	01/22/2015	Corr from Trk Mtce Plan	02/22/2015		missing interlocker bolts

Switches Inspected

Switch Inspected by	Subdivision	Original Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
			Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN	-	418.51	2766 CROS	77 -023	CROSSOVER 023-042	RBM Standard Point
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN	-	418.55	2766 YARD	01 -049	NEW TRANSFER TO LITTLE ROCK	Spring-All Rail Extd length
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	-	419.14	2767 CNRT	01 -600	OLD TRANSFER OFF LITTLE ROCK	Spring-All Rail Extd length
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	-	419.16	2767 SIDE	01 -105	SIMN TO SIDING	

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 06:28:10 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 01/22/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 01/22/2015 10:22:24 PM
Date Inspection Closed by Inspector: 01/22/2015 10:10:03 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 CNRT	01 600	418.89	419.14	No	BOKENKAMP	PASLAY	OLD TRANSFER OFF LITTLE ROCK

Track Traversed Information

- NONE -

Comments

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

Top of Page

Fri, June 03, 2016 06:28:22 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 01/27/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 01/27/2015 11:53:57 PM
Date Inspection Closed by Inspector: 01/27/2015 11:47:02 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	453.00	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	453.00	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	419.10		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	01/27/2015	Corr from Trk Mtce Plan	02/22/2015		3 interlocker bolts out

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 06:28:33 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 01/30/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Harris
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 01/30/2015 04:32:57 PM
Date Inspection Closed by Inspector: 01/30/2015 04:22:04 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2762 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2762 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	451.19		BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Harris 461 to 488 - Wright 417.48 to 461

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	01/30/2015	Corr from Trk Mtce Plan	02/22/2015		Interlocker bolts

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 06:28:43 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 02/03/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 02/03/2015 03:57:10 PM
Date Inspection Closed by Inspector: 02/03/2015 03:52:21 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.00	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.00	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	02/03/2015	Corr from Trk Mtce Plan	02/22/2015		interlocker bolts

Switch Defects
No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 06:28:53 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 02/05/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 02/05/2015 05:17:34 PM
Date Inspection Closed by Inspector: 02/05/2015 05:07:30 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 044	417.81	418.60	No	BOKENKAMP	PASLAY	#44 YARD TRACK #4
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 042	417.84	418.60	No	BOKENKAMP	PASLAY	#42 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 061	418.60	418.77	No	BOKENKAMP	PASLAY	#61 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 052	418.58	418.58	No	BOKENKAMP	PASLAY	#52 YARD TRACK #12
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 054	418.60	418.60	No	BOKENKAMP	PASLAY	#54 YARD TRACK #14
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 CROS	77 022	418.58	418.60	No	BOKENKAMP	PASLAY	#22 W. CROSSOVER 042-044
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 CROS	77 022	418.60	418.62	No	BOKENKAMP	PASLAY	W CROSSOVER 042-044
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 061	417.75	418.60	No	BOKENKAMP	PASLAY	#61 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 CROS	77 024	418.38	418.43	No	BOKENKAMP	PASLAY	#24 E. CROSSOVER 042-044
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 CNRT	01 600	418.89	419.14	No	BOKENKAMP	PASLAY	OLD TRANSFER OFF LITTLE ROCK
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 CROS	77 023	418.47	418.51	No	BOKENKAMP	PASLAY	#23 CROSSOVER MAIN-042
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 044	418.60	418.98	No	BOKENKAMP	PASLAY	#44 YARD TRACK #4
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 042	418.60	419.05	No	BOKENKAMP	PASLAY	#42 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 053	418.57	418.57	No	BOKENKAMP	PASLAY	#53 YARD TRACK #13
Track Traversed Information										
- NONE -										
Comments										

Track Defects

No track defect records found

Switches Inspected

Switch Inspected by	Subdivision	Original Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
			Segment/Track	ZTS		Segment/Track	ZTS		
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 044	418.38	2766 CROS	77 -024	CROSSOVER 042-044	RBM Standard Point
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 042	418.43	2766 CROS	77 -024	CROSSOVER 042-044	RBM Standard Point
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 044	418.45	2767 YARD	01 -061	EE 061	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 042	418.47	2766 CROS	77 -023	CROSSOVER 023-#1 MAIN	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 044	418.557	2766 YARD	01 -054	EE 054	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 044	418.571	2766 YARD	01 -053	EE 053	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 042	418.58	2766 CROS	77 -022	CROSSOVER 022	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 044	418.582	2766 YARD	01 -052	EE 052	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 044	418.62	2767 CROS	77 -022	CROSSOVER 044-042	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 044	418.63	2767 YARD	01 -050	EE 050	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 044	418.64	2766 YARD	01 -049	EE 049	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 044	418.66	2767 YARD	01 -046	EE 046	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 044	418.68	2767 YARD	01 -045	EE 045	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 042	418.98	2767 YARD	01 -044	WE 044	

Switch Defects
No switch defect records found



[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

[Top of Page](#)

Fri, June 03, 2016 06:29:06 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 02/06/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 02/06/2015 06:22:01 PM
Date Inspection Closed by Inspector: 02/06/2015 06:17:26 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.00	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.00	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

Top of Page

Fri, June 03, 2016 06:29:16 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 02/10/2015	Inspected By: RYAN Wright
Inspection Type: FRA Required	Relief Inspector: J.W.Harris
Weather: Clear	How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 02/10/2015 07:16:44 PM
Date Inspection Closed by Inspector: 02/10/2015 07:08:03 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		419.20	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		419.20	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Wright tex to 458 - Harris 458 to Mt Pleasant

Track Defects

No track defect records found

Switch Defects

No switch defect records found



[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

Top of Page

Fri, June 03, 2016 06:29:29 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 02/11/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 02/11/2015 05:55:15 PM
Date Inspection Closed by Inspector: 02/11/2015 05:43:23 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.20	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.20	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Comments

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#)

[PRINTER FRIENDLY](#)

[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

Top of Page

Fri, June 03, 2016 06:29:41 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 02/13/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 02/13/2015 03:26:23 PM
Date Inspection Closed by Inspector: 02/13/2015 03:18:02 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	423.00		BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE 01 105	418.80		121D2-121.D2 - Less than 1 bolt	213.9B	02/13/2015	Corr from Trk Mtce Plan	02/19/2015		Left rail
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE 01 105	418.80		121D2-121.D2 - Less than 1 bolt	213.9B	02/13/2015	Corr from Trk Mtce Plan	02/19/2015		right rail
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10	Number of Bolts : 1	121E-121.E - Less than 2 bolts	Repaired Before Traffic	02/13/2015	Installed bolt or bolts	02/13/2015		1 bolt in corner of interlocker where rail end meets
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10	Number of Bolts : 1	121E-121.E - Less than 2 bolts	Repaired Before Traffic	02/13/2015	Installed bolt or bolts	02/13/2015		1 bolt in corner of interlocker where rail end meets
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	02/13/2015	Corr from Trk Mtce Plan	02/22/2015		missing interlocker bolts

Switch Defects
No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 06:29:50 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 02/17/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Lo Bennett
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 02/17/2015 05:43:00 PM
Date Inspection Closed by Inspector: 02/17/2015 05:33:13 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

tex to 464 bennett 464 to BS wright

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#)

[PRINTER FRIENDLY](#)

[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

Top of Page

Fri, June 03, 2016 06:30:01 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 02/18/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 02/18/2015 05:15:37 PM
Date Inspection Closed by Inspector: 02/18/2015 05:05:37 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 CNRT	01 600	418.89	419.14	No	BOKENKAMP	PASLAY	OLD TRANSFER OFF LITTLE ROCK

Track Traversed Information

- NONE -

Comments

Track Defects

No track defect records found

Switches Inspected

Switch Inspected by	Subdivision	Original Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
			Segment/Track	ZTS		Segment/Track	ZTS		
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN	-	418.51	2766 CROS	77 -023	CROSSOVER 023-042	RBM Standard Point
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN	-	418.55	2766 YARD	01 -049	NEW TRANSFER TO LITTLE ROCK	Spring-All Rail Extd length
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 - 105	419.12	2779 INDU	02 -748	SIDING TO KERMAGIE LEAD	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	-	419.14	2767 CNRT	01 -600	OLD TRANSFER OFF LITTLE ROCK	Spring-All Rail Extd length
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	-	419.16	2767 SIDE	01 -105	SIMN TO SIDING	

Switch Defects

No switch defect records found

[PRINT](#)
[PRINTER FRIENDLY](#)
[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

Top of Page

Fri, June 03, 2016 06:30:49 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 02/19/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 02/19/2015 05:33:07 PM
Date Inspection Closed by Inspector: 02/19/2015 05:27:38 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2762 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2762 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	435.93		BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10	Number of Bolts : 1	121E-121.E - Less than 2 bolts	213.9B	02/19/2015	Corr from Trk Mtce Plan	02/20/2015		only one blt in end of rail at corner of interlocker
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10	Number of Bolts : 1	121E-121.E - Less than 2 bolts	213.9B	02/19/2015	Corr from Trk Mtce Plan	02/20/2015		only one bit in end of rail at corner of interlocker
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10	Number of Bolts : 1	121E-121.E - Less than 2 bolts	213.9B	02/19/2015	Corr from Trk Mtce Plan	02/20/2015		only one blt in end of rail at corner of interlocker

Switches Inspected

Switch Inspected by	Subdivision	Original Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
			Segment/Track	ZTS		Segment/Track	ZTS		
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN	-	418.51	2766 CROS	77 -023	CROSSOVER 023-042	RBM Standard Point
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN	-	418.55	2766 YARD	01 -049	NEW TRANSFER TO LITTLE ROCK	Spring-All Rail Extd length

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 06:31:01 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 02/25/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 02/26/2015 07:07:37 AM
Date Inspection Closed by Inspector: 02/25/2015 06:06:06 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	451.19		BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

No track defect records found

Switches Inspected

Switch Inspected by	Subdivision	Original Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
			Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 - 105	418.77	2766 YARD	01 -061	WE 061	Solid Mang. Self Guarding
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 - 105	419.05	2767 YARD	01 -042	WE 042	

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

Top of Page

Fri, June 03, 2016 06:31:14 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 02/27/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 02/27/2015 02:12:35 PM
Date Inspection Closed by Inspector: 02/27/2015 02:03:26 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

Top of Page

Fri, June 03, 2016 06:31:26 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 03/03/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 03/03/2015 01:32:29 PM
Date Inspection Closed by Inspector: 03/03/2015 01:24:26 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg / Trk Type	Zone / Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 CNRT	01 600	418.89	419.14	No	BOKENKAMP	PASLAY	OLD TRANSFER OFF LITTLE ROCK
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	435.93		BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 CNRT 01 600	419.13		127A2-127.A2 - Insufficient fas	Scheduled for Repair	03/03/2015	Corr from Trk Mtce Plan	03/31/2015		Loose spikes allowing too much rail movement in curve.

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

Top of Page

Fri, June 03, 2016 06:31:36 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 03/06/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Harris
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 03/06/2015 03:54:14 PM
Date Inspection Closed by Inspector: 03/06/2015 03:52:19 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Harris from 417.48 to CB419 Wright CB419 to MP.

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#)

[PRINTER FRIENDLY](#)

[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

Top of Page

Fri, June 03, 2016 06:31:47 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 03/10/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 03/10/2015 04:26:44 PM
Date Inspection Closed by Inspector: 03/10/2015 04:22:00 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.10		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	03/10/2015	Corr from Trk Mtce Plan	03/14/2015		Missing multiple frog bolts on UP Pine Bluff main interlockers
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE 01 105	419.10		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	03/10/2015	Corr from Trk Mtce Plan	03/16/2015		missing multiple interlocker bolts UP interlockers Pine Bluff siding

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

Top of Page

Fri, June 03, 2016 06:31:56 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 03/12/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 03/12/2015 11:04:08 PM
Date Inspection Closed by Inspector: 03/12/2015 11:00:40 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg / Trk Type	Zone / Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 061	417.75	418.60	No	BOKENKAMP	PASLAY	#61 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 042	418.60	419.05	No	BOKENKAMP	PASLAY	#42 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 CNRT	01 600	418.89	419.14	No	BOKENKAMP	PASLAY	OLD TRANSFER OFF LITTLE ROCK
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 CROS	77 022	418.60	418.62	No	BOKENKAMP	PASLAY	W CROSSOVER 042-044
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 061	418.60	418.77	No	BOKENKAMP	PASLAY	#61 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 CROS	77 024	418.38	418.43	No	BOKENKAMP	PASLAY	#24 E. CROSSOVER 042-044
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 044	417.81	418.60	No	BOKENKAMP	PASLAY	#44 YARD TRACK #4
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 042	417.84	418.60	No	BOKENKAMP	PASLAY	#42 YARD TRACK #2
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 CROS	77 023	418.47	418.51	No	BOKENKAMP	PASLAY	#23 CROSSOVER MAIN-042
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 CROS	77 022	418.58	418.60	No	BOKENKAMP	PASLAY	#22 W. CROSSOVER 042-044
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 044	418.60	418.98	No	BOKENKAMP	PASLAY	#44 YARD TRACK #4
Track Traversed Information										
- NONE -										
Comments										

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD 01 042	418.80		109B2-109.B2 - Crossties not ef	Scheduled for Repair	03/12/2015	Corr from Trk Mtce Plan	04/08/2015		8 in a row
PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD 01 042	418.76		109B2-109.B2 - Crossties not ef	Scheduled for Repair	03/12/2015	Corr from Trk Mtce Plan	04/08/2015		9 in a row
PINE BLUFF SUB	PINE BLUFF SUB	2767 CNRT 01 600	419.12		127A2-127.A2 - Insufficient fas	Scheduled for Repair	03/12/2015	Corr from Trk Mtce Plan	03/31/2015		Loose spikes allowing lateral rail movement

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 06:32:08 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 03/13/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 03/13/2015 07:12:16 PM
Date Inspection Closed by Inspector: 03/13/2015 07:02:52 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	423.00		BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	419.15	Number of Bolts : 1	121E-121.E - Less than 2 bolts	213.9B	03/13/2015	Installed bolt or bolts	03/13/2015		Repaired by Gang 3106

Switches Inspected

Switch Inspected by	Subdivision	Original Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
			Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN	-	418.51	2766 CROS	77 -023	CROSSOVER 023-042	RBM Standard Point
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN	-	418.55	2766 YARD	01 -049	NEW TRANSFER TO LITTLE ROCK	Spring-All Rail Extd length
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 - 105	419.05	2767 YARD	01 -042	WE 042	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 - 105	419.12	2779 INDU	02 -748	SIDING TO KERMAGIE LEAD	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	-	419.14	2767 CNRT	01 -600	OLD TRANSFER OFF LITTLE ROCK	Spring-All Rail Extd length
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	-	419.16	2767 SIDE	01 -105	SIMN TO SIDING	

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 06:32:20 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 03/17/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 03/17/2015 02:36:02 PM
Date Inspection Closed by Inspector: 03/17/2015 02:30:10 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE 01 105	419.09		127A2-127.A2 - Insufficient fas	Scheduled for Repair	03/17/2015	Corr from Trk Mtce Plan	03/25/2015		Pull and plug to secure fastening.

Switches Inspected

Switch Inspected by	Subdivision	Original Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
			Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 - 105	418.77	2766 YARD	01 -061	WE 061	Solid Mang. Self Guarding

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 06:58:59 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 03/20/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 03/20/2015 05:12:26 PM
Date Inspection Closed by Inspector: 03/20/2015 05:04:34 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/ TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/ TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	479.60	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 06:59:13 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 03/24/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 03/24/2015 07:00:40 PM
Date Inspection Closed by Inspector: 03/24/2015 09:57:57 AM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 CROS	77 022	418.58	418.60	No	BOKENKAMP	PASLAY	#22 W. CROSSOVER 042-044
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 052	418.58	418.58	No	BOKENKAMP	PASLAY	#52 YARD TRACK #12
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 054	418.60	418.60	No	BOKENKAMP	PASLAY	#54 YARD TRACK #14
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 053	418.57	418.57	No	BOKENKAMP	PASLAY	#53 YARD TRACK #13
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 CROS	77 022	418.60	418.62	No	BOKENKAMP	PASLAY	W CROSSOVER 042-044
Track Traversed Information										
- NONE -										
Comments										

Track Defects

No track defect records found

Switches Inspected

Switch Inspected by	Subdivision	Original Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
			Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 044	418.38	2766 CROS	77 -024	CROSSOVER 042-044	RBM Standard Point
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 042	418.43	2766 CROS	77 -024	CROSSOVER 042-044	RBM Standard Point
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 044	418.45	2767 YARD	01 -061	EE 061	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 042	418.47	2766 CROS	77 -023	CROSSOVER 023-#1 MAIN	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 044	418.557	2766 YARD	01 -054	EE 054	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 044	418.571	2766 YARD	01 -053	EE 053	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 042	418.58	2766 CROS	77 -022	CROSSOVER 022	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2766 YARD	01 - 044	418.582	2766 YARD	01 -052	EE 052	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 044	418.62	2767 CROS	77 -022	CROSSOVER 044-042	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 044	418.63	2767 YARD	01 -050	EE 050	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 044	418.64	2766 YARD	01 -049	EE 049	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 044	418.66	2767 YARD	01 -046	EE 046	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 044	418.68	2767 YARD	01 -045	EE 045	
Walked	PINE BLUFF SUB	PINE BLUFF SUB	2767 YARD	01 - 042	418.98	2767 YARD	01 -044	WE 044	

Switch Defects

No switch defect records found

PRINT
PRINTER FRIENDLY

Fri, June 03, 2016 06:59:28 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 03/24/2015	Inspected By: RYAN Wright
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 03/24/2015 07:00:40 PM
Date Inspection Closed by Inspector: 03/24/2015 06:52:21 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE 01 105	419.15		121D2-121.D2 - Less than 1 bolt	Repaired Before Traffic	03/24/2015	Installed bolt or bolts	03/24/2015		
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.15		127A3-127.A3 - Insufficient fas	Repaired Before Traffic	03/24/2015	Installed additional fasteners	03/24/2015		

Switch Defects

No switch defect records found

[PRINT](#)
[PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:00:50 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 03/24/2015	Inspected By: RYAN Wright
Inspection Type: FRA Required	Relief Inspector: Data not entered
Weather: Clear	How Conducted: Data not entered

Date Inspection Uploaded into the Central System: 03/24/2015 07:00:40 PM
Date Inspection Closed by Inspector: 03/24/2015 06:52:21 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE 01 105	419.15		121D2-121.D2 - Less than 1 bolt	Repaired Before Traffic	03/24/2015	Installed bolt or bolts	03/24/2015		
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN -	419.15		127A3-127.A3 - Insufficient fas	Repaired Before Traffic	03/24/2015	Installed additional fasteners	03/24/2015		

Switch Defects

No switch defect records found

[PRINT](#)
[PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:01:02 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 03/26/2015 **Inspected By:** RYAN Wright
Inspection Type: FRA Required **Relief Inspector:** Data not entered
Weather: Clear **How Conducted:** Data not entered

Date Inspection Uploaded into the Central System: 03/26/2015 10:26:14 PM
Date Inspection Closed by Inspector: 03/26/2015 09:55:33 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	No	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments
FRA inspection and looking at select curves.

Track Defects

No track defect records found

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)

Fri, June 03, 2016 07:01:16 AM

**Union Pacific Railroad
FRA Track Inspection & Defect Report**

Inspection Date: 03/31/2015 **Inspected By:** Printice Allen
Inspection Type: FRA Required **Relief Inspector:** Ryan Wright
Weather: Clear **How Conducted:** Hi-Rail

Date Inspection Uploaded into the Central System: 03/31/2015 05:51:20 PM
Date Inspection Closed by Inspector: 03/31/2015 05:43:28 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1

Track Traversed Information

NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIDE	01 105	417.48	418.60	No	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2766 SIMN		417.48	418.60	No	BOKENKAMP	PASLAY	Main 1
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN		418.60	419.64	Yes	BOKENKAMP	PASLAY	AR/TX STATE LINE TO W. TEXARKANA
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2767 SIDE	01 105	418.60	419.16	Yes	BOKENKAMP	PASLAY	SIDING
NORTH LITTLE ROCK	PINE BLUFF SUB	PINE BLUFF SUB	2768 SIMN		419.64	480.25	No	BOKENKAMP	PASLAY	W. TEXARKANA TO MT. PLEASANT

Comments

Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
PINE BLUFF SUB	PINE BLUFF SUB	2767 SIMN	419.10		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	03/31/2015	Corr from Trk Mtce Plan	04/09/2015		Replace missing interlocker bolts

Switch Defects

No switch defect records found

[PRINT](#) [PRINTER FRIENDLY](#)